

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. JIC. TRIBAL CONTRACT #54
2. Name of Operator GOLDEN OIL HOLDING CORPORATION		6. If Indian, Allottee or Tribe Name JICARILLA APACHE
3a. Address 2200 POST OAK BLVD., STE. 720 HOUSTON, TX 77056	3b. Phone No. (include area code) 713/626-1110	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT K; 1850' FSL & 1850' FWL, S3, T22N, R3W		8. Well Name and No. JICARILLA APACHE 54-11
		9. API Well No. 3004320650
		10. Field and Pool, or Exploratory Area LINDRITH GALLUP DAKOTA
		11. County or Parish, State SANDOVAL, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input checked="" type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RIG UP A PLUS UNIT #8; PRESSURE TEST TUBING; CLEAN AND SCRAP CASING; MOVE PACKER TO LOCATE AND IDENTIFY LEAKS IN CASING. PATCH HOLES IN CASING WITH CEMENT; RETURN WELL TO PRODUCTION.



2006 MAR 8 AM 9 30
 RECEIVED
 070 FARMINGTON NM

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed) **DARRYL EMMERT** Title **DIRECTOR OF OPERATIONS**

Signature *Darryl Emmert* Date **03/03/2006**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Original Signed: Stephen Mason	Title	Date MAR 13 2006
Approved by _____ Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOC