

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

SEP 03 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: Atlantic B LS 1B	Facility Type: Natural gas well

Surface Owner: Federal	Mineral Owner: Federal	API No. 3004529970
------------------------	------------------------	--------------------

LOCATION OF RELEASE

Unit Letter I	Section 33	Township 31N	Range 10W	Feet from the 900	North/South Line North	Feet from the 880	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.85395° Longitude -107.88124°

NATURE OF RELEASE



Type of Release: condensate	Volume of Release: 45 bbl	Volume Recovered: none
Source of Release: Separation of ferule connection on intercooler piping.	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: September 1, 2015 at 9:06 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? A phone call to Cory Smith	
By Whom? Steve Moskal of BP	Date and Hour: 9/1/2015 at 11:45 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Tech found stain on ground around condensate tank. Tank previously gauged on 8/6/2015. Tech gauged tank and found a drop of approximately 2.25' since the last gauging event. BP coordinated for the tank to be emptied via spec truck. The tank will be removed and inspected. Repairs will be determined upon analysis of the well production rate.

Describe Area Affected and Cleanup Action Taken.\* Area immediately surrounding the tank has evidence of staining. The tank and staining is contained in an earthen containment berm. A preliminary site assessment will be conducted using a hand auger.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Steve Moskal		Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator		Approval Date: <u>10/14/15</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com		Conditions of Approval:	
Date: September 1, 2015 Phone: 505-326-9497		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

#NCS 1528742 272