RECEIVED

Form 3160-5 (February 2005)

UNITED STATES

FORM APPROVED

DEPARTMENT OF THE INTERIOR JUL 2 2 2015 BUREAU OF LAND MANAGEMENT				OMB No. 1004-0137 Expires: March 31, 2007		
В	REAU OF LAND MA	ANAGEMENT		5. Lease S		
SUNDRY NOTICES AND REPORTS ON WElch Sigton Field Office				NMSF 078362		
					6. If Indian, Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals.				7 If Unit of CA/Agragment Name and/or No.		
SUBMIT IN TRIPLICATE – Other instructions on page 2. 1. Type of Well				7. If Unit of CA/Agreement, Name and/or No. 132829		
				8. Well Name and No.		
Oil Well Gas Well Other OIL CONS. DIV DIST. 3				NE Chaco Com #265H		
2. Name of Operator	nu 97 2015		9. API Well No.			
WPX Energy Production, LLC		JUL 27 2015		30-039-31290		
3a. Address PO Box 640 Aztec, NM 87410		3b. Phone No. (include area code) 505-333-1808		10. Field and Pool or Exploratory Area Chaco Unit NE HZ (oil)		
4. Location of Well (Footage, Sec.,	ion)		11. Country or Parish, State			
SHL: 1366' FSL & 268' FWL SEC 5 T23N R6W BHL: 1565' FNL & 915' FWL SEC 6 T23N R6W				Rio Arriba, NM		
		ES) TO INDICATE NATURI	E OF NOTICE, R	EPORT OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen Deepen	Produ (Start/Resu	uction ume)	Water Shut-Off	
	Alter Casing	Fracture Treat		mation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Reco	mplete	Other COMPLETION	
	Change Plans	Plug and Abandon	The second second	orarily		
Bl			Abandon	- Diamont		
Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration						
thereof. If the proposal is to deep and zones. Attach the Bond under within 30 days following complet	en directionally or recomplete which the work will be perfo ion of the involved operations on completed. Final Abandonn	horizontally, give subsurface learned or provide the Bond No. If the operation results in a ment Notices must be filed only	ocations and meas on file with BLM/ ultiple completion	ured and true BIA. Required or recompleti	vertical depths of all pertinent markers il subsequent reports must be filed on in a new interval, a Form 3160-4 g reclamation, have been completed	
6/4/15- Ran CBL TOC @450'						
6/25/15-6/18/15- MIRU & CO				VEIDA		
6/4/15- Ran CBL TOC @450' 6/25/15-6/18/15- MIRU & CO 6/19/15- CO to 10160' Pressure test 7" casing to 1500' chart for 30 min- GOOD TEST Pressure Tested 7" casing to 4,000 psi, GOOD TEST,,						
Pressure test 7" casing to 1500' chart for 30 min-GOOD TEST						
Pressure Tested 7" casing to 4,000 psi, GOOD TEST,,						
Perf Gallup 1st stage, 9927'-10082' + RSI TOOL @ 10160' with 18, 0.40" holes.						
<u>6/20/15-</u> RDMO				JL 23 2015		
6/20/15-7/6/15- Prepare for frac.			FARMINGTON FIELD OFFICE			
14. I hereby certify that the foregoing i	s arue and correct.		2			
Name (Printed/Typed) Lacey Granillo			te Permit Tec	ch III		
W/ MM						
Signature	THE SPACE E		ate 7/22/15	ICE		
Approved by						
Approved by			Title	4-70-	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NE Chaco Com #265H - page 2

7/7/15-Frac Gallup 1st stage 9927'-10160'- with 221,445# 20/40 PSA Sand
Set flo-thru frac plug @ 9870' MD. Perf 2nd stage 9611'-9812'- with 24, 0.40" holes. Frac Gallup 2nd stage with 219,260#, 20/40 PSA Sand

7/8/15-Set flo-thru frac plug @ 9550' MD. Perf 3rd stage 9308'-9511'- with 24, 0.40" holes. Frac Gallup 3rd stage with 212,440#, 20/40 PSA Sand

Set flo-thru frac plug @ 9250' MD. Perf 4th stage 9010'-9210'- with 24, 0.40" holes. Frac Gallup 4th stage with 209,056#, 20/40 PSA Sand Set flo-thru frac plug @ 8950' MD. Perf 5th stage 8708'-8910'-with 24, 0.40" holes. Frac Gallup 5th stage with 217,240#, 20/40 PSA Sand

7/9/15-Set flo-thru frac plug @ 8670' MD. Perf 6th stage 8407'-8605'- with 24, 0.40" holes. Frac Gallup 6th stage with 217,900#, 20/40 PSA Sand

Set flo-thru frac plug @ 8350' MD. Perf 7th stage 8106'-8307'- with 24, 0.40" holes. Frac Gallup 7th stage with 216,700#, 20/40 PSA Sand Set flo-thru frac plug @ 8070' MD. Perf 8th stage 7790'-8006'- with 24, 0.40" holes. Frac Gallup 8th stage with 201,953#, 20/40 PSA Sand Set flo-thru frac plug @ 7750' MD. Perf 9th stage 7474'-7690'- with 24, 0.40" holes. Frac Gallup 9th stage with 214,580#, 20/40 PSA Sand Set flo-thru frac plug @ 7410' MD. Perf 10th stage 7158'-7371'- with 24, 0.40" holes. Frac Gallup 10th stage with 216,280#, 20/40 PSA Sand Set flo-thru frac plug @ 7090' MD. Perf 11th stage 6842'-7058'- with 24, 0.40" holes. Frac Gallup 11th stage with 219,440#, 20/40 PSA Sand Set flo-thru frac plug @ 6780' MD. Perf 12th stage 6496'-6742'- with 24, 0.40" holes. Frac Gallup 12th stage with 224,440# 20/40 PSA Sand

7/10/15-Set flo-thru frac plug @ 6450' MD. Perf 13th stage 6150'-6396'- with 24, 0.40" holes. Frac Gallup 13th stage with 222,440#, 20/40 PSA Sand Set 4-1/2" CBP @ 6050'.

7/11/15- RDMO Frac & WL.

7/18/15- MIRU. Pressure Tested BOP- OK.

7/19/15- DO CBP @ 6050'. DO flo-thru Frac plug @ 6450', 6780', 7090', 7410', 7750', 8070', 8350', 8670', 8950', 9250', 9550' and 9870' Circ. & CO well to 10157'

7/20/15-Land tbg @ 6000'. As follows, Run production tubing: 37 jts of 2 7/8" L-80 tbng (1144.99) GLV #9 @1164.39' 26 jts of 2 7/8" (802.68) GLV #8 @1971.17 20 jts of 2 7/8" (616.85) GLV #7 @2592.12 16 jts of 2 7/8" (493.21) GLV #6 @3089.43 16 jts of 2 7/8" GLV #5 @3588.69 17 jts of 2 7/8" (523.92) GLV #4 @4116.71 16 jts of 2 7/8" (493.64) GLV #3 @4614.45 16 jts of 2 7/8" (492.25) GLV #2 @5110.80 13 jts of 2 7/8" (399.44) 2.313" XN @5511.44 9 jts of 2 7/8" (276.82) GLV #1 @5792.36 1 jt of 2 7/8" (30.75) 2 7/8" pup jt(4.20) on/off tool, 7" packer set @5836.63 2 7/8" x 2 3/8" xo, 4 jts of 2 3/8" J-55 tbng (129.03) 1.791" XN @5966.91 1 jt of 2 3/8" with mule shoe collar (33.53) EOT @6000.44 Nipple down BOP, Set packer in tension. (10,000# over sttring weight) Land tbng.Packer @5836.63. EOT @6000.44

NOTE: Will file flowback test info on gas delivery sundry.