Submit 1 Copy To Appropriate District	1 - (575) 393-6161   Energy, Minerals and Natural Resources     II - (575) 748-1283   OIL CONSERVATION DIVISION     First St., Artesia, NM 88210   11220 South St. Francis Dr.     III - (505) 346-0   Santa Fe, NM 87505		Form C-103
Office			Revised July 18, 2013 WELL API NO.
<u>District II</u> - (575) 748-1283			30-039-08089 30.045.0917
$\frac{1151}{11} = 500000000000000000000000000000000000$			5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV = (505) 476-3460			STATE FEE   6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Paul Palmer
1. Type of Well: Oil Well Gas Well Other			8. Well Number #1
2. Name of Operator Merrion Oil & Gas Corporation			9. OGRID Number 14634
3. Address of Operator			10. Pool name or Wildcat
610 Reilly Ave, Farmington NM 87401			Flora Vista MV
4. Well Location			and the second
	feet from theSouth lin		
Section 26 To	1 0		NMPM San Juan County
	11. Elevation (Show whether DR, 563		<i>c.</i> )
12. Check A	ppropriate Box to Indicate N	ature of Notice	e, Report or Other Data
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WO     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DI			RILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE   DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	MULTIPLE COMPL	CASING/CEMEI	
OTHER:		OTHER:	
	k). SEE RULE 19.15.7.14 NMAC		nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
Merrion Oil & Gas Corporation plug	ged the above mentioned well on 8/	/14/2015. Please s	see attached plugging procedure.
Approved for plugging of wellbore only. Liability under bond is retained pending Receipt of C-103 (Subsequent Report of Well			-10T 9
			NS. DIV DIST. 3 EP 2 5 2015
Plugging) which may be found @ OCD web			-0.0 5 2015
page und www.em	er forms nrd.state.us/ocd	S	EPBO
DUR MAL			
TAR OTT	$\sim$		
Spud Date: 9/13/1961	Rig Release Da	ite:	
Spines			
I hereby certify that the information a	have is true and complete to the be	est of my knowled	lae and belief
	nove is use and complete to the be	st of my knowled	
SIGNATURE Miller	Mull MTTLE_Regu	latory Compliance	e SpecialistDATE9/23/2015
Type or print namePhilana Thom For State Use Only			
4//	DEPUTY	OIL & GAS	INSPECTOR <sub>DATE</sub> 10/14/15
APPROVED BY: Conditions of Approval (if any):		BISTRICT	3 DATE 10/17/13
constitutions of repproval (il any).			

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

# Merrion O&G Corporation Paul Palmer #1

August 14, 2015 Page 1 of 2

2360' FSL and 830' FWL, Section 26, T-30-N, R-12-W San Juan County, NM Lease Number: FEE API #30-045-09177

Plug and Abandonment Report Notified NMOCD and BLM on 8/10/15

### Plug and Abandonment Summary:

- Plug #1 with 32 sxs (37.76 cf) Class B cement from 3425' to 3003' to cover the Mesaverde top and fish. Tag TOC at 3332'.
- Plug #2 (combined #3) with bi-wire holes at 2990 and CR at 1918' spot 516 sxs (608.88 cf) Class B cement from 2990' to 1192' with 82 sxs under, 55 sxs above and 379 sxs outside to cover the Chacra, Pictured Cliffs and Fruitland Coal.
- Plug #4 with squeeze holes at 530' spot 175 sxs (206.5 cf) Class B cement from 530' to surface. Tag TOC at 25'.
- Plug #5 with 36 sxs Class B cement top off casings and install P&A marker with coordinates N 36° 46' 58.44" / W 108° 04' 24.78".

#### **Plugging Work Details:**

- 8/10/15 Rode rig and equipment to location. Spot in and RU. Check well pressures: tubing 50 PSI, casing 100 PSI and bradenhead 0 PSI. RU relief lines. Perform start well. ND wellhead. NU BOP. Pull tubing hanger. Tubing hung up. Wait on weight indicator. SI well. SDFD.
- 8/11/15 Travel to location. Perform Hot Work Permit. Repair rig. RU and attempt to pull tubing. Could not work free. Pulling to 2700' approximately. PU Sandline tools with tools, sinker bar and jars and no-go. Check with depth meter, estimated at 3400'. LD tools. Attempt to work tubing free, unable. Note: P. Weibe, NMOCD and T. Saylers, BLM approved procedure change. RU A-Plus wireline. RIH with 2-3/8" GR to 3443'. Tight spot at 2600'. POH and LD GR. PU 2-3/8" tubing jet cutter RIH to 3401'. PU tubing 5k over cut tubing at 3401'. LD cutter. Free tubing and LD 31 jnts with 2 subs. Tubing and collars pitted as more LD. Shut down to get 2-3/8" MYT. LD 78 jnts collars on tubing. Look better had flat bottom for elevator. PU 4-1/2" GR to 1919' could not work past. SI well. SDFD.
- 8/12/15 Check well pressures: no tubing, casing 128 PSI and bradenhead 0 PSI. RU relief lines. Round trip 4-1/2" string mill to 1919', attempt to work past unable. Attempt to work past call for power swivel. RU pump attempt to mill fish. Pump total 60 bbls, no circulation. Attempt to work for 1 hr. RD power swivel. RU tubing. PU 2-3/8" SN and tag fish at 3425'. Establish circulation. Spot plug #1 with calculated TOC at 3003'. Note: P. Wiebe, NMOCD approved procedure change. TH with tubing. Establish circulation. SI well. SDFD.

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

# Merrion O&G Corporation Paul Palmer #1

August 14, 2015 Page 2 of 2

### Plugging Work Details (continued):

- 8/13/15 Open up well; no pressures. RU relief lines. Tag TOC at 3332'. Note: P. Wiebe, NMOCD and B. Powell approved procedure change Plug #2. Pressure test casing to 800 PSI, OK. RU A-Plus wireline. RIH with 3-1/8" gun to 1919', could not get past. Wait on bi-wire gun. Perforate 4 bi-wire holes at 2990'. Establish rate of 3.5 bpm at 750 PSI. PU 4-1/2" wireline CR and set at 1918'. TIH with tubing and stinger, sting into CR. Establish circulation, found leaking in 9-5/8" casing through ground. Spot plug #2 combined #3 with calculated TOC at 1192'. RU A-Plus wireline. Perforate 3 HSC squeeze holes at 530'. Establish circulation. Found leak in 9-5/8" casing. Wait on water truck to vacuum cellar while pumping clean returns. Pump total 200 bbls of water. Circulate well. Note: B. Powell, NMOCD approved procedure change. Spot plug #3. SI well and WOC. SDFD.
- 8/14/15 Open up well; no pressures. RU relief lines. Tag TOC at 25'. Chip out cement behind blind rams. ND BOP. Dig out wellhead. Perform Hot Work Permit. Cut off wellhead. Found cement down 4' in 9-5/8" x 4-1/2" casing. Spot plug #5 top off casings and install P&A marker with coordinates N 36° 46' 58.44" / W 108° 04' 24.78". RD and MOL.

Shacie Murray, Merrion O&G representative was on location. Paul Weibe, NMOCD representative was on location.