Office State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II – (575) 748-1283 811 S. First St. Artesia, NM 88210 OIL CONSERVATION DIVISION	30-045-28674
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178  1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Pio Brazos Pd. Aztec NM 87410	STATE FEE
District IV – (505) 476-3460 Santa Fe, NIVI 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	I
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7 Laga Nama or Unit Agramant Nama
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name B Montoya 25
PROPOSALS.)	all of the control of
1. Type of Well: Oil Well Gas Well Other	8. Well Number 2
2. Name of Operator	9. OGRID Number 241333
Chevron Midcontinent L.P.	
3. Address of Operator	10. Pool name or Wildcat
332 Road 3100 Aztec NM 87410	Basin Fruitland Coal
Section and Appropriate Report to the Contract of Cont	
4. Well Location	
Unit Letter K : 1625 feet from the S line and 2210	feet from theWline
Section 25 Township 32N Range 13W NMPM	County San Juan
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
5881	
The state of the s	A THE STREET,
12 Cl. 1- A	David an Other Date
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOF	
TEMPORARILY ABANDON	ILLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
proposed completion or recompletion.	inpretional remain works and an or
proposed completion of recompletion.	
Chevron Midcontinent L.P. respectfully submits this subsequent sundry following the repa	ir of a hole in tubing repair. Please see
attached procedure and well bore diagram.	if of a note in tubing repair. Thease see
attached procedure and wen bore diagram.	
06/20/1002	
Spud Date: 06/29/1992 Rig Release Date:	
Spud Date: 06/29/1992 Rig Release Date:	
Spud Date: 06/29/1992 Rig Release Date:	
Spud Date: Rig Release Date:	ve and halief
Spud Date:  06/29/1992  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge.	ge and belief.
Spud Date: Rig Release Date:	ge and belief.
I hereby certify that the information above is true and complete to the best of my knowledge.	
Spud Date: Rig Release Date:	ge and belief
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE APPLE Permitting Specialist_	DATE10/30/15
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	DATE10/30/15
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	DATE10/30/15 n PHONE: _505-333-1941
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	DATE10/30/15 n_ PHONE: _505-333-1941
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	DATE10/30/15 n PHONE: _505-333-1941

RV

10/20/2015

Set BPV. ND 7 1/16" top flange. NU 7 1/16" BOPE, change pipe rams to 2 7/8".

Test BOPE pipe rams & the break @ 260 low & 2200#'s high, good test.

Pull & LD tbg hanger. POOH standing back 2 7/8" prod tbg, removing 400', 1/4" cap tube stinger.

RIH w/ prod tbg, PU additional Jt 2 7/8", tag 2' below EOT @ 2168'. SDFN.

10/21/2015

RU Tuboscope scanning unit. POOH LD 67 total Jt's 2 7/8" bare prod tbg, PSN & mule shoe jt. Found a rod cut hole in landing/top Jt, 4 Jt's BB, 2 GB & 60 YB. RD Tuboscope unit. PU & RIH w/ 4 3/4" bit, bit sub & 65 Jt's prod tbg to 2150'. Install rotating rubber, PU power swivel. RU High Tech air/foam unit break circ w/ same.

Clean out fr/ 2168 to PBTD @ 2180', mostly coal fines, slight scale in returns. Circ & pump sweeps tilll returns clean.

ND swivel, pull above perfs to 2044'. SDFN.

10/22/2015

Short trip fr/ 2044' to PBTD, OK, no fill up overnight.

POOH to 1900'. PU Baker 5 1/2" RBP. RIH & set same @ 60'. Fill & test csg @ 500#'s, good test. Release fr/ RBP, POOH.

ND 7 1/16" 3K BOPE. NU 7 1/16" 3K X 7 1/16" 3K Tbg Rotator Head. NU 7 1/16" BOPE. Test BOPE connections, blind rams & csg @ 500#'s, good test.

RIH, release RBP.POOH w/ RBP, POOH & LD 4 3/4" bit & bit-sub.

PU & RIH w/ 2 7/8" mud anchor assem & 2 7/8" boronized/DYB J-55 bare prod tbg assem to 2154'.

NU 7 1/16" tbg rotation hanger & land tbg on same, EOT @ 2164"', PSN @ 2141"'. Engage hold down pins.

ND 7 1/16" BOPE. NU 7 1/16" 3K X 2 7/8" top flang, radiigon & flow cross. Install shut in valve.

RU to run rod string. RIH w/ rod pump & rod string as per design. PU polish rod. Seat pump, fill & test tbg @ 500#'s, good. Verify pump operation, good.

Land polish rod on clamp, PU & install horses head & bridle.

10/23/2015

RDMO.



## **Wellbore Schematic**

