# RECEIVED

	UNITED STATES DEPARTMENT OF THE INTERIOR		AUG 0	0	DRM APPROVED MB No. 1004-0137
BUREAU OF LAND MANAGEMENT			Expires: March 31, 2007		
SUNDRY	NOTICES AN	ID REPORTS ON WE		iold Cast Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS <sup>Bureau of Land</sup> Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well				NMNM 133482X	
Oil Well Gas Well Other				8. Well Name and No. NW Lybrook UT # 132H	
2. Name of Operator				9. API Well No.	
WPX Energy Production, LLC   3a. Address   3b. Phone No. (include area code)				30-045-35625 10. Field and Pool or Exploratory Area	
PO Box 640 Aztec, NM 87410 505-333-1808			and could	Lybrook Unit NW HZ(oil)	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL: 1910' FNL & 1569' FWL, SEC 36, T24N, R8W BHL: 2146' FNL & 230' FWL SEC 35 T24N R8W				11. Country or Parish, State San Juan, NM	
12. CHE	CK THE APPROPR	IATE BOX(ES) TO INDICAT	E NATURE OF NOTIC	E, REPORT OR OT	HER DATA
TYPE OF SUBMISSION TYPE OF ACTION					
	Acidize	Deepen	Production (Sta	art/Resume) Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	Г. Г.	Well Integrity
	Casing Repai		Recomplete	Other COMPLETION	
Subsequent Report	Change Plans		Temporarily A	Abandon	
Final Abandonment	Convert to	Plug Back	POOL NAME		
7/13/15- MIRU HWS #6 RU Antelope & Pressure tester Recorded on chart. RD HWS #6		n completed and the operator h Opsi, held for 30 minutes – test			
	anice & Basin Wireli	<b>D</b> A			
7/16/15- MIRU Baker Pump service & Basin Wireline. CO to 11091'.					AUG 07 2015
Perf Gallup 1 <sup>st</sup> stage, 10867'-11086' + RSI TOOL @11091' with 18, 0.40" holes.					
7/17/15-7/23/15- prepare for	frac				and the second second
14. I hereby certify that the fore Name (Printed/Typed) Marie E. Jaramillo	going is true and corre	ct.	e Permit Tech III		the state of the second
Signature	1 h Jusiu	Dat	. 8410	5	
10/0.0	THIS S	PACE FOR FEDERAL	OR STATE OFF	ICE USE	
Approved by	U		Title	Da	ate
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					17.952 30.2
Title 18 U.S.C. Section 1001 and United States any false, fictitious	d Title 43 U.S.C. Sect s or fraudulent statem	ion 1212, make it a crime for any ents or representations as to any	person knowingly and wil matter within its jurisdiction	lfully to make to any	CEPTED POR RECORD
(Instructions on page 2)				AUG 0 5 2015	
	Copyright 2006 F		IOCD A d.com). For individual or s	single-branch use 🎮	RMINGTON FIELD OFFICE. Y: William Tamberoy

2

## NW Lybrook UT #132H - page 2

## 7/24/15-Frac Gallup 1<sup>st</sup> stage 10867'-11091'- with 218,120# 20/40 PSA Sand

Set flo-thru frac plug @ 10840' MD. Perf 2<sup>nd</sup> stage 10621'-10807'- with 24, 0.40" holes. Frac Gallup 2<sup>nd</sup> stage with 219,100#, 20/40 PSA Sand Set flo-thru frac plug @ 10586' MD. Perf 3<sup>rd</sup> stage 10375'-10561'- with 24, 0.40" holes. Frac Gallup 3<sup>rd</sup> stage with 213,200#, 20/40 PSA Sand Set flo-thru frac plug @ 10350' MD. Perf 4<sup>th</sup> stage 10129'-10315'- with 24, 0.40" holes. Frac Gallup 4<sup>th</sup> stage with 216,960#, 20/40 PSA Sand

### 7/25/15

Set flo-thru frac plug @ 10070' MD. Perf 5<sup>th</sup> stage 9843'-10029'-with 24, 0.40" holes. Frac Gallup 5<sup>th</sup> stage with 217,760#, 20/40 PSA Sand Set flo-thru frac plug @ 9820' MD. Perf 6<sup>th</sup> stage 9597'-9783'- with 24, 0.40" holes. Frac Gallup 6<sup>th</sup> stage with 219,440#, 20/40 PSA Sand Set flo-thru frac plug @ 9570' MD. Perf 7<sup>th</sup> stage 9351'-9537'- with 24, 0.40" holes. Frac Gallup 7<sup>th</sup> stage with 217,800#, 20/40 PSA Sand Set flo-thru frac plug @ 9320' MD. Perf 8<sup>th</sup> stage 9105'-9291'- with 24, 0.40" holes. Frac Gallup 8<sup>th</sup> stage with 217,800#, 20/40 PSA Sand Set flo-thru frac plug @ 9073' MD. Perf 8<sup>th</sup> stage 8862'-9045'- with 24, 0.40" holes. Frac Gallup 9<sup>th</sup> stage with 216,920#, 20/40 PSA Sand Set flo-thru frac plug @ 8830' MD. Perf 9<sup>th</sup> stage 8613'-8799'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 219,800#, 20/40 PSA Sand Set flo-thru frac plug @ 8830' MD. Perf 10<sup>th</sup> stage 8613'-8799'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 219,800#, 20/40 PSA Sand Set flo-thru frac plug @ 8830' MD. Perf 11<sup>th</sup> stage 8613'-8799'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 219,800#, 20/40 PSA Sand Set flo-thru frac plug @ 8580' MD. Perf 11<sup>th</sup> stage 8367'-8553'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 219,800#, 20/40 PSA Sand Set flo-thru frac plug @ 8580' MD. Perf 11<sup>th</sup> stage 8367'-8553'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 219,800#, 20/40 PSA Sand Set flo-thru frac plug @ 8336' MD. Perf 12<sup>th</sup> stage 8121'-8307'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 214,340# 20/40 PSA Sand Set flo-thru frac plug @ 8336' MD. Perf 12<sup>th</sup> stage 8121'-8307'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 214,340# 20/40 PSA Sand Set flo-thru frac plug @ 8336' MD. Perf 12<sup>th</sup> stage 8121'-8307'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 214,340# 20/40 PSA Sand Set flo-thru frac plug @ 8336' MD. Perf 12<sup>th</sup> stage 8121'-8307'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 214,340# 20/40 PSA Sand Set flo-thru frac plug @ 8336' MD. Perf 12<sup>th</sup> stage 8121'

#### 7/26/15

Set flo-thru frac plug @ 8090' MD. Perf 13<sup>th</sup> stage 7875'-8061'- with 24, 0.40" holes. Frac Gallup 13<sup>th</sup> stage with 219,240#, 20/40 PSA Sand Set flo-thru frac plug @ 7840' MD. Perf 14<sup>th</sup> stage 7629'-7815'- with 24, 0.40" holes. Frac Gallup 14<sup>th</sup> stage with 217,240#, 20/40 PSA Sand Set flo-thru frac plug @ 7590' MD. Perf 15<sup>th</sup> stage 7343'-7529'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 218,480#, 20/40 PSA Sand Set flo-thru frac plug @ 7320' MD. Perf 16<sup>th</sup> stage 7100'-7283'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 215,100#, 20/40 PSA Sand Set flo-thru frac plug @ 7070' MD. Perf 16<sup>th</sup> stage 6851'-7037'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 214,520#, 20/40 PSA Sand Set flo-thru frac plug @ 6820' MD. Perf 17<sup>th</sup> stage 6605'-6791'- with 24, 0.40" holes. Frac Gallup 18<sup>th</sup> stage with 219,160#, 20/40 PSA Sand Set flo-thru frac plug @ 6820' MD. Perf 18<sup>th</sup> stage 6605'-6791'- with 24, 0.40" holes. Frac Gallup 18<sup>th</sup> stage with 219,160#, 20/40 PSA Sand Set flo-thru frac plug @ 6820' MD. Perf 19<sup>th</sup> stage 6359'-6545'- with 24, 0.40" holes. Frac Gallup 18<sup>th</sup> stage with 219,160#, 20/40 PSA Sand Set flo-thru frac plug @ 6575' MD. Perf 19<sup>th</sup> stage 6359'-6545'- with 24, 0.40" holes. Frac Gallup 19<sup>th</sup> stage with 217,220#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 19<sup>th</sup> stage 6359'-6545'- with 24, 0.40" holes. Frac Gallup 19<sup>th</sup> stage with 217,220#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 20<sup>th</sup> stage 6113'-6299'- with 24, 0.40" holes. Frac Gallup 20<sup>th</sup> stage with 217,220#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 20<sup>th</sup> stage 6113'-6299'- with 24, 0.40" holes. Frac Gallup 20<sup>th</sup> stage with 218,020#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 20<sup>th</sup> stage 6113'-6299'- with 24, 0.40" holes. Frac Gallup 20<sup>th</sup> stage with 218,020#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 20<sup>th</sup> stage 6113'-6299'- with 24, 0.40" holes. Frac Gallup 20<sup>th</sup> stage with 218,020#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 20<sup>t</sup>

Set 4-1/2" CBP @@ 5000'.

7/27/15- RDMO Frac & WL.

7/28/15- MIRU HWS #10. TEST BOP to 1500psi-Test OK. DO CBP @ 5000'.

7/29/15-DO flo- thru Frac plug @ 6330', 6575', 6820', 7070', 7320', 7590', 7840', 8090', 8336', 8580', 8830', 9073', 9320', 9570' & 9820'.

7/30/15- DO flo- thru Frac plug @ 10070', 10350', 10586', & 10840'.

C/O well to @ 11086'. Pulled and landed tieback string.

#### 7/31/15

Land tbg @ 6005', as follows: Run production tbg: 35jts of 2 7/8" J-55tbg GLV #9 @ 1155.95', 24jts of 2 7/8" GLV #8 @ 1942.89', 19jts of 2 7/8" GLV #7 @ 2566.72', 15jts of 2 7/8 GLV #6 @ 3059.82', 16jts of 2 7/8" GLV #5 @ 3586.30', 16jts of 2 7/8" GLV #4 @ 4113.15', 15jts of 2 7/8" GLV #3 @ 4605.90', 16jts of 2 7/8" GLV #2 @ 5132.27', 13jts of 2 7/8 2.313" XN @ 5560.74', 8jts of 2 7/8" GLV #1 @ 5823.17', 1jt of 2 7/8", 2 7/8" pup jt, on/off tool w/ 2.25" profile, 7" ASI-X Packer set @ 5865.96', 2 7/8" X 2 3/8" XO, 3jts of 2 3/8" tail pipe, 1.791" XN @ 5970.54', 1jt of 2 3/8 w/ MS collar. EOT @ 6005'. RD. ND BOP. Set packer in tension 12,000# over, **Packer set @ 5866'**. Landed tbg, NU well head. Shut in well.