

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company WPX Energy Production	Contact Deborah Watson	
Address PO Box 640 Aztec, NM 87410	Telephone No. 505-386-9693	
Facility Name Rosa Unit 208Y	Facility Type Well Site	
Surface Owner Federal/BLM	Mineral Owner Federal/BLM	API No. 30-045-33854

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	16	31N	06W	605	North	440	East	San Juan

Latitude 36.90528 Longitude -107.46056

**NATURE OF RELEASE**

Type of Release Hydraulic fluid resulted in small fire	Volume of Release 15 gallons	Volume Recovered 10 gallons
Source of Release Hydraulic hose broke and oil ignited on exhaust manifold.	Date and Hour of Occurrence 10/14/15, 14:00	Date and Hour of Discovery 10/14/15, 14:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith (NMOCD) Mike Flannigan (BLM)	
By Whom? Deborah Watson	Date and Hour 10/14/15; 15:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**OIL CONS. DIV DIST. 3**

If a Watercourse was Impacted, Describe Fully.\*  
N/A

**OCT 27 2015**

**Describe Cause of Problem and Remedial Action Taken.\***

While cleaning out the air mist on Rosa Unit 208Y, hydraulic hose broke and oil ignited on exhaust manifold causing a fire in engine compartment of air unit. Crew and air jammer acquired fire extinguishers and had fire out in 2.5 minutes. No injuries.

**Describe Area Affected and Cleanup Action Taken.\***

- 15 gallons total oil released, 10 gallons captured in buckets and blotter material, 5 gallons on ground.
- Impacted soils were cleaned up and removed for disposal.
- Damaged engine was removed from the location.
- No fluids migrated off the location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Deborah Watson</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Deborah Watson	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 12/28/2015	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/25/2015	Phone: 505-386-9693	

\* Attach Additional Sheets If Necessary

NCS1528754138