Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Other

Workover Operations

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

NOG98111310

5. Lease Serial No.

abandoned w	6. If Indian, Allottee EASTERN NA			
SUBMIT IN TR	7. If Unit or CA/Ag NMNM102964	reement, Name and/or No.		
Type of Well     Oil Well	8. Well Name and N SHAREN COM			
Name of Operator     COLEMAN OIL & GAS INCO	ORPORATED Contact:	MICHAEL T HANSON	9. API Well No. 30-045-29925	-00-S1
3a. Address FARMINGTON, NM 87499		3b. Phone No. (include area co Ph: 505.327.0356	de) 10. Field and Pool, of BASIN FRUIT	
Location of Well (Footage, Sec.,  Sec 13 T26N R12W SESW		on)	11. County or Parish SAN JUAN CO	
12. CHECK API	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION		TYPE	OF ACTION	
☑ Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Deepen ☐ Fracture Treat	☐ Production (Start/Resume) ☐ Reclamation	☐ Water Shut-Off ☐ Well Integrity

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

☐ Plug Back

■ New Construction

□ Plug and Abandon

Coleman Oil & Gas, Inc. proposes to pressure test casing and return to production.

☐ Casing Repair

□ Change Plans

☐ Convert to Injection

See the attached procedure.

☐ Subsequent Report

☐ Final Abandonment Notice

OIL CONS. DIV DIST. 3

□ Recomplete

■ Water Disposal

☐ Temporarily Abandon

Notify NMOCD 24 hrs prior to beginning operations

JAN 04 2016

14. I hereby certify that th	ne foregoing is true and correct.  Electronic Submission #327443 verifie  For COLEMAN OIL & GAS INCORF  Committed to AFMSS for processing by ABDEL	ORATE	D, sent to the Farmington	56SE)	
Name (Printed/Typed)	MICHAEL T HANSON	Title	ENGINEER		
Signature	(Electronic Submission)	Date	12/30/2015		
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE		
_Approved_By_ABDELG	SADIR_ELMADANL	TitleF	ETROLEUM ENGINEER	Date 12/30/	/2015
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Farmington		
Title 18 U.S.C. Section 100 States any false, fictitious	1 and Title 43 U.S.C. Section 1212, make it a crime for any pe or fraudulent statements or representations as to any matter w	rson kno ithin its j	wingly and willfully to make to any depurisdiction.	artment or agency of the United	

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



# Coleman Oil & Gas, Inc.

## Workover Procedure Pressure Test Casing

Wednesday, October 07, 2015

Well: SL Location: Sharen Com #1

1035' FSL & 1665' FWL (SESW) Sec 13, T26N, R12W, NMPM

San Juan County, New Mexico

Field:

Basin Fruitland Coal

Elevation:

6045' RKB 6040' GL

Lease:

NO-G-9811-1310

API#:

30-045-29925

Fruitland Coal Perforations: 1212-1227

Original PBTD at 1325 FT KB


Procedure:

(Note: This procedure will be adjusted on site based upon actual conditions)

- 1. Review and Comply with Regulatory Requirements.
- 2. MIRU Well Service Rig and Equipment.
- POOH with Rods & Pump. 3.
- Nipple up BOP equipment, function test BOP. 4.
- Tag up and POOH, Tally Tubing. 5.
- Cement Bond Log shows very good cement from TD to base of surface pipe.
- RIH with retrievable Bridge Plug and set at + 1120 FT KB. Place two sacks of 7. sand on top of Retrievable Bridge Plug.
- Load and pressure test casing with water. If casing does not pressure test 8. proceed to step 9. If Casing pressure tests, proceed to step 14.
- 9. Make sure well is dead and remove BOP and Production Tubing Well Head. Rig up and pull slips on casing. Rotate production casing to check for thread leak.
- Install tubing wellhead and BOP equipment. 10.
- 11. Load and pressure test casing with water, chart pressure test per NMOCD requirements. NMOCD may want to witness.
- If casing does not pressure tests locate hole and try to establish circulation. 12.
- Squeeze hole with cement. Procedure to be approved by regulatory agencies. 13.
- If casing pressure tests return well to production. Production test for one to three months to determine economic viability.

Note: Workover recommendation due to Braden Head Test failure and NMOCD requirement. If at any time it is determined that there is a hole in casing and it is determined that economics do not support workover, procedure may alter from workover to P&A with Regulatory approval.

	OHAHEN O	OM 17 1							Hy S				-				-54 U		-				
FIELD:	BASIN								Ampiltude VDL VariableDensity (V (US)						=								
COUNTY:	SAN JUAN	STATE:	NHEW	MEXICO					Am Variab										=				
Fret.	Schlumberger CEMENT BOND LOG						E-2::::		MIII 200														
SL 4 1565 N COM # NAN OIL 8	1036' FSL & 1665' FWL		Elev.: KB. G.L. D.F.	604° ft 6041 ft				100	2)														
any.	Drilling Measured From: KB 0.0 ft. above Pe		ft e Perm. Datum	454	MAIN PASS		CBL Amplitude (SA2)	CBL Amplitude (SA2)				H					X	THE PARTY.					
Company	API Serial No.	SECTION 13	TOWNSHIP 26 N	RANGE 12 W	l a		> 80% Good Bond	LAm	LAM	#	$\dagger \dagger$	H		H	$\parallel$	+	H		T.		Н	+	-
op Log Interval  Lasing Fluid Type  Saintly  Density	128 ft WATER					T" 18"	r -16	T.:	Ţ					_	100								
lensity luid Level BIT/CASING/TUBI iii Size rom	NG STHING 6 250 in				- -	150	200	4000	I									H	F	П		Ħ	-
asing/Tubing Size	4,500 in 10.5 lbm u-55				ocator (CCL)	ay (GR)	6 2 (TT2)	TENS)	collars												<u> </u>		
rom o laximum Recordec	0 ft 1370 ft				Casing Collar !	Gamma Ray (GR) (GAPI)	Transit Time 2 (TT2)	Tension (TENS) (LBF)	Casing Collars		1	1			-W		Λ		人	\rangle \rangl	W	1	
nit Number ecorded By /itnessed By	Location 151  BEN SA  MIKE H	FARMINGTON NDERS			Casi		400				Щ					V		<b>M W</b>				$\parallel$	1



## **BLM CONDITION OF APPROVAL**

### CASING REPAIR, WORKOVER AND RECOMPLETION OPERATIONS:

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs. If a CBL or other logs are run, provide this office with a copy.
- 2. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minute test period. Provide test chart with your subsequent report of operations
- 3. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 4. Contact this office at (505) 564-7750 prior to conducting any cementing operations

#### SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.