

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 05 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company WPX Energy Production	Contact Deborah Watson
Address PO Box 640	Telephone No. 505-333-1880/505-386-9693
Facility Name Well Pad 27 Rosa Unit # 641H	Facility Type Well Site
Surface Owner Federal/BLM	Mineral Owner Federal/BLM
API No. 30-039-31314	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	19	31N	05W	966	North	526	West	Rio Arriba

Latitude N36.889676 Longitude W107.405979

NATURE OF RELEASE

Type of Release: Natural gas/produced water	Volume of Release ~11 mmcf natural gas /1.5 bbls produced water	Volume Recovered 0 bbls
Source of Release: Equipment failure- ball valve	Date and Hour of Occurrence 1/21/16 3:45AM	Date and Hour of Discovery 1/21/16 7:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Katherina Diemer (BLM-FFO) -1/22/16 8:50 hrs Cory Smith (NMOCD) -1/22/16 8:50 hrs <i>Agencies contacted as soon as volume of release determined.</i>	
By Whom? Deborah Watson	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

A 2-inch ball valve failed and leaked at 641H inlet piping at separator. Production unit was isolated. Piping and ball valve were replaced.

Describe Area Affected and Cleanup Action Taken.*

- Release stopped. Failed equipment replaced.
- Fluids remained on skid/small amount mixed with snow on ground.
- No further action recommended.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 02/05/2016	Expiration Date:
E-mail Address: deborah.watson@wpenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/4/16 Phone: 505-333-1800/505-386-9693		

* Attach Additional Sheets If Necessary

NUP 1602249879

14