| | Submit 1 Copy To Appropriate District | State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION | | Form C-103 | |
|----|--|--|-----------------------------------|--|--|
| | Office District I - (575) 393-6161 | | | Revised July 18, 2013 | |
| | 1625 N. French Dr., Hobbs, NM 88240 | | | WELL API NO. | |
| | <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 | | | 30-045-08972 | |
| | District III – (505) 334-6178 | 1220 South | St. Francis Dr. | 5. Indicate Type of Lease STATE ☐ FEE ☒ | |
| | 1000 Rio Brazos Rd., Aztec, NM 87410 | istrict IV – (505) 476-3460 Santa Fe, NM 8/303 20 S. St. Francis Dr., Santa Fe, NM | | 6. State Oil & Gas Lease No. | |
| | 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | | o. State on & Gas Lease No. | |
| | SUNDRY NOT | TICES AND REPORTS ON | | 7. Lease Name or Unit Agreement Name | |
| | (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | Elliott Gas Com N | |
| | 1. Type of Well: Oil Well Gas Well Other | | | 8. Well Number | |
| | 2. Name of Operator | | | 9. OGRID Number | |
| | BP America Production Company | | | 000778 | |
| | 3. Address of Operator | | | 10. Pool name or Wildcat | |
| | 501 Westlake Park Blvd., Three Eldridge Place, 12.181A Houston, TX 77079 | | | Basin Dakota, Blanco-Mesaverde | |
| | 4. Well Location | | | | |
| | Unit Letter I: | feet from the | South line and 870 | feet from the <u>East</u> line | |
| | Section 33 | Township 30N | Range 09W N | IMPM County San Juan | |
| | 11. Elevation (Show whether DR, RKB, RT, GR, etc.) | | | | |
| 0 | | | 5706' | | |
| KR | 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | | | |
| | | | | | |
| | NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | | | |
| | PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A | | | | |
| | TEMPORARILY ABANDON DULL OR ALTER CASING | A CONTRACTOR OF THE PROPERTY O | | | |
| | PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE | | | 1 30B | |
| | CLOSED-LOOP SYSTEM | | | | |
| | OTHER: Plug Back Dake | | OTHER: | | |
| | 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | | | | |
| | DD America Production Compan | v requests to abandon the | Dalrata formation in the s | ubject well with a CIPP and continue to | |
| | produce solely from the Mesavere | | Notify NMOCD 2 | ubject well with a CIBP, and continue to 4 hrs | |
| | produce solely from the Mesaver | de formation. | prior to beginn operations | | |
| | Please see the attached procedure | including wellbore diagr | ams. | The second secon | |
| | # See cont information | on diagram not | included in proce | dure. JAN 15 2016 | |
| | 0.154 | n: I | N. I D. I | | |
| | Spud Date: 03/01/19 | 765 Rig I | Release Date: | | |
| | The Contract of the Contract o | | | | |
| | I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | |
| | 1 motory certain, and the information doors is the unit complete to the best of my knowledge and benefit | | | | |
| | SIGNATURE Oya CO | TITL | E Regulatory Analyst | DATE1/12/2016 | |
| | Type or print name Toya Col | vin E-mail addre | ess: Toya.Colvin@bp.co | m PHONE: 281-366-7148 | |
| | For State Use Only | _ | | | |
| | 1/ | /// | · · · · · · · · · · · · · · · · · | INSPECTOR | |
| | | | | #3 DATE | |
| | Conditions of Approval (if any): | A | | | |

Elliott GC N 001M-MV/DK

API # 30-045-08972-00 Location: Unit I - Sec 33 - T30N - R09W San Juan County, New Mexico


Reason/Background for Job

The proposed work is to temporarily abandon the Dakota formation in order to more effectively produce the Mesaverde formation with the EOT placed at the Mesaverde. At a future date, the Dakota formation may be PxA'd or returned to production following evaluation of Mesaverde production.

Basic job procedure

- 1. Pull tubing
- 2. RIH to set CIBP @ +/- 6,650'
- 3. Land tubing @ +/- 4,650'
- 4. Return well to production

Current WBD



Proposed WBD

