Submit 3 Copies To Appropriate District Office	Energy, Minerals and Natural Resources os, NM 88240 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-103
District I			Jun 19, 2008 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II			30-045-05846
1301 W. Grand Ave., Artesia, NM 88210 District III			5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV			6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	Francis Dr., Santa Fe, NM		B-10894-15
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Greer
1. Type of Well: Oil Well Gas Well Other P&A			8. Well Number 2
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289			10. Pool name or Wildcat Ballard Pictured Cliffs
4. Well Location			
Unit Letter K : 185	0 feet from the South	_line and18	50 feet from the <u>West</u> line
Section 16 Township 26N Range 9W NMPM San Juan County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
6349' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
OTHER:		OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 			
1/15/16 Contacted Brandon Powell/OCD re Plug 2. Requested permission to perf @ 1255' instead of 1289' as proposed. Rec'vd verbal approval to proceed.			
The subject well was P&A'd on 1/19/16 per the notification above and the attached report.			
The subject well was P&A'd on 1/19/16 per the notification above and the attached report.			
FEB 1 0 2016			
Spud Date: Rig Released Date:			
	the state of the s	1 6 1 1 1	11.11.0
I hereby certify that the information	above is true and complete to the be	st of my knowledg	ge and bener.
SIGNATURE Jallie	Busse TITLE_	Staff Regulatory	Technician DATE <u>2/10/16</u>
Type or print name Dollie L. Bus	se E-mail address: dollie.1.1	busse@conocophi	illips.com PHONE: 505-324-6104
For State Use Only			
1/1			SAS INSPECTOR
APPROVED BY: DS Con	TITLE	DISTRIC	DATE 2/24/14
Conditions of Approval (if any):	Pr		
		nly	
Approved for plugging of wellbore only. Liability under bond is retained pending			
PNR ONLY Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web			
T lugging) which may be round C			
0	page under forms		

a de

www.emnrd.state.us/ocd

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources Greer #2

January 19, 2016 Page 1 of 1

1850' FSL and 1850' FWL, Section 16, T-26-N, R-9-W San Juan County, NM Lease Number: B-10894-15 API #30-045-05846

Plug and Abandonment Report Notified NMOCD and BLM on 1/14/16

Plug and Abandonment Summary:

- Plug #1 with CR at 1888' spot 12 sxs (14.16 cf) Class B cement from 1888' to 1453' to cover the Pictured Cliffs and Fruitland tops. Tag TOC at 1500'.
- Plug #2 with bi-wire holes at 1255' and squeeze holes at 1205' spot 90 sxs (106.2 cf) Class B cement from 1255' to 1024' with 83 sxs in CR, 2 sxs below and 5 sxs above CR to cover the Kirtland and Ojo Alamo tops.
- Plug #3 with squeeze holes at 172' mix 70 sxs (82.6 cf) Class B cement down 2-7/8" from 172' to surface to cover the surface casing shoe and circulate good cement to surface.
- Plug #4 with 20 sxs (56.64 cf) Class B cement top off casings and install P&A marker.

Plugging Work Details:

- 1/14/16 Rode rig and equipment to location. Spot in and RU. SDFD.
- 1/15/16 Bump test H2S equipment. Check well pressures: no tubing, 2-7/8" casing 40 PSI, 5-1/2" casing and bradenhead 0 PSI. RU relief lines. Blow well down. RU A-Plus companion flange. NU kill spool and BOP. RU A-Plus wireline. RIH with 2-7/8" GR to 1900'. RIH with 2-7/8" CIBP and set at 1888'. PU and tally 58 jnts, 10' sub of 1-1/4" tubing IJ to 1888'. Attempt to pressure test casing to 800 PSI, bled down to 700 PSI in 10 minutes. TOH with tubing. RU A-Plus wireline. Ran CBL from 1888' to surface, found TOC at 22'. Establish circulation. Spot plug #1 with calculated TOC at 1453'. PUH with tubing. SI well. SDFD.
- 1/18/16 Bump test H2S equipment. Open up well; no pressures. Function test BOP. TIH and tag TOC at 1500'. Pressure test casing to 800 PSI, OK. RU A-Plus wireline. Perforate bi-wire holes at 1255'. Note: approved by B. Powell. NMOCD. Establish rate of 1 bpm at 1000 PSI. RIH with 2-7/8" CR and set at 1205'. Establish circulation and rate of 1 bpm at 1000 PSI. Spot plug #2 with calculated TOC at 1024'. RU A-Plus wireline. Perforate 4 squeeze holes at 172'. Establish circulation out bradenhead. ND BOP and kill spool. RU wellhead. Spot plug #3 with TOC at surface. SI well. SDFD.
- 1/19/16 Bump test H2S equipment. Open up well; no pressures. Tag TOC at surface. Dig out wellhead. RU A-Plus cut off. Cut off wellhead. Found cement at surface in 2-7/8" casing and down 14' in 5-1/2" casing and 3' in bradenhead. Spot plug #4 top off casings and install P&A marker. RD and MOL.

Jim Morris, MVCI representative, was on location. Monica Keuhling, NMOCD representative, was on location.