| Submit 3 Copies To Appropriate District Office State of New Mexico   | Form C-103   |
|--|--|
| District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240  | WELL API NO.   |
| District II  | 30-045-10370   |
| District III 1220 South St. Francis Dr.  | 5. Indicate Type of Lease STATE FEE  |
| 1000 Rio Brazos Rd., Aztec, NM 87410<br>District IV Santa Fe, NM 87505   | 6. State Oil & Gas Lease No.   |
| 1220 S. St. Francis Dr., Santa Fe, NM<br>87505   | FEE  |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  | 7. Lease Name or Unit Agreement Name Wilmuth   |
| PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ☒ Other   | 8. Well Number 1   |
| 2. Name of Operator Burlington Resources Oil Gas Company LP  OIL CONS. DIV DIST. 3   | 9. OGRID Number<br>14538   |
| 3. Address of Operator   | 10. Pool name or Wildcat   |
| P.O. Box 4289, Farmington, NM 87499-4289 MAR <b>0 4</b> 2016   | Blanco Mesaverde   |
| 4. Well Location   |  |
| Unit Letter N: 800 feet from the South line and 1500   |  |
| Section 26 Township 31N Range 11W  11. Elevation (Show whether DR, RKB, RT, GR, etc.   | NMPM San Juan County   |
| 11. Elevation (Snow whether DR, RKB, R1, GR, etc. 5689' GR   |  |
| 12. Check Appropriate Box to Indicate Nature of Notice,  | Report or Other Data   |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR  | ILLING OPNS. □ P AND A □   |
|  | ready for OCD inspection after P&A   |
|  |  |
| NOTE: The subject well was P&A'd 6/4/14 and has private surface & minerals. The CDP on location 18 (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface  | n (owned by Enterprise) still services the Wilmuth   |
| <b>NOTE:</b> The subject well was P&A'd 6/4/14 and has private surface & minerals. The CDP on location 1B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.  | n (owned by Enterprise) still services the Wilmuth<br>Lease Agreement between private landowner and  |
| 1B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   ☐ All pits have been remediated in compliance with OCD rules and the terms of the Ope ☐ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been   | Lease Agreement between private landowner and<br>rator's pit permit and closure plan.<br>properly abandoned.   |
| 1B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   ✓ All pits have been remediated in compliance with OCD rules and the terms of the Ope   | Lease Agreement between private landowner and<br>rator's pit permit and closure plan.<br>properly abandoned.   |
| B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.  All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMAT   | rator's pit permit and closure plan. properly abandoned. n concrete. It show the   |
| B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.  All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU  | rator's pit permit and closure plan. properly abandoned. n concrete. It show the   |
| 1B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMAT PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has   | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR   |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMAT PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment.   | erator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and  |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATE PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment.  □ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s)   | erator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR CION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with  |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATE PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment.  □ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(stone) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines.  | erator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR CION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with  |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.  All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMAT PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment. □ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, removed from lease and well location. □ All metal bolts and other materials have been removed. Portable bases have been removed.  | crator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with production equipment and junk have been  |
| <ul> <li>1B (3004534905) &amp; Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.</li> <li></li></ul>  | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not  |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.  All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMAT PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment. □ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, removed from lease and well location. □ All metal bolts and other materials have been removed. Portable bases have been removed.  | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not  |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.  All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in   OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATE PERMANENTLY STAMPED ON THE MARKERS SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines removed from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines.   | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not all fluids have been removed from non-   |
| <ul> <li>1B (3004534905) &amp; Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.</li> <li></li></ul>  | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not all fluids have been removed from non-   |
| 1B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATE PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, removed from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to scheme.   | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not all fluids have been removed from non-nedule an inspection.  |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATE PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment.  □ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, removed from lease and well location.  □ All metal bolts and other materials have been removed. Portable bases have been remake to be removed.)  □ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines.  □ SIGNATURE □ TITLE □ Regulatory Tech  | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not all fluids have been removed from non-nedule an inspection.  |
| 1B (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATE PERMANENTLY STAMPED ON THE MARKERS SURFACE.  □ The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, removed from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to scheme.   | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. ) have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not all fluids have been removed from non-nedule an inspection.  |
| IB (3004534905) & Wilmuth 100S (3004534706). Equipment left on location is covered by Surface El Paso dated 2/10/1958.   All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUINIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMAT PERMANENTLY STAMPED ON THE MARKERS SURFACE.  The location has been leveled as nearly as possible to original ground contour and has other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, removed from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines.  When all work has been completed, return this form to the appropriate District office to schedule. Busse E-mail address: dollie.l.busse@conocopheted. | rator's pit permit and closure plan. properly abandoned. n concrete. It show the  UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR  been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with production equipment and junk have been oved. (Poured onsite concrete bases do not all fluids have been removed from non-nedule an inspection.  All fluids have been removed from non-nedule an inspection. |