Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

5. Lease Serial No.

SF-080117 6. If Indian, Allottee or Tribe Name

SUNDRY	NOTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter an
abandoned well.	Use Form 3160-3 (APD) for such proposals.

7. If Unit of CA/Agreement, Name and/or wand Management Farmington Field Office SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. **Huerfanito Unit 34R** 9. API Well No. 2. Name of Operator **Burlington Resources Oil & Gas Company LP** 30-045-30864 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 **Ballard Pictured Cliffs** 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Unit F (SENW), 1885' FNL & 1920' FWL, Sec. 34, T27N, R9W San Juan **New Mexico** 

12. CHECK	THE APPROPRIATE BOX(E	S) TO INDICATE NATURE	OF NOTICE, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	X Other	
6	Change Plans	Plug and Abandon	Temporarily Abandon	MIT	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Burlington Resources requests permission to perform a MIT on the subject well per the attached procedure in order to extend the TA status.

Notify NMOCD

24 hours

prior to MIT

OIL CONS. DIV DIST. 3 MAR 28 2016

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Dollie L. Busse Regulatory Technician Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Abdelgadir Elmadani Title Conditions of approva, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instruction on page 2)

## ConocoPhillips HUERFANITO UNIT 34R Expense - MIT

Lat 36° 32' 1.644" N

Long 107° 46' 39.9" W

## **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure.
- 4. Load casing with 2 % KCl water & corrosion inhibitor, as necessary. Perform MIT (Mechanical Integrity Test) above the bridge plug at 2,332' to 560 psig for 30 minutes on a 2 hour chart with 1000 lb. spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.

Schematic Current ConocoPhillips **HUERFANITO UNIT #34R** API / UWI NEW MEXICO noe (ii) North/South Reference 1,885.00 FNL SOUTH FULCHER KUTZ PC (GAS) 3004530864 SAN JUAN East/West Reference North/South Distance [ff] Original Spud Date Surface Legal Location East/West Distance (ft) 1,920.00 FWL 2/18/2002 034-027N-009W-F and december a VERTICAL - Original Hole; 3/15/2016 7:42:38 AM MD (ftKB) . Formation Tops Vertical schematic (actual) 12.1 Surface Casing Cement, 12.0-138.4; 2/19/2002; 50 sxs Class B; circ 4bbls to 1; Surface; 7 in; 6.458 in; 12.0 ftKB; 138.4 138.5 surface 146.0 1,492.1 Ojo-Alamo 1,652.9 Kirtland 1,982.0 Fruitland 2,332.0 Bridge Plug - Temporary: 2,332,0-2,333.0 2,333.0 2,381.9 Pictured Cliffs -2,391.1 Perf: 2.382.0-2.447.0; 3/3/2002 2,446.9 2,456.0 Perf; 2,456.0-2,637.0; 3/3/2002 2,537.1 Production Casing Cement, 12.0-2,623.4 2/21/2002; 355 sxs Prem Lite FM Lead PBTD: 2.590.0 2,589.9 followed by 90 sxs Type III fall; circ 45 bbts to surface 2; Production; 2 7/8 in; 2.441 in; 12.0ftKB; 2,623,4 PBTD: 2,590,0-2,623.5; 2/21/2002 Cement: 2,623.5-2,633.0; 2/21/2002 2,632.9 Page 1/1 Report Printed: 3/15/2016