

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OIL CONS. DIV DIST. 3

APR 27 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BP America Production Company	Contact: Steve Moskal	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497	
Facility Name: Northeast Blanco Unit #432	Facility Type: Natural gas well	
Surface Owner: Federal	Mineral Owner: Federal	API No. 3004533195

LOCATION OF RELEASE

Unit Letter O	Section 33	Township 31N	Range 7W	Feet from the 905	North/South Line South	Feet from the 2145	East/West Line East	County: San Juan
------------------	---------------	-----------------	-------------	----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.85148585° Longitude -107.5740725°

NATURE OF RELEASE



Type of Release: produced water	Volume of Release: 30.0 bbl	Volume Recovered: none
Source of Release: Tank overflow	Date and Hour of Occurrence: April 6, 2016; unknown	Date and Hour of Discovery: April 7, 2016 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith – NMOCD Aztec	
By Whom? Steve Moskal – BP	Date and Hour: 4/14/2016 – 1:28PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Production tech arrived onsite to find the produced water aboveground tank overflowing due to a failed pumping switch. The tank was pumped with the switch in the manual position.

Describe Area Affected and Cleanup Action Taken.* The released water was confined to the bermed area. Standing water was recovered via vac truck and transported for disposal. Soil samples will be collected for analysis of BTEX, GRO and DRO TPH and chloride. A subsequent C-141 will be filed with attached lab results and documentation of the gypsum application.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>4/27/2016</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 14, 2016	Phone: 505-326-9497	

* Attach Additional Sheets If Necessary

N051610548494

①