

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Tony Delfin
Deputy Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



July 5, 2016

Certified Mail Return Receipt#: 7013 1090 0001 7318 4401

Tony Cooper
McElvain Energy, Inc.
1050 17th Street
Suite 2500
Denver, CO 80265-0265

Re: Well Name Howard Federal 15 #43, UL I Sec 15 Twn 25N Rge 2W,
API # 30-039-23949

Dear Mr. Cooper:

The 2016 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **September 28, 2016**. Initial Surface Casing psi was 59. Initial Production Casing psi was 177.

The Gas analysis and wellbore schematic have been received. Gas analysis show same gas on bradenhead and production casing.

Reference: RBDMS MPK1617634647 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File
BLM Farmington Field Office