Form 3160-5 (November 1994)

SUB

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

NO-G-9601-1296

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name
MIT IN TRIPLICATE – Other instructions on reverse side	THE If Unit or CA/Agreement, Name and/or No. gement

1	Selection and the selection of the selec	
Oil Well Gas Well Other	8. Well Name and No. Rylebart Federal 1S	
2. Name of Operator		
Elm Ridge Exploration Company, LLC		9. API Well No.
3a. Address	3b. Phone No. (include area code)	30-045-30539
PO Box 156 Bloomfield, NM 87413	505-632-3476 ext. 201	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Basin Fruitland Coal
		11. County or Parish, State
1350' FNL X 990' FWL "E" Sec.24-T26N-R13W		San Juan County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	☐ Alter Casing	Fracture Treat	Reclamation	Well Integrity
O Subsequent Report	Casing Repair	New Construction	Recomplete	Other
F 69	Change Plans	X Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Elm Ridge Exploration Co., LLC requests permission to plug and abandon the following well according to the attached procedure. We will be using a closed loop system while plugging this well.

> Notify NMOCD 24 hrs prior to beginning operations

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

SEE ATTACHED FOR CONDITIONS OF APPROVAL

OIL CONS. DIV DIST. 3

2100 4 4 111

					JUN 3 0 2010
14. I hereby certify that the foregoing	s true and correct				
Name (Printed/Typed) Amy A	rchuleta	Title	Sr. R	Regulatory Supervisor	
Signature		Date		May 19, 2016	
0,01	THIS	SPACE FOR FEDER	AL OR STATE USE		
Approved by Jap Sau	ug	Ti	le PÉ	Date 5/3	16
Conditions of approval, it any, are attached or certify that the applicant holds legal or clease which would entitle the applicant to conductive the applicant to conduct the applicant the applicant the applicant the applicant to conduct the applicant the applicant the applicant to conduct the applicant the ap	ed. Approval of this notice	Oi	fice KKO		
Title 18 U.S.C. Section 1001, makes it a fraudulent statements or representations	crime for any person know		nake to any department o	r agency of the United States a	any false, fictitious or

(Instructions on reverse)

Plugging Program for Rylebart Federal 1S

- 1) MOL RU.
- 2) With EOT at 1173', mix and pump 87 sx. or sufficient volume to bring cement to surface inside 4-1/2" casing.
- 3) Cut off well head 4 feet below surface and remediate location in accordance with regulatory agencies' conditions of approval.

Elm Ridge Resources

Pertinent Data Sheet

Well Name:

Rylebart Federal 1S

Footage:

1350' FNL and 990' FWL

Location:

SWNW Section 24, T26N, R13W

County:

San Juan County, NM

API#:

30-045-30539

Field: Basin Fruitland Coal

Elevation: 6037' KB TD:1410' KB

PBTD: 1356' KB

Completed: 1/26/2005

Casing Record:

Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
8-3/4"	7"	23#	N/A	132'	65 sx. (Circ. to surface)
6-1/4"	4-1/2"	11.6#	N/A	1386'	185 sx (Circ. to surface)

Rods: Pump, 43x3/4" plain rods, 1x8-3/4 sub, 1x6-3/4 sub, 1x4-3/4" sub, polish rod

Tubing: MA, SN, 35 jts 2-3/8" tubing

Formation Tops:

Nacimiento Surface Fruitland 795' Pictured Cliffs 1123'

Perforations:

Fruitland perforations: 964-1114'

Wellbore Diagram Rylebart Federal 1S SWNW Sec. 24, T26N, R13W San Juan County, NM API #30-045-30539

Before

Nacimiento - surface

8-3/4" OH 7" 20# J-55 set @ 132' Circulated cmt to surface

Fruitland - 795'

Pictured Cliffs - 1123'

Fruitland Perforations: 964-1114' 35 its. 2-3/8" tubing

6-1/4" OH 4-1/2" 11.6# set @ 1386' Circulated cmt to surface TD: 1410'

Wellbore Diagram Rylebart Federal 1S SWNW Sec. 24, T26N, R13W San Juan County, NM API #30-045-30539

After

Nacimiento - surface

8-3/4" OH 7" 20# J-55 set @ 132' Circulated cmt to surface

Fruitland - 795'

Pictured Cliffs - 1123'

Fruitland Perforations: 964-1114'

6-1/4" OH 4-1/2" 11.6# set @ 1386' Circulated cmt to surface TD: 1410'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Rylebart Federal 1S

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.