1 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

JUL 2 5 2016

RECEIVED

FORM APPROVED OMB No. 1004-0137

	BUREAU OF LAND MA	NAGEMENT		Expires: J	uly 31, 2010		
			5. Lease Seri		M-4454		
SII	NDRY NOTICES AND REP	PORTS ON WELLS	ngton Field Office				
	se this form for proposals			i mones or annex.			
abandone	d well. Use Form 3160-3 (A	APD) for such propos	sals.				
S. S. S. W. II	UBMIT IN TRIPLICATE - Other in	structions on page 21V D	ST. 3 7. If Unit of	CA/Agreement, Na	me and/or No.		
. Type of well	_			127-			
Oil Well	X Gas Well Other	AUG 0 1 201	6 8. Well Nam		ON SRC 4E		
Name of Operator			9. API Well		0110112		
	gton Resources Oil & Gas				39-30418		
a. Address	NIN 07400	3b. Phone No. (include area	CALCULATION TO SECURE AND ADDRESS OF THE PARTY OF THE PAR	10. Field and Pool or Exploratory Area Basin DK / Blanco Mesaverde			
PO Box 4289, Farming		(505) 326-97			Sianco Mesaverde		
Location of Well (Footage, Sec., T.,	R.,M., or Survey Description)			or Parish, State	New Mexico		
ULK (N	IESW), 1370' FSL & 1875'	FWL. Sec. 2, T30N, R		, Alliba	HOW MICKIGO		
	THE APPROPRIATE BOX(ES			ORT OR OTHE	R DATA		
TYPE OF SUBMISSION			31634 V F 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
			OF ACTION				
X Notice of Intent	Acidize	Deepen	Production (Sta	art/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New Construction	X Recomplete		Other		
	Change Plans	Plug and Abandon	Temporarily Al				
Final Abandonment Notice	Convert to Injection peration: Clearly state all pertinent de	Plug Back	Water Disposal				
	shes to recomplete this well cedure, wellbore diagram a						
Burlington Resources do Tear Drop (working area Production Facilities, Pa	es not anticipate this activity) per the BLM FFO Bare Soil ge 16. Burlington Resource etated as dictated by Vegeta	Reclamation Procedus realizes that bare so	res, Part A.3 – Loc Il disturbance grea	ation of Existi ter than 0.10	ng and/or Proposed acre outside the working		
reseeding time.	ll utilize a Closed Loop Syste		s	EE ATTAC	HED FOR		
					Notify NMOCD 24 hr prior to beginning		
	s true and correct. Name (Printed/Typ ly G. Roberts	Title	Regu	latory Techni	operations		
Signature Tally G	.P.A.	Date	1/25/16	,			
	THIS SPACE FO	R FEDERAL OR STA	TE OFFICE USE				
pproved by							
AG Elmad	ani		Title PE		Date 7/28/16		
	thed. Approval of this notice does not ble title to those rights in the subject le- ons thereon.	The state of the s	Office FFO				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Carson SRC #4E

Sec 02-T30N-R05W, Unit K


API# 3003930418

Mesaverde Recompletion Sundry

7/20/2016

Procedure:

- 1. MIRU service rig and associated equipment; test BOP.
- TOOH with 2 3/8" tubing set at 8,009'.
- 3. Set a 4-1/2" composite bridge plug at +/- 6,250' to isolate the Dakota. Note: TOC at 3,100' by CBL.
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- Perforate and frac the Mesaverde in two stages (Point Lookout / Lower Menefee, and Cliffhouse / Upper Menefee).
- 7. Isolate frac stages with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top isolation plug and Mesaverde frac plugs.
- 10. Clean out to Dakota isolation plug and, when water and sand rates are acceptable, flow test the Mesaverde.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 8,092'. TOOH.
- 12. TIH and land production tubing. Get a commingled Dakota / Mesaverde flow rate.
- 13. Release service rig and turn well over to production.



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources **Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011 Permit 224040

1. API Num		2. Poo					3. F	ool Name		45041		DODATI	ED 040)
30-039-30			72319						LANCO-	MESAVE	ERDE (P	PRORATI	ED GAS)
4. Property Code 18492 5. Property Name CARSON SRC							6. V	6. Well No. 004E					
7. OGRID No. 8. Operator Name 14538 BURLINGTON R				ON RESOURCE	RESOURCES OIL & GAS COMPANY LP			9. Elevation 6535'					
	11000		DOT MAINTON			Surface Location							
UL-Lot.	Sect	Ion	Township	Range	Lot Idn	Feet From	N/S Line	Feet Fr	rom	E/W Line	e Co	ounty	
	К	2	30N	.05W		1370		3	1875		W	R RRIBA	lO.
				11. Botto	m Hole L	ocation if Differe	ent From	Burface					
UL - Lot	S	ection	Township	Range	Lot Idn	Feet From	N/SI	ine	Feet Fr	om.	E/W Line	Col	unty
The second secon	2. Dedicated Acres 318.79 W/2			13. Joint or	13. Joint or Infill		solidation Code				15. Order No.		
NOAL	LOWA	ABLEW	ILL BE ASSIG		JNIT HAS	TION UNTIL ALI BEEN APPROV	ED BY TH	E DIVIS	ON R CERT	FICATION	ON		
NO AL	LOWA	ABLEW	ILL BE ASSIG		JNIT HAS	I hereby certify that is knowledge and belie mineral interest in the this well at this locat interest, or to a volume by the division. E-Signed By: Title: Regulatory	OP the information, and that the land including pursuant attary pooling A G.	ERATO on contain is organizing the pro- to a contra agreement	R CERTI ed herein ation eithe oposed bo act with arn of a con	FICATIO is true end er owns a v ttom hole in owner of	ON d complete working in location(s,	e to the bes nterest or un s) or has a n ineral or wi	st of my nleased right to drill lorking
NO AL	LOWA	ABLEW	ILL BE ASSIG		JNIT HAS	I hereby certify that is knowledge and belie mineral interest in the this well at this local interest, or to a volume by the division. E-Signed By:	op the information f, and that the land include fon pursuant nitary pooling Can Technicia	ERATO on contain is organizating the part to a contra agreement to	R CERTI ed herein adition eithe opposed bo act with arn t or a con	FICATIO FICATIO FICATIO FICATIO at was ploi	ON i complete working in location(s) such a mi oolling ord ON tted from i	e to the best (terest or un s) or has a n (neral or wi der heretofo	st of my nleased right to drill orking ore entered

BLM CONDITION OF APPROVAL

CASING REPAIR, WORKOVER AND RECOMPLETION OPERATIONS:

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs. If a CBL or other logs are run, provide this office with a copy.
- 2. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minute test period. Provide test chart with your subsequent report of operations
- 3. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 4. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.