

## Morales, Tony, EMNRD

---

**From:** Doescher, Shelly <sdoescher@EnerVest.net>  
**Sent:** Friday, September 16, 2016 9:01 AM  
**To:** Morales, Tony, EMNRD  
**Cc:** Collins, Reubin  
**Subject:** EnerVest Operating, LLC Inspection Violations

Mr. Morales,

The following wells have been brought into compliance:

<u>Well Name and Number</u>	<u>API Number</u>	<u>Inspection Number</u>	<u>Corrective Action</u>
WLH G4S Unit No.006 location sign mounted	30-015-03403 ✓	iTM1620841023	Staining remediated,
WLH G4S Unit No.001	30-015-10498 ✓	iTM1620837122	Staining remediated
WLH G4S Unit No.001 location sign correct and legible	30-015-03233 ✓	iTM1620339767	Staining remediated,
WLH G4S Unit No.055	30-015-40525 ✓	iTM1620342705	Old pump jack removed
WLH G4S Unit No.008	30-015-04497 ✓	iTM1621539305	Staining remediated

These wells are ready for re-inspection. Thank you for your assistance.

Best regards,  
Shelly Doescher  
Agent  
EnerVest Operating, LLC  
505-320-5682

