

Morales, Tony, EMNRD

From: Doescher, Shelly <sdoescher@EnerVest.net>
Sent: Friday, September 16, 2016 9:01 AM
To: Morales, Tony, EMNRD
Cc: Collins, Reubin
Subject: EnerVest Operating, LLC Inspection Violations

Mr. Morales,

The following wells have been brought into compliance:

| <u>Well Name and Number</u> | <u>API Number</u> | <u>Inspection Number</u> | <u>Corrective Action</u> |
|--|-------------------|--------------------------|--------------------------|
| WLH G4S Unit No.006 location sign mounted | 30-015-03403 ✓ | iTM1620841023 | Staining remediated, |
| WLH G4S Unit No.001 | 30-015-10498 ✓ | iTM1620837122 | Staining remediated |
| WLH G4S Unit No.001 location sign correct and legible | 30-015-03233 ✓ | iTM1620339767 | Staining remediated, |
| WLH G4S Unit No.055 | 30-015-40525 ✓ | iTM1620342705 | Old pump jack removed |
| WLH G4S Unit No.008 | 30-015-04497 ✓ | iTM1621539305 | Staining remediated |

These wells are ready for re-inspection. Thank you for your assistance.

Best regards,
Shelly Doescher
Agent
EnerVest Operating, LLC
505-320-5682

