RECEIVED		RECEIVED	
----------	--	----------	--

N.

ŝ

Form 3160-5 (August 2007)	UNITED STATES DEPARTMENT OF THE INT	SEP 2 0 201 TERIOR	FORM APP OMB No. 1				
	BUREAU OF LAND MANAGEMENT			Expires: July 31, 2010 5. Lease Serial No.			
		NMSF-078459					
	SUNDRY NOTICES AND REPORT t use this form for proposals to dr	6. If Indian, Allottee or Tribe Nam	le				
	oned well. Use Form 3160-3 (APD)						
	SUBMIT IN TRIPLICATE - Other instruction	7. If Unit of CA/Agreement, Name	e and/or No.				
1. Type of Well		San Juan 32-7 Unit					
Oil Well	X Gas Well Other	8. Well Name and No.	8. Well Name and No. San Juan 32-7 Unit 203 (POW)				
2. Name of Operator		9. API Well No.					
3a. Address	ConocoPhillips Company	30-045-27458 10. Field and Pool or Exploratory Area					
PO Box 4289, Farm	ington, NM 87499	Phone No. (include area code) (505) 326-9700	Basin Fruitland Coal				
	c., T.,R.,M., or Survey Description) 3 (NWNE), 1265' FNL & 1775' FEL, -	11. Country or Parish, State San Juan ,	New Mexico				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF ACTION							
X Notice of Intent	Acidize I	Deepen P	roduction (Start/Resume)	Water Shut-Off			
	Alter Casing	Fracture Treat R	eclamation	Well Integrity			
Subsequent Report			ecomplete X				
Final Abandonment Notic			emporarily Abandon Vater Disposal	Pressure Observation			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) ConocoPhillips proposes to conduct a Mechanical Integrity Test and extend Temporary Abandonment status in order to continue using this well as a Pressure Observation Well per the attached procedure and wellbore diagram. OIL CONS. DIV DIST. 3 SEP 26 2016							
	on 9/21/2017 ping is true and correct. Name (Printed/Typed)						
	Kelly G. Roberts	Title	Regulatory Technician				
Signature Velly G. Rott Date 9/20/16							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
that the applicant holds legal or ec entitle the applicant to conduct op		ich would Office F	deum Engineer FD	Date 9/21/2016			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instruction on page 2) NMOCD (A) 3							

ConocoPhillips SAN JUAN 32-7 UNIT 203 POW Expense - MIT

PROCEDURE

Lat 36° 58' 12.014" N

Long 107° 33' 3.064" W

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations. Notify BLM and NMOCD 24 hours prior to MIT to obtain witnesses.

2. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Wells Engineer.

3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure.

4. Load casing with 2 % KCl water & corrosion inhibitor, as necessary. Perform MIT between the 2-3/8" tubing and 7" casing above the packer at 3060' to 560 psig for 30 minutes on a 2 hour chart with 1000 lb. spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.

