RECEIVED

.

4

Form 3160-5 (February 2005)	UNITED STATES DEPARTMENT OF THE INTERIOR			FORM APPROVED DMB No. 1004-0137 pires: March 31, 2007	
SUNDR	BUREAU OF LAND MANAGEMENT Y NOTICES AND REPORTS ON W his form for proposals to drill or to	Bureau of Land Mana	General Serial S		
abandoned well. Use Form 3160-3 (APD) for such proposals.			Jicarilla Apac		
	UBMIT IN TRIPLICATE – Other instructions of	on page 2.	7. If Unit of CA	A/Agreement, Name and/or No.	
1. Type of Well	Gas Well Other	INS. DIV DIST. 3	8. Well Name a Jicarilla 92 #1		
2. Name of Operator WPX Energy Production, LLC OCT 07 2016			9. API Well No. 30-039-29943		
3a. Address 3b. Phone No. (include area code)			10. Field and Pool or Exploratory Area		
PO Box 640 Aztec, NM 87410 505-333-1808			Blanco MV		
	4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1850' FNL & 2000' FEL SEC 29, T27N, R3W			11. Country or Parish, State Rio Arriba, NM	
the second s	X THE APPROPRIATE BOX(ES) TO INDICAT	TE NATI DE OF NOTICE		the second se	
TYPE OF SUBMISSION	A THE AFFRORMATE BOA(E3) TO INDICAL		, KEI OKI OK OI		
I THE OF SUBMISSION		TYPE OF ACTION	test (Decourse)	Water Shut-Off	
Notice of Intent	Acidize Deepen	Production (S	tart/Resume)		
	Alter Casing Fracture Treat	Reclamation		Well Integrity Other	
Subsequent Report	Casing Repair New Construction	n Recomplete		Request MIT/TA	
Bl	Change Plans Plug and Abando	on Temporarily	-		
Final Abandonment	Convert to Injection Plug Back	Water Dispos			
wPX requests to cond	terval, a Form 3160-4 must be filed once testing h reclamation, have been completed and the operato luct a MIT in order to keep the well in on 12/7/11. WPX would like to save t	r has determined that the si	te is ready for fina	and wellbore diagram.	
TA AAAau	1 until 11/01/2017	A	CTION DOES N DERATOR FRO UTHORIZATIO	AL OR ACCEPTANCE OF THIS NOT RELIEVE THE LESSEE AND DM OBTAINING ANY OTHER IN REQUIRED FOR OPERATIONS ND INDIAN LANDS	
14. I hereby certify that the fore Name (Printed Typed) Lacey Granillo	going is true and correct.	Title Permit Tech III			
Signature		Date 10/5/16			
	THIS SPACE FOR FEDERA	L OR STATE OFFIC	CE USE	1	
or certify that the applicant hold	are attached. Approval of this notice does not warrant is legal or equitable title to those rights in the subject plicant to conduct operations thereon.	Title Petroleum Office FFD	Enginee	Date 10/6/2016	
	d Title 43 U.S.C. Section 1212, make it a crime for a as or fraudulent statements or representations as to an			ny department or agency of the	
(Instructions on page 2)					
	NAC	CDR			

i.



Legacy MIT Procedure

Well: Jicarilla 92 #18A API: 30-039-29943 Location: Rio Arriba County, New Mexico S-T-R: 29-27N-3W Date: 5Oct16 Objective: Conduct Mechanical Integrity Test (MIT) AFE: N/A

EH&S Notes:

- Personnel Safety is the number one job, no exceptions.
- ✓ Please follow appropriate WPX Energy contractor protocols for this job plan. (Please see your WPX Energy Business Representative if you have any questions; Contractor protocols can be found in the WPX Energy Contractor Guide.)
- ✓ Continuous personal H2S monitoring is required. Any H2S alarms or other indications above 10 ppm will require work to stop and the situation to be evaluated
- ✓ A Safety meeting shall be held each morning before work and subsequent "tailgate" safety meetings are to be held during the day when operation objectives shift in nature and intent. Please ensure these are documented per the WPX Contractor Guide.

Prior to Job:

- Notify NMOCD/BLM 24-48 hours prior to MIT such they can witness if they choose.
- Arrange for pump truck with chart recorder for MIT based on NMOCD/BLM witness availability.

Current Wellbore Status: Well is TA'd, CIBP @ 5,720'.

- Casing
 - o 4-1/2" 11.6# K-55 LTC liner set @ 6,632'
 - o TOL 4,259'.

Procedure:

- Ensure NMOCD/BLM is present to witness or has given authorization to proceed with MIT w/o witness.
- Tie pump onto casing. Load hole as needed to perform MIT-hole should be full. Conduct 500-550 psi MIT for at least 30 minutes, recording pressure with a chart recorder per regulatory requirements. Turn chart into NMOCD/BLM as required.

Notes:

Ensure all JSA's, ECP's and Lockout procedures are in place for energized piping or equipment.

Jicarilla 92 #18A Blanco Mesa Verde

 Spud Date:
 02-03-09

 Completed:
 03-25-09

 1st Delivered:
 00-00-00

 5 year MIT/TA

Location: 1850' FNL & 2000' FEL SW/4 NE/4 Section 29 (G), T27N, R03W Rio Arriba Co., NM

Elevation: 7262' GR API #: 30-039-29943

<u>Tops</u>	<u>Depth</u>
Fruitland	3810'
Pictured Cliffs	4010'
Cliff House	5741'
Menefee	5864'
Point Lookout	6171'
Mancos	6509'

<u>CliffHouse/upper Menefee</u> 5748'-6038' (50, 0.35' holes) Frac w/ 1239# 20/40 BASF, followed by 5000# Mono prop, followed by 5100# 20/40 BASF.

<u>PLO/lower Menefee</u> 6063'-6254' (60, 0.34" holes) Frac w/ 819# 20/40 BASF, followed by 5000# Mono prop

Lower PLO_6286"-6340" (25, 0.34" holes) Frac w/69# 20/40 BASF, followed w/1640# Mono Prop, followed w/273# 20/40 BASF

> Weatherford 4-1/2" / Cement retainer @ 6370'

7 jts of 9-5/8", 36#, K-55, LT&C csg. Set @ 341'.
109 jts of 7", 23#, K-55, LT&C csg. Set @ 4422'.
Top of Liner: 4259'
53 jts of 4-1/2", 11.6#, K-55, LT&C csg. Set @ 6632', Marker Jt @ 5141'. TOL: 4259'
CIBP @ 5720'
5748' 6038'
6063' 6254'

TD @ 6641' PBTD @ 6370' 6286' 6340'

HOLE SIZE	CASING	CEMENT	CU. FT.	CMT TOP
12-1/4"	9-5/8", 36#	200 s xs	240 cu.ft.	surface
8-3/4"	7",23#	545 s xs	1330 cu.ft.	surface
6-1/4"	4-1/2", 11.6#	250 s xs	342 cu.ft.	4290' (CBL)