

## **United States Department of the Interior**

## BUREAU OF LAND MANAGEMENT

Farmington Field Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



In Reply Refer To: 3162.3-2 (21110)

October 31, 2016

Ms. Arleen White Vulcan Minerals & Energy INC. P.O. Box 4289 Farmington, NM 87499 OIL CONS. DIV DIST. 3 NOV 0 3 2016

Dear Ms. White:

Our records indicate that Vulcan Minerals & Energy INC. is operator of the following well:

 Horseshoe Gallup Unit No. 4W; API: 30-045-10163; 2390' FSL & 0738' FWL; sec.34, T.31N., R.16W.; San Juan County, New Mexico; Lease 14206041951;. Well last produced in January, 1963.

Title 43 CFR Section 3162.3-4 requires that the lessee shall promptly plug and abandon, condition as a service well, or condition as a water well, any well on a lease that is not used or useful for the purpose of the lease. Accordingly, you are required to advise this office by Sundry Notice within 30 calendar days of your intent to perform one of the following: a) Condition the well to a useful function, b) Temporarily abandon the well, c) Continued shut-in status, d) Permanently plug and abandon the well.

See attached General Requirements for Non-Producing wells on Federal leases.

The 30 calendar days commences upon receipt of this letter or seven days from the date it is mailed, whichever is less. Failure to comply within the 30 calendar days may result in an assessment in accordance with 43 CFR 3163.1.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the orders described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management (NM-93000), P.O. Box 27115, Santa Fe, New Mexico 87502-0115. Such request shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 et seq.

If you have any questions, please contact William Tambekou at (505) 564-7746.

Sincerely,

William Tambekou Petroleum Engineer

Petroleum Management Team

1 Attachment

bcc: well file

**NMOCD**