RECEIVED

Form 3160-5 (February 2005) JUH 3 0 2016

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Farmington Field Office
Bureau of Land Managemen

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an			5. Lease Serial No. NO-G-1401-1867	
abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well			NMNM 13521	6X
Oil Well Gas Well Other			8. Well Name and No. W. Lybrook UT # 707H	
Name of Operator WPX Energy Production, LLC			 API Well No. 30-045-35739 	
3a. Address 3b. Phone No. (include area code) PO Box 640 Aztec, NM 87410 505-333-1808			10. Field and Pool Lybrook Manco	ol or Exploratory Area
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 877' FSL & 366' FEL, Sec 12, T23N, R9W BHL: 339' FNL & 2325' FWL, Sec 12 T23N, R9W			11. Country or Parish, State San Juan, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA				
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent Acidize Alter Cas	· =	Production (Sta	urt/Resume)	Water Shut-Off Well Integrity
Subsequent Report Casing Repair New Construction Change Plans Plug and Abandon		= -	OtherAbandon COMPLETION	
Final Abandonment Notice Convert	to Plug Back	Water Disposal	Water Disposal scluding estimated starting date of any proposed work and approximate	
duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)				
5/9/16- MIRU prsr test- GOOD OIL CONS. DIV DIST. 3				
Perf MC 1st stage, 9910'-10035' + RSI TOOL @ 10109' with 18, 0.35" holes. RDMO wait for frac JUL 08 2016				
5/10/16-5/18/16- wait on frac CONFIDENTIAL 5/19/16-Frac MC 1st stage 9910'-10109'- with 310,927# 20/40 PSA Sand				
5/19/16-Frac MC 1st stage 9910'-10109'- with 310,927# 20/40 PSA Sand				
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Lacey Granillo Title Permit Tech				
Signature Date 6/30/16 THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by				
		Title		Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowinMCy and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				

(Instructions on page 2)

NMOCDPY

ACCEPTED FOR RECORD

JUL 0 5 2016

5/20/16-Set flo-thru frac plug @ 9883' MD. Perf 2nd stage 9700'-9856'-with 24, 0.35" holes. Frac MC 2nd stage with 311,609#, 20/40 PSA Sand

Set flo-thru frac plug @ 9672' MD. Perf 3rd stage 9489'-9645'- with 24, 0.35" holes. Frac MC 3rd stage with 309,560#, 20/40 PSA Sand 5/21/16-Set flo-thru frac plug @ 9461' MD. Perf 4th stage 9278'-9434'- with 24, 0.35" holes. Frac MC 4th stage with 310,135#, 20/40 PSA Sand

Set flo-thru frac plug @ 9250' MD. Perf 5th stage 9067'-9223'-with 24, 0.35" holes. Frac MC 5th stage with 312,620#, 20/40 PSA Sand 5/22/16-Set flo-thru frac plug @ 9039' MD. Perf 6th stage 8856'-9012'- with 24, 0.35" holes. Frac MC 6th stage with 308,720#, 20/40 PSA Sand

Set flo-thru frac plug @ 8836' MD. Perf 7th stage 8645'-8801'- with 24, 0.35" holes. Frac MC 7th stage with 310,594#, 20/40 PSA Sand Set flo-thru frac plug @ 8614' MD. Perf 8th stage 8434'-8590'- with 24, 0.35" holes. Frac MC 8th stage with 310,398#, 20/40 PSA Sand Set flo-thru frac plug @ 8406' MD. Perf 9th stage 8223'-8379'- with 24, 0.35" holes. Frac MC 9th stage with 313,260#, 20/40 PSA Sand 5/23/16-Set flo-thru frac plug @ 8195' MD. Perf 10th stage 8012'-8165'- with 24, 0.35" holes. Frac MC 10th stage with 310,860#, 20/40 PSA Sand

Set flo-thru frac plug @ 7984' MD. Perf 11th stage 7802'-7957'- with 24, 0.35" holes. Frac MC 11th stage with 310,305#, 20/40 PSA Sand Set flo-thru frac plug @ 7773' MD. Perf 12th stage 7590'-7746'- with 24, 0.35" holes. Frac MC 12th stage with 310,176#, 20/40 PSA Sand Set flo-thru frac plug @ 7562' MD. Perf 13th stage 7379'-7535'- with 24, 0.35" holes. Frac MC 13th stage with 309,160#, 20/40 PSA Sand 5/24/16-Set flo-thru frac plug @ 7350' MD. Perf 14th stage 7168'-7324'- with 24, 0.35" holes. Frac MC 14th stage with 309,440#, 20/40 PSA Sand

Set flo-thru frac plug @ 7145' MD. Perf 15th stage 6955'-7113'- with 24, 0.35" holes. Frac MC 15th stage with 266,300#, 20/40 PSA Sand Set flo-thru frac plug @ 6929' MD. Perf 16th stage 6746'-6902'- with 24, 0.35" holes. Frac MC 16th stage with 309,868#, 20/40 PSA Sand Set flo-thru frac plug @ 6712' MD. Perf 17th stage 6535'-6691'- with 24, 0.35" holes. Frac MC 17th stage with 310,860#, 20/40 PSA Sand 5/25/16-Set flo-thru frac plug @ 6514' MD. Perf 18th stage 6324'-6480'- with 24, 0.35" holes. Frac MC 18th stage with 309,400#, 20/40 PSA Sand

Set flo-thru frac plug @ 6296' MD. Perf 19th stage 6114'-6269'- with 24, 0.35" holes. Frac MC 19th stage with 311,149#, 20/40 PSA Sand Set flo-thru frac plug @ 6085' MD. Perf 20th stage 5902'-6058'- with 24, 0.35" holes. Frac MC 20th stage with 310,488#, 20/40 PSA Sand 5/26/16-Set flo-thru frac plug @ 5874' MD. Perf 21st stage 5691'-5847'- with 24, 0.35" holes. Frac MC 21st stage with 314,600#, 20/40 PSA Sand

5/26/16-Set 4-1/2" CBP @ 5640'

RDMO Frac & WL.

5/27/16-6/23/16- wait on DO

6/24/16- Pressure test BOP- 200 psi high 3000 psi- good

DO flo-thru Frac plug @ 5640', 5874', 6085', 6296', 6514', 6712', 6929', 7145', 7350', 7562' & 7773'

6/25/16- DO flo-thru Frac plug @ 7984', 8195' & 8406'

6/26/16- DO flo- thru Frac plug @ 8614', 8836', 9039', 9250', 9461', 9672'& 9883'

Circ. & CO

6/27/16- pull tieback

Land well at 5,616' w/ 25' KB as follows, 1/2 MS, 1 Jt of 2.375" J55 tbg, 1.87" XN set at 5487.68', 4 Jt of 2.375" J55 tbg, 2.375" XOVER-2.875, 7" AS1-X Pkr set at 5,453.38', On/Off Tool at 5,445.8', 4' pup jt, 1 Jt 2.875" J55 tbg, GLV #1 set at 5,407.26', 11 Jts of 2.875" J55 tbg, X-NIP set at 5,044.68', 10 Jts of 2.875" J55 tbg, GLV #2 set at 4,717.57', 14 Jts of 2.875" J55 tbg, GLV #3 set at 4,257.13', 15 Jts of 2.875" J55 tbg, GLV #4 set at 3,764.31', 14 Jts of 2.875" J55 tbg, GLV #5 set at 3,303.94', 15 Jts of 2.875" J55 tbg, GLV #6 set at 2,811.19', 15 Jts of 2.875" J55 tbg, GLV #7 set at 2,318.44', 16 Jts of 2.875" J55 tbg, GLV #8 set at 1,792.95', 21 Jts of 2.875" J55 tbg, GLV #9 set at 1,105.09', 33 Jts of 2.875" J55 tbg, 2.875" J55 tbg, Hanger, 25' KB Total 4 Jts of 2.375" J55 tbg in well, Total 163 Jt of 2.875" J55 tbg in well, Total 170 Jts, Landed TBG in 25k Tension. RD rig floor and equipment. ND BOP stack and NU prod tree. Test TBG hanger seals good to 3000 psi. 6/28/16- Oil Delivery

Note: Will file flow info on delivery sundry