RECEIVED

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP 0 7 2016

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELL Ston Field Office NMNM 057164 Do not use this form for proposals to drill onto recenter all anagement 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well OIL CONS. DIV DIST. 3 8. Well Name and No. Lybrook 2309 34B #765 Oil Well Gas Well Other NOV 1 0 2016 2. Name of Operator 9. API Well No. WPX Energy Production, LLC 30-045-35731 3b. Phone No. (include area code) 3a. Address 10. Field and Pool or Exploratory Area PO Box 640 Aztec, NM 87410 505-333-1808 **Basin Mancos** 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State SHL: 550' FNL & 1508' FEL SEC 34 23N 9W San Juan, NM BHL: 409' FNL & 1522' FEL SEC 34 23N 9W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) Notice of Intent Fracture Treat Well Integrity Alter Casing Reclamation New Construction Casing Repair Recomplete Other Completion Subsequent Report Temporarily Abandon Plug and Abandon Change Plans Convert to Final Abandonment Notice Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 8/10/16-8/15/16 MIRU, C/O 8/15/16- Tag on joint 166, 30 ft out @ 5,256 ft (Float Collar @ 5,279 ft) Rig up to Circulate Hole, Pull out of the hole with tubing. Test 5-1/2 Casing for 30 minutes, 4000 psi, Test Good 8/16/16- Run in the Hole as Followed Gun, 10 ft space, Gun 8 ft Space, Gun 12 ft Space, Gun, 6 ft Perf Sub, 4 ft sub, 10 ft sub, packer, 1 joint, xn nipple start running in the hole with tubing, Set Packer @ 5,098 ft. Test Packer to 500 psi, good test 8/17/16- RIH, Set Gauges in XN Nipple @ 5,064' (Top gauge set @ 5,069', lower guage set @ 5,070') POOH Test Halliburton Lines to 6,400 psi, Test Good Perforating Guns shot (Perf Depths 5,118' - 5,119 / 5,130' - 5,131' / 5,138' - 5,139' / 5,148'- 5,149'), start dfit pump in. SD 8/18/16-8/31/16- Monitor gauges 9/1/16- TOOH with Down Hole Gauges, Release Packer, TOOH 102 Stands. SD 9/5/16- WPX notified and received verbal approval from BLM (William & AG) & OCD (Brandon) to plug back the Sanastee interval per attached procedure & wellhore and to continue with operations.

ACCEPTED FOR RECORD 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typ) Lacey Granillo Title Permit Tech III FARMINGTON FIELD OFFICE Signatur IS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

(Instructions on page 2)



United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Lybrook 2309-34B #765 P&A Procedure

Sanastee

- 1. Move Wireline truck and rig up.
- 2. Run in the well and set Cast Iron Bridge plug @ 5,100'.
- 3. Run in with cement dump bailer and cement on top of CIBP. 4sx Type 1 Portland cement (5 cu/ft) approx. 35+' coverage above cibp. Tag with wireline to verify top of cement.

Garrett Stacey - Garrett.Stacey@wpxenergy.com

Lybrook 2309-34B # 765

Spud: 5/11/16


SHL: 550' FNL & 1,508' FEL NW/4 NE/4 Section 34(B), T23N, R9W

BHL: 334' FNL & 2193' FEL NW/4 NE/4 Section 34(B), T23N, R9W

San Juan, NM Elevation: 6696' API: 30-045-35731

Formation	MD	TVD
PICTURE CLIFFS	957	955
LEWIS	1061	1057
CHACRA	1316	1307
CLIFF HOUSE	2259	2230
MENEFEE	2331	2300
POINT LOOKOUT	3343	3295
MANCOS	3486	3436
GALLUP	3663	3613

TD: 5327' MD TVD: 5327' PBTD: 5279' MD



HOLE SIZE	CASING	CEMENT	VOLUME	CMT TO
12-1/4"	9-5/8"	10 ls x	162cu.ft.	Surface
8-3/4"	5-1/2"	1360 sx	2246u.ft.	Surface
	4.11			