

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: San Juan 29-6 Unit 31M	Facility Type: Gas Well

Surface Owner Public (Private)	Mineral Owner Federal	API No. 3003927516
---------------------------------------	------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter K	Section 10	Township 29N	Range 06W	Feet from the 2275	North/South Line South	Feet from the 2060	East/West Line West	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.73919 Longitude -107.45162

NATURE OF RELEASE

Type of Release Hydrocarbon - Condensate	Volume of Release 14 BBL	Volume Recovered 0 BBL
Source of Release Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 02/20/14 @ 12:20 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Pinhole on bottom side of weld at bottom of production tank caused a slow release of 14 BBLs of condensate, in which 0 BBLs were recovered. Leak was stopped and product transferred.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary. Third-Party Environmental assessed. Excavation was 10' x 10' x 4' Deep. 44 c/yds of soil was transported to I.E.I Land Farm and 44 c/yds of clean soil was transported from Bill Smith Ranch, and placed in the excavation site. Analytical results were below the regulatory standards – no further action required. The soil sampling report is attached for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 2/8/17	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval: Modifications to total yard Rest of Report	Attached <input type="checkbox"/>
Date: June 19, 2014	Phone: (505) 326-9786	

* Attach Additional Sheets If Necessary

#NSK 1425132861

In Well File

①