RECEIVED

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BURGALL OF LAND MANAGEMENT

FEB 07 2817

FORM APPROVED OMB No. 1004-0137

OITE	U. 1 U		010,
Expires:	July	31,	2010

	BUREAU OF LAND MAI	NAGEMENT	- 1	Expires: J	uly 31, 2010
		Farmi	ngton Fie	5. Lease Serial No.	N-078194
SUN	NDRY NOTICES AND REPO				
	e this form for proposals t				
	well. Use Form 3160-3 (A				
	UBMIT IN TRIPLICATE - Other ins	tructions on page 2.		7. If Unit of CA/Agreement, Na	me and/or No.
1. Type of Well Oil Well	X Gas Well Other		-	8. Well Name and No.	
On wen	A das well United				rick LS 13B
2. Name of Operator	0 011111		9	9. API Well No.	45.00400
3a, Address	ConocoPhillips Compa	3b. Phone No. (include area	code)	10. Field and Pool or Explorator	45-30136 rv Area
PO Box 4289, Farmingt		(505) 326-97			erde / Basin Dakota
4. Location of Well (Footage, Sec., T.,F				11. Country or Parish, State	
Surface Unit B (N	NWNE), 660' FNL & 2600' F	EL, Sec. 5, T29N, R	10W	San Juan ,	New Mexico
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATUR	E OF NOT	ICE, REPORT OR OTHE	R DATA
TYPE OF SUBMISSION		TYP	E OF ACT	ION	
X Notice of Intent	Acidize	Deepen	Pro	oduction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Re	eclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction		ecomplete	X Other Payadd
First About and Marie	Change Plans	Plug and Abandon		mporarily Abandon	
Final Abandonment Notice 13. Describe Proposed or Completed Op	Convert to Injection	Plug Back		ater Disposal	to duration thereof
Testing has been completed. Final determined that the site is ready for ConocoPhillips request the Blanco Mesaverde for the Standard Mesaverde for the Stand	red operations. If the operation results Abandonment Notices must be filed or r final inspection.) ts permission to add pay t formation per the attached oved before the work proc	o the subject well in	the Basi	in Dakota formation a	the operator has
0			AC OF AU	LM'S APPROVAL OR ACC TION DOES NOT RELIE PERATOR FROM OBTAIN JTHORIZATION REQUIR N FEDERAL AND INDIAN	VE THE LESSEE AND NING ANY OTHER RED FOR OPERATIONS
			Cano	selled MK2	-21-17
14. I hereby certify that the foregoing is	true and correct. Name (Frimew Type	4)			
Dollie L. Busse	7	Title Regu	llatory Te	chnician	
Signature	J Busse	Date A	6/2	2017	
	THIS SPACE FO	R FEDERAL OR STA	ATE OFFI	CE USE	
Approved by William	Tambekou		Title Petro	leum Enginee	p Date 2/8/2017
Conditions of approval, if any, are attach	ned. Approval of this notice does not v	varrant or certify			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Office FFO

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equitable title to those rights in the subject lease which would

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 229863

 HARTAGA	ALID AOD	FAGE DEDI	MILAMAA	A -
M - W W W				Δ

	TILLE LOOK HOW THE MOUNT OF DEDICATION I LA						
1. API Number	2. Pool Code	3. Pool Name					
30-045-30136	71599	BASIN DAKOTA (PRORATED GAS)					
4. Property Code	5. Property Name	6, Well No.					
31823	LUDWICK LS	013B					
7. OGRID No.	8. Operator Name	9. Elevation					
217817	CONOCOPHILLIPS COMPANY	5881					

10. Surface Location

UL - Lot Sec	tion Township	Range	Lot Idn Feet From	N/S Line F	Feet From E/V	W Line C	County
В	5	29N 10W	660	N	2600	E	SAN JUAN

11. Bottom Hole Location If Different From Surface

			II. DOLLOIN	HOIG LOCATION	I II Dillordille I	TOIL OULIACE			
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 297.66		13. Joint or Infil	i	14. Consolidation	on Code		15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	•	
.*		

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By:

Regulatory Technician Title:

12/15/2016 Date:

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Neale C. Edwards

Date of Survey: Certificate Number:

10/16/1999

Ludwick LS #13B

Sec 05-T29N-R10W, Unit B

API# 3004530136

Dakota Recomplete Sundry

1/5/2017

Procedure:

- MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 4,586'.
- 3. Pick up 4-3/4" bit, TIH with 2-3/8" work string and drill cement plug from 6,820' 6,860'. TOOH.
- 4. Pick up packer for 5-1/2" casing, TIH to 5,010' and test casing to frac pressure. TOOH.
- 5. Make up 5-1/2" packer to 3-1/2" frac string and TIH to 5,010'.
- 6. Test casing, packer, and frac string to frac pressure.
- 7. N/U frac stack and test.
- 8. Perforate and fracture stimulate the Dakota. Flowback.
- 9. N/D the frac stack and pull the 3-1/2" frac string.
- 10. TIH with 2-3/8" tubing and clean out to new PBTD of 6,860'.
- 11. When sand and water rates are acceptable, land production tubing and get a commingled Dakota / Mesaverde flow rate.
- 12. Release service rig and turn well over to production.

