## RECEIVED

Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR 16 201 BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. Farmington Field Office Contract 64 SUNDRY NOTICES AND REPORTS ON WELLS IN Manager Confindian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. Jicarilla Apache SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well X Gas Well Oil Well Other 8. Well Name and No. Jicarilla 20 5 2. Name of Operator 9. API Well No. ConocoPhillips Company 30-039-20446 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 Lindrith Gallup-Dakota West 11. Country or Parish, State 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit P (SESE), 390' FSL & 620' FEL, Sec. 20, T25N, R4W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Water Shut-Off Acidize Deepen Production (Start/Resume) Well Integrity Alter Casing Fracture Treat Reclamation Subsequent Report Casing Repair New Construction Recomplete Other. Change Plans Plug and Abandon Temporarily Abandon Remedial Work Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Please see attached. OIL CONS. DIV DIST. 3 ACCEPTED FOR RECORD MAR 0 1 2017 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Crystal Walker Regulatory Coordinator** Title

Signature Date 2/16/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.







Jicarilla 20 5 30-039-20446

12/20/2016 MIRU BES 1583. ND WH. NU BOPE. PT BOPE. Test - OK. 12/21/2016 RIH w/ 4 1/2" pkr set @ 30'. PT csg to 600#. Test - Failed. Unset Pkr & RIH w/ 4 1/2" RBP. Set RBP @ 60'. RIH w/ pkr @ 30'. Test RBP. Test - OK. POOH w/ Pkr. Remove tbg head & csg slips. Gas leaking from BH. Attempt to pump kill on BH. Pumped 20bbls w/ Opsi. BH unloaded Water. Bubbles seen around WH. See NOI Filed 12/21/16 NU original tbg head & BOP. POOH w/ RBP. R/U Two 3" flowlines to flowback tank. Monitor well. 12/22/2016 TOOH w/ 2 3/8" tbg. RU W/L. RIH w/ gauge ring to 5223'. Unable to get past 5223'. POOH. RIH w/ 4" CIBP set @ 5218'. Unable to get off CIBP. Pull out of rope socket. Tag CIBP. POOH. Load hole. Run CBL. Log from 5218' to Surface. Good cmt to 2500'. PU pkt. RIH 10'. Below WH. Attempt to PT csg to 800#. PT - Failed. See NOI Filed 12/22/2016. 12/23/2016 RIH w/ 4 1/2" RBP set @ 1230'. Load hole w/ 12bbls. PU Pkr. RIH 30' & PT. Test- Failed. TOOH to surface. RIH w/ pkr set @ 370'. PT csg above and below pkr. No Test. TIH to 30' above RBP & Test. Test - OK. Work out of hole testing 4 1/2" csg. Top of Good csg @ 673'. 12/23/16 Notified BLM (Jack Savage), JOGA (Bryce Hammond) and OCD (Brandon Powell with request to set cmt retainer @ 680', Perf @ 730 and pump cmt since it was determined csg is leaking from 673' up. Verbal approval received. RU W/L. Perf @ 730'. Pump 15bbls down tbg. No returns. RIH w/ cmt retained @ 643'. Pump 425sx, 501cf, 89bbls Class B NEAT cmt. Had returns to surface after 15bbls cmt pumped. Lost returns @ 30bbls and never regained. Monitored well overnight. 12/27/2016 RIH w/ 2 3/8" tbg. Tag cmt @ 633'. Cmt retainer @ 643'. Start D/O cmt and cmt retainer @ 643'. Tagged cmt @ 680' and D/O to 690'. Circulate with clean returns. 12/28/2016 TIH w/ Drilling assembly. Tag cmt @ 690'. D/O cmt from 690' to 824'. Circ. PT 4 1/2" csg to 600#. Test -Failed. Fluid out of BH Annulus. RIH w/ 4 1/2" RBP @ 1230'. Unset RBP. RIH w/ Fishing Assembly. Tripped to 4860'. 12/29/2016 Tag TOF @ 5210'. Engage Fish. Recover all of setting tool Fish. 12/30/2016 Gas leaking around WH & Surface csg. Opened well to Flowback Tank. RU W/L. Run GR/CBL/CCL Log from 2500' to Surface. Cmt top in 4 ½" annulus @ 580'. Circ from 4 ½" annuals from outside of surface csg. 12/30/2016 Notified BLM (Troy Salvers), JOGA (Bryce Hammond) and OCD (Brandon Powell) of request to permission to Perf @ 500' and pump 100sx to shut-off surface water/pressure. Verbal approval received. RIH and Perf @ 500'. RD W/L. Set cmt retainer @ 447'. Pump 5bbls FW. Pumped 31bbls cmt slurry and lost circ. Pumped 150sx Class B cmt at 1.18ft3 yield. Pumped 146sx through sqz holes @ 500'. Left 4sx below cmt retainer. Displaced cmt w/ 2bbls FW. TOC estimated @ 445'. TOOH. Blind Rams Closed & Locked. 1/3/2016 Make-Up Drilling Assembly. TIH & tag cmt @ 441'. D/O cmt to 520'. Circ clean. D/O cmt to 780'. 1/3/2017 Notified BLM (Troy Salvers), JOGA (Bryce Hammond) and OCD (Brandon Powell) of performed sqz and did not receive returns to surface, but water is gone and pressure is minimal. Requested to perform CBL from 5218' up and start P&A procedure from CIBP @ 5218' due to csg issues. Verbal approval received. 1/4/2017 – 1/10/2017 Tag cmt @ 780' D/O cmt for several day. to 1071'. 1/5/2017 D/O cmt to 1940'. 1/11/2017. Tag CIBP @ 5218'. RU W/L. Run GR/CBL/CCL Log from 5218' to Surface. RD W/L. RIH w/ tbg/cmt BHA to 5103'.

. . . .

P&A operations continue and P&A Report will be submitted on separate sundry.