

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: TALLANT No. 001	Facility Type: Natural gas well

Surface Owner: Federal	Mineral Owner: Federal	API No. 3004529058
------------------------	------------------------	--------------------

LOCATION OF RELEASE

Unit Letter J	Section 26	Township 30N	Range 08W	Feet from the 1,510	North/South Line South	Feet from the 1,460	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.77990° Longitude -107.64139°

NATURE OF RELEASE



Type of Release: natural gas	Volume of Release: 350 mcf	Volume Recovered: none
Source of Release: Compressor PSV	Date and Hour of Occurrence: 3/17/2017 @ 10:00 AM	Date and Hour of Discovery: 3/20/17 @ 12:45PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* During restart of down compressor, the operator heard gas seeping by at separator. Found that PSV on fuel pot was only holding 25# on gauge and was leaking gas. Shut in separator and reported.

Describe Area Affected and Cleanup Action Taken.* Pressure sensitive valve vented directly to atmosphere. No action necessary outside of repairing or replacing the PSV.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>4/6/2017</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval: <u>NIF1709652779</u>	Attached <input type="checkbox"/>
Date: March 29, 2017	Phone: 505-326-9497	

* Attach Additional Sheets If Necessary

MAR 30 2017
OIL CONS. DIV DIST 3