Form 3160-5 June 2015)	15) UNITED STATES DEPARTMENT OF THE INTERIOR					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2						5. Lease Serial No. NMSF078139		
						6. If Indian, Allottee or Tribe Name		
						7. If Unit or CA/Agreement, Name and/or No. SW455		
1. Type of Well ☐ Oil Well ☑ Gas Well ☐ Other						8. Well Name and No. ELLIOTT GAS COM T 1		
2. Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION COMPA®-Mail: Toya.Colvin@bp.com						9. API Well No. 30-045-20297-00-S1		
	LAKE PARK BLVD , TX 77079	. THREE ELDRIGE PLAC	io. (include area code) 92.5369) 10. Field and Pool or Exploratory Area KUTZ PICTURED CLIFFS				
	-	, R., M., or Survey Description		11. County or Parish, State				
	N R9W NWNE 079 N Lat, 107.746310				SAN JUAN COUNTY, NM			
12.	CHECK THE AP	PROPRIATE BOX(ES)	TO INDIC.	ATE NATURE O	F NOTICE,	REPORT, OR OTI	HER DATA	
TYPE OF	PE OF SUBMISSION TYPE OF ACTIO							
🛛 Notice of	Intent				5-30	ion (Start/Resume)	U Water Shut-Off	
Subseque	nt Report	 Alter Casing Casing Repair 	_ ,		 Reclamation Recomplete 		Well Integrity Other	
□ Final Abandonment Notice		Change Plans	-	Plug and Abandon		Temporarily Abandon		
		Convert to Injection			U Water D			
determined th	at the site is ready for fines to P&A the subject	andonment Notices must be fil nal inspection. ct well. Please see the at	-	0 - 800		mation OIL C	ONS DIVE	
In accordar operations.	nce with NMOCD P	it Rule 19.15.17.9 NMAC	e a closed-loop sy	stem during	A	PR 1 7 2017		
C	SEE ATTAC ONDITIONS C	CHED FOR DF APPROVAL Notify NMO prior to be operat	ginning	ACTION OPERAT AUTHO	DOES NOT	R ACCEPTANCE O RELIEVE THE LES OBTAINING ANY O' EQUIRED FOR OPI NDIAN LANDS	F THIS SEE AND THER	
14. I hereby cert	ify that the foregoing is	true and correct. Electronic Submission # For BP AMERICA PR nmitted to AFMSS for proc	371879 verifi CODUCTION cessing by J	ed by the BLM We COMPANY, sent to ACK SAVAGE on 0	ll Information o the Farming 4/13/2017 (17	System gton JWS0088SE)		
Name (Printed/Typed) TOYA COLVIN				Title REGUL	ATORY AN	ALYST		
Signature (Electronic Submission)				Date 04/03/2	017			
		THIS SPACE FO	OR FEDER	AL OR STATE	OFFIÇE U	SE		
Approved By J	ACK SAVAGE		TitlePETROLE		ER	Date 04/13/20		
onditions of appr rtify that the app	oval, if any, are attached	 Approval of this notice does itable title to those rights in the ct operations thereon. 	1					
tle 18 U.S.C. Sec States any false, t	ction 1001 and Title 43 I fictitious or fraudulent s	J.S.C. Section 1212, make it a tatements or representations as	crime for any p to any matter	person knowingly and within its jurisdiction.	willfully to ma	ke to any department or	agency of the United	

4

Z

NMOCD PY

PLUG AND ABANDONMENT PROCEDURE

November 9, 2016


Elliott GC T 001 Blanco Pictured Cliffs 790' FNL and 1615' FEL, Section 26B, T30N, R09W San Juan County, New Mexico / API 30-045-20297 Lat: N / Lat: W

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.

If this well has rods or a packer, then modify the work sequence in step #2 as appropriate. Round trip 4.5" mill to 2502'.

- NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or where a T.S. or CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
- Plug #1 (Pictured Cliffs interval and Fruitland top, 2502' 2156'): RIH and set 4.5" CR at 2502'. Circulate well clean. Pressure test tubing to 1000#. Pressure test casing to 800#. <u>If</u> <u>casing does not test then spot or tag subsequent plugs as appropriate.</u> Mix 31 sxs Class B cement inside casing from 2502' to cover the PC interval and Fruitland top. PUH.
- Plug #2 (Kirtland and Ojo Alamo tops, 1554' 1357'): Mix and pump 19 sxs Class B cement and spot a balanced plug inside casing to cover the Kirtland and Ojo Alamo tops. PUH.
- 4. Plug #3 (8-5/8" casing shoe, 273' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 25 sxs cement and spot a balanced plug from 273' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

Proposed Wellbore Diagram



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD.

FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Elliot Gas Com T 1

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

a) Set Plug #2 (1580-1308) ft. to cover the entire Ojo Alamo interval. BLM picks top of Kirtland at 1530 ft. BLM picks top of Ojo Alamo at 1358 ft.

Operator must run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.