UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals	

5. Lease Serial No. NMNM021121

abandoned wel	6	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. SW131				
Type of Well Oil Well	8	Well Name and No. MONCRIEF FEDERAL 1						
Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION COMPAN-Mail: Toya.Colvin@bp.com				9. API Well No. 30-045-08084-00-S1				
3a. Address 501 WESTLAKE PARK BLVD. THREE ELDRIGE PLACE: 281.892.5369 HOUSTON, TX 77079				10. Field and Pool or Exploratory Area BASIN DAKOTA WEST KUTZ PICTURED CLIFFS				
4. Location of Well (Footage, Sec., T.	1	11. County or Parish, State						
Sec 22 T29N R12W SENE 14 36.715260 N Lat, 108.081090		SAN JUAN COUNTY, NM						
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production	(Start/Resume)	☐ Water Shut-Off			
	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	on	■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair	■ New Construction	□ Recomplet	e	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	□ Temporari	ly Abandon				
BP	□ Convert to Injection	☐ Plug Back	■ Water Disp	oosal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BP requests to P&A the subject well. Please see the attached P&A procedure and wellbore diagram. In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during SEE ATTACHED FOR CONDITIONS OF APPROVAL Notify NMOCD 24 hrs prior to beginning operations Notify NMOCD 24 hrs prior to beginning operations Notify NMOCD 24 hrs prior to beginning operations Notify NMOCD 25 hrs prior to beginning operations Notify NMOCD 26 hrs prior to beginning operations								
14. I hereby certify that the foregoing is true and correct. Electronic Submission #375928 verified by the BLM Well Information System For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by ABDELGADIR ELMADANI on 05/17/2017 (17AE0212SE) Name (Printed/Typed) TOYA COLVIN Title REGULATORY ANALYST								
Signature (Electronic S	Submission)	Date 05/11/2	2017					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By ABDELGADIR ELM/ Conditions of approval, if any, are attached certify that the applicant holds legal or equ	rant or	ROLEUM ENGINEER Date (Date 05/17/2017				
which would entitle the applicant to condu		Office Farming	gton					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				to any department or a	gency of the United			

(Instructions on page 2) ** BLM REVISED **

PLUG AND ABANDONMENT PROCEDURE

April 27, 2017

Moncrief Federal #1

West Kutz Pictured Cliffs
1450 FNL and 1190' FEL, Section 22, T29N, R12W
San Juan County, New Mexico / API 30-045-08084
Lat: N / Lat: W

Lat: N _____/ Lat: W _____ All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing Note: wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield. 1. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP. (NOTE: Need additional 200' +/- workstring). Packer: Yes ____, No X__, Unknown___, Type _____. If this well has rods or a packer, then modify the work sequence in step #2 as appropriate. 3. Plug #1 (Pictured Cliffs interval and Fruitland tops, 2000' - 1608'): TOH with rods and pump. TOH and inspect tubing. TIH with tubing and tag existing CIBP @ 2000'. Pressure test tubing to


- 3. Plug #1 (Pictured Cliffs interval and Fruitland tops, 2000' 1608'): TOH with rods and pump. TOH and inspect tubing. TIH with tubing and tag existing CIBP @ 2000'. Pressure test tubing to 1000#. Mix and pump 60 sxs Class B cement (100% excess due to open perforations) above existing CIBP to cover the PC interval and Fruitland top. PUH and WOC. TI H and tag cement. Pressure test casing to 800#. If casing does not test then spot or tag subsequent plugs as appropriate. If cement tags low or casing does not pressure test then spot subsequent plugs as necessary.
- 4. Plug #2 (Fruitland top, 1358' 1258'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Fruitland top. PUH.
- 5. Plug #3 (Kirtland top and 8.625" casing shoe, 520' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 45 sxs cement and spot a balanced plug from 520' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A
 marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.

Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

Moncrief Federal 1 **Pictured Cliffs** API # 30-04508084 T-29N, R-12-W, Sec. 22 San Juan County, New Mexico

Formation Tops Kirtland 470 470 Fruitland 1308 PC 1660' 3148' PT. Lookout Manco Shale 4380 6140 Dakota

CIBP Set @ 2000'



TD: 6330'

G R 5640'

12-1/4" hole to 349 8-5/8", 24# @ 349' w/ 300 sx

Plug #3: 520' - 0' Class B cement, 45 sxs

Plug #2: 1358' - 1258' Class B cement, 12 sxs

Plug #1: 2000' - 1608' Class B cement, 60 sxs

PC Perforations 1658'-1707' w/ 3 jspf

1/1991 - Squeezed off casing leak between 2781

CIBP @ 3250'

Tubing cut at 3500' Tag cement in tubing at 4600' Pump 50 sx Class G, 15.8 ppg cement down tubi Followed with 8 bbls 15.8 ppg cement behind wi

1/1991 added perforation frac'd with 34,300 lbs 6142-6150' in 12,700 gals 30# cro 6212-6231 6236'-6245' Hole size: 7-7/8" 4- 1/2", 11.6# J-55 @ 6310' cmt w/ 250 sx

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Monrief Federal #1.

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: aelmadani@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

OIL CONS. DIV DIST. 3

JUN 06 2017