Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM AP	PROVED
OMB NO.	1004-0137
Expires: Janu	ary 31, 201

	SUI	NDF	Y N	OTIC	ES	AND	REF	o	RTS	ON	WELLS	
Do	not	use	this	form	for	propo	sals	to	drill	or to	re-enter	an

5. Lease Serial No. NMNM101058

SUNDRY	NIVINIVITOTOS						
Do not use thi abandoned we	6. If Indian, Allottee or	Tribe Name					
SUBMIT IN	7. If Unit or CA/Agreer	ment, Name and/or No.					
Type of Well	8. Well Name and No. JUNIPER 9 44						
Name of Operator     COLEMAN OIL & GAS INCOR		9. API Well No. 30-045-31859-00	)-S1				
3a. Address FARMINGTON, NM 87499		10. Field and Pool or Ex BASIN FRUITLA	xploratory Area ND COAL				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	Fx: 505-327	0.20		11. County or Parish, State		
Sec 9 T24N R10W SESE 120 36.324129 N Lat, 107.895576					SAN JUAN COU	NTY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION			TYPE OF	ACTION			
Notice of Intent	☐ Acidize	☐ Deep	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	olete	□ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	□ Tempor	arily Abandon		
BP	□ Convert to Injection	Plug	Back	☐ Water D	Disposal		
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  Coleman Oil & Gas proposes to P&A this well per the attached procedure. Reclamation Plan will be submitted following onsite. Onsite scheduled for Friday May 5, 2017.  MAY 2 2 2017  BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEF AND ACTION DOES NOT RELIEVE THE LESSEF AND ACTION REQUIRED FOR OPERATIONS AUTHORIZATION REQUIRED FOR OPERATIONS AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS  ON FEDERAL AND INDIAN LANDS							
	Electronic Submission #3 For COLEMAN OIL & ted to AFMSS for procession	GAS INCORP	ORATED, sent to GADIR ELMADAN	the Farming I on 05/17/20	gton		
Name (Printed/Typed) MICHAEL	T HANSON		Title ENGINE	ER			
Signature (Electronic S	Submission)		Date 05/04/20	)17			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	SE		
Approved By ABDELGADIR ELM. Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant	d. Approval of this notice does nitable title to those rights in the	TitlePETROLE		EER	Date 05/17/2017		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a c	crime for any pe to any matter wi	rson knowingly and		ke to any department or a	gency of the United	

NMOCD PY

(Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

#### PLUG & ABANDONMENT PROCEDURE

March 1, 2017

### Juniper 9#44

Basin Fruitland Coal 1205' FSL and 980' FEL, Section 9, T-24-N, R-10-W San Juan County, New Mexico, API 30-045-31859 Lat: 36.324167 / Long: 107.895000


Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- This project requires the Operator to obtain an approved NMOCD C-144 CLEZ Closed-Loop System
  Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well.
- Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit.
  Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead
  pressures. NU relief line and blow down well. LD Down Rods and Pump. Kill well with water as
  necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP.
  Function test BOP. TOH and tally Tbg.

3.	Rods:	Yes	X	, No		Unknown	;				
	Tubing:	Yes	Χ,	No_	,	Unknown	,	Size	2.875"	, Length 1728'	;
	Packer:	Yes	,	No	Χ,	Unknown		, Type	1		_
	If this w	ell has	s rods or	a pa	cker, t	hen modify	the wor	rk seq	uence in	step #2 as appr	opriate.

- 4. Plug #1 (Pictured Cliffs interval and Fruitland top, 1542' 1297'): Round trip 5.5" casing scraper or 1592', or as deep as possible. TIH and set 5.5" cement retainer at 1542'. Pressure test tubing to 1000 PSI. Load the casing with water and circulate the well clean. Pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 34 sxs above CR to isolate the PC interval and cover the Fruitland top. PUH.
- 5. Plug #2 (Kirtland and Ojo Alamo tops, 972' 742'): Mix 32 sxs cement and spot a balanced plug inside the casing to cover the Kirtland and Ojo Alamo Formaton tops. PUH.
- 6. Plug #3 (Surface, 180' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 21 sxs cement and spot a balanced plug from 180' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 180' and the annulus from the squeeze holes to surface. Shut in well and WOC.
- 7. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per BLM stipulations.

## COLEMAN OIL GAS, INC. JUNIPER 9#44



## Juniper 9 #44

## Proposed P&A

**Basin Fruitland Coal** 

1205' FSL & 980' FEL, Section 9, T-24-N, R-10-W, San Juan County, NM

Lat: 36.332222 / Long: 107.895000 / API #30-045-31859

Spud: 12/4/03 Today's Date: 13/1/17 Completed: 4/12/04 Elevation: 6921' GR

Nacimiento (Surface)

12.25" hole

8.625", 24#, J-55 Csg set @ 129.68' Cmt with 90 sxs (Circulated to Surface)

> Plug #3: 180' - 0' Class B cement, 21 sxs

Ojo Alamo @ 792'

Kirtland: 922'

Fruitland: 1357'

Pictured Cliffs: 1612'

Plug #2: 972'- 742' Class B cement, 32 sxs

Plug #1: 1542' - 1297' Class B Cement, 34 sxs:

Set CR @ 1542'

Fruitland Coal Perforations: 1592' - 1606'

5.5" 15.5#, J-55 Casing set @ 1728.55' Cement with 185 sxs Lite Tailed with 90 sxs G Poz 50/50 (Circulated to Surface)

7.875" hole

TD 1735' **PBTD 1705**'

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Juniper Com 9 #44.

### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
  - a) Set Plug #1 (1542'-1244') ft. To cover the top of Fruitland top. BLM picks top of Fruitland at 1294 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.