ONITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICE
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease	Serial	No.
----------	--------	-----

6. If Indian, Allottee or Tribe Name

SF-078267-A

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3	(APD) for such proposals.		
	SUBMIT IN TRIPLICATE - Other instructions on page 2.  7. If Unit of CA/Agreement, Name and/or No.  Huerfano Unit		
1. Type of Well		Huerfano Unit	
Oil Well X Gas Well Othe	r	8. Well Name and No.	
		Huerfano Unit 110E	
2. Name of Operator		9. API Well No.	
Burlington Resources Oil & Ga	Burlington Resources Oil & Gas Company LP		
3a. Address	3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area	
PO Box 4289, Farmington, NM 87499 (505) 326-9700		Basin Dakota	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		11. Country or Parish, State	
Surface Unit H (SENE), 1840' FNL & 1160' FEL, Sec. 3, T26N, R10W		San Juan , New Mexico	
12. CHECK THE APPROPRIATE BOX(E	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA		
TYPE OF SURMISSION	TYPE OF ACTION		

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	X Other MIT
GK	Change Plans	Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
12 D - 7 D - 1 O 1 1 1 O 1 O 1 O 1 O 1 O 1 O 1 O 1				

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Burlington Resources requests permission to perform a MIT on the subject well per the attached procedure and wellbore schematic.

> OIL CONS. DIV DIST. 3 MAY 1 1 2017

Notify NMOCD 24 hrs prior to beginning operations

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Dollie L. Busse	Title	e Staff Regulatory Technician		
Signature Allie Busse	Date	6/3/2017		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by William Tambe Kan		Title Petroleum Engineer Date 5/5/2017		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or	certify			
that the applicant holds legal or equitable title to those rights in the subject lease which w	vould	Office (= E)		
entitle the applicant to conduct operations thereon.		FFU		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## ConocoPhillips HUERFANO UNIT 110E Expense - MIT

Lat 36° 31' 9.48" N

Long 107° 52' 40.368" W

## **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations.
- 2. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure.
- 4. Load casing with 2 % KCl water & corrosion inhibitor, as necessary. Perform MIT (Mechanical Integrity Test) above the bridge plug at 6748' to 560 psig for 30 minutes on a 2 hour chart with 1000 lb. spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.

