

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report



Name of Company: BP	Contact: Steve Moskal	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497	
Facility Name: Atlantic B LS 003C	Facility Type: Natural gas well	
Surface Owner: Federal	Mineral Owner: Federal	API No. 3004532178

**LOCATION OF RELEASE**

Unit Letter O	Section 4	Township 30N	Range 10W	Feet from the 720	North/South Line South	Feet from the 2,445	East/West Line East	County: San Juan
------------------	--------------	-----------------	--------------	----------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.83538° Longitude -107.88766°

**NATURE OF RELEASE**

Type of Release: hydrocarbons	Volume of Release: unknown	Volume Recovered: none
Source of Release: Historic workover pit	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 6/21/17 @ 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* During final reclamation of the P&A well site, a liner was encountered which contained hydrocarbon contents. Further research indicates that the liner is likely the result of an in place closure of a workover pit in 2007.		
Describe Area Affected and Cleanup Action Taken.* The hydrocarbon impacts and contents will be removed and fully delineated via excavation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>6/27/2017</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 21, 2017 Phone: 505-326-9497	<u>Sample Area 8015/8021</u> <u>Include M20 Range</u> <u>NVF1717839189</u>	

\* Attach Additional Sheets If Necessary

OIL CONS. DIV DIST. 3  
JUN 22 2017