Form 3160-5 (June 2015)

TED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 201

5.	Lease Serial No.	
	NMNM12027	


SUNDRY Do not use thi	5. Lease Serial No. NMNM12027									
abandoned wel	6. If Indian, Allottee or Tribe Name									
SUBMIT IN T		7. If Unit or CA/Agreement, Name and/or No.								
Type of Well ☐ Oil Well ☐ Gas Well ☑ Oth		8. Well Name and No. CHACO PLANT 90S								
Name of Operator DUGAN PRODUCTION COR	Contact:	ALIPH REEN a@duganprodu	A ction.com		9. API Well No. 30-045-33782-00-S1					
3a. Address 709 E MURRAY DRIVE FARMINGTON, NM 87499	3b. Phone No Ph: 505-32	(include area code) 5-1821		10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL						
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	11. County or Parish, State							
Sec 17 T26N R12W SESE 12 36.484523 N Lat, 108.128158				SAN JUAN COUNTY, NM						
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OF	NOTICE,	REPORT, OR OTH	ER DATA				
TYPE OF SUBMISSION			TYPE OF	ACTION						
Notice of Intent	☐ Acidize	□ Deep	pen	☐ Product	ion (Start/Resume)	☐ Water Shut	-Off			
_	☐ Alter Casing	□ Hyd	☐ Hydraulic Fracturing ☐ Recla		ation	☐ Well Integr	ity			
☐ Subsequent Report	☐ Casing Repair	□ New	☐ New Construction ☐ Re		olete	☐ Other				
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon		□ Tempor	arily Abandon					
BP	☐ Convert to Injection	Plug	☐ Plug Back ☐ Water		Disposal					
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.										
Dugan Production Corp. plans to plug and abandon the well as per the following procedure: 1) Set CR @ 881'. Pressure test casing. 2) Spot Plug I above retainer @ 660'-881 w/32 sks (37 cu ft) Class G neat - 15.6#/gal, 1.15 cu ft/k - Fruitland, Plug I: 660'-881'. 3) Spot Plug II below surface casing shoe @ 175' w/27 sks (30 cu ft) Class G cement w/2% CaCl2 - 15.6#/gal, 1.15 cu ft/sk - Surface, Plug II: 0-175'. 4) Tag TOC at surface. Fill cement in case needed. Cut wellhead. 5) Install dry hole marker. Cut anchors. Clean location. BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER										
SEE ATTACH	ED FOR		AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS							
CONDITIONS OF APPROVAL Notify NMOCD 24 hrs prior to beginning										
14. I hereby certify that the foregoing is	true and correct. Electronic Submission # For DUGAN PRODU ted to AFMSS for process	CTION CORP	d by the BLM Well DRATION, sent to	the Farming	aton					
Name (Printed/Typed) ALIPH RE	•		Title AGENT, ENGINEERING SUPERVISOR							
Signature (Electronic S	Submission)		Date 08/03/20	17						
2.g.aaa.e (Elevione E	THIS SPACE FO	OR FEDERA			SE					
							.1			
Approved By ABDELGADIR ELM	ANDANI	TitlePETROLEU	JM ENGINE	EER	Date 08/1	4/2017				
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the	Office Farmingto	on							
Tid- 10 H C C C 1001 - 1 Tid- 42	11000 1 1010 1 1		1 : 1 1	:11C 11 .	1	Col III is	1			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCDA

Current Wellbore Schematic

Chacoplant 90S 30-045-33782 1285' FSL & 660' FEL S17 T26N R12W



8 5/8" J-55 24# casing @ 125'. Cemented with 80 sks Type 5w/ 2% CaCl2. Hole size 12-1/4"

Cement production casing w/ $231\ cu.ft.$ 5 bbl Cement Circulated to surface.

5 ½" 15.5 # casing @ 1313'. Hole size: 7"


Set CR @ 881'. Set Inside Plug with 32 sks (37 cu.ft) @ 660'-881' Class G cement.(660'-881') (Plug I, Fruitland)

Fruitland Coal Perforated @ 931' - 1128'

PBTD @ 1268'

Planned P & A Schematic

Chaco Plant 90S 30-045-33782 1285' FSL & 660' FEL S17 T26N R12W



 $8\,5/8"$ J-55 24# casing @ 125'. Cemented with 80sks Type 5 w/ 2% CaCl2. Hole size 12-1/4"

Spot plug to surface w/ 27 sks Class G Cement (30 cu.ft) (Plug II, Surface -175')

Cement production casing $w/231\ cu.ft.\ 5\ bbl$ Cement circulated to surface.

Set CR @ 881'. Set Inside Plug with 32.sks (37 cu.ft) @ 660'-881' Class G cement(660'-881') (Plug I, Fruitland)

5 1/2" 15.5 # casing @ 1313'. Hole size: 7"

Fruitland Coal Perforated @ 931' - 1128'

PBTD @ 1268'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Chaco Plant # 90s

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.