

Submitt 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-045-08080
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Martin
8. Well Number 1
9. OGRID Number
10. Pool name or Wildcat Aztec Fruitland Sand
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5482 GL

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
RIGGS OIL & GAS

3. Address of Operator
P. O. BOX 711, FARMINGTON, NM 87499

4. Well Location
 Unit Letter 1470 feet from the NORTH line and 1180 feet from the EAST line
 Section 24 Township 28-N Range 11-W NMPM County SAN JUAN

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	Approved for plugging of wellbore only. Liability under bond is retained pending Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web page under forms www.emnrd.state.us/ocd <input type="checkbox"/> date

13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.

WELL WAS PLUGGED OCTOBER 21, 2016. REFER TO ATTACHED PLUS REPORT OF PLUGGING. SURFACE WAS REMEATED WITH ABOVE GROUND DRY HOLE MARKER PER REGULATION 19.15/25.10.

**File sundays in a timely manner*

LAND OWNER HAS REQUESTED THE REMOVAL OF THE ABOVE GROUND MARKER AND TO INSTALL A BELOW GROUND MARKER FOR AGRICULTURAL PURPOSES PER REGULATION 19.15.25.10.C

** File a C-102 using a Current Survey and photos of the marker in place and with the C-103 wellsite release form*

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Thomas J. Smith TITLE AGENT DATE 12/26/2017

Type or print name THOMAS J. SMITH E-mail address: tjsmith1940@gmail.com PHONE: 505-320-2380

APPROVED BY: Bob Bell TITLE AV DATE 1/2/18

Conditions of Approval (if any):

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
Farmington, New Mexico 87499
505-325-2627 *fax: 505-325-1211

Riggs Oil & Gas
Martin #1

October 21, 2016
Page 1 of 2

1470' FNL and 1180' FEL, Section 24, T-29-N, R-11-W
San Juan County, NM
Lease Number: FEE
API #30-045-08080

Plug and Abandonment Report
Notified NMOCD and BLM and Jicarilla BLM on 10/17/16

Plug and Abandonment Summary:

- Plug #1** with 8 sxs (9.44 cf) Class B cement from 1536' to 1475' to cover the Pictured Cliffs and Fruitland tops. Tag TOC at 1536'.
- Plug #2** with CR at 1474' spot 15 sxs (17.7 cf) Class B cement from 1474' to 1281' to cover the Fruitland top. Tag TOC at 1265'.
- Plug #3** with 34 sxs (40.12 cf) Class B cement with 2% CaCl from 792' to 353' to cover the Kirtland and Ojo Alamo tops.
- Plug #4** with squeeze holes at 346' spot 37 sxs (43.66 cf) Class B cement from 164' to surface. Tag TOC down 18' in 4-1/2" casing.
- Plug #5** with 20 sxs Class B cement top off casings and install P&A marker with coordinates Lat 36.71448 / Long -107.93811.

Plugging Work Details:

- 10/18/16 Road rig and equipment to location. Spot in and RU. Check well pressures: tubing, casing and bradenhead 50 PSI. Blow well down, tubing had 20 PSI. ND wellhead. Pump 20 bbls of water down tubing to kill well. PU on tubing pulled up to 45,000# to get slips out of 6-5/8" tubing head. Strip off 6-5/8" cap and wellhead, strip on A-Plus 4-1/2" x 8-5/8" tubing head. 8-5/8" companion flange and BOP function test pipe rams. PU 1 A-Plus 2-3/8" jnt (15 jnts A-Plus 2-3/8" workstring total) tubing taking weight. PU or TIH finally went to string weight 7000 to 8000# turned tubing to right and released unknown packer. POH and tally 48 jnts, 1 AD packer, 1 upside down 4' sub 48 jnts 2-3/8" EUE total tally 1489'. TIH and tag at 1536'. Note: Tom Smith, E.A. Riggs and Charlie Perrin, NMOCD approved procedure change. Spot plug #1 with calculated TOC at 1475'. SI well. WOC overnight. SDFD.
- 10/19/16 Travel to location. Held safety meeting. Check well pressures: tubing, casing and bradenhead on vacuum. TIH and tag TOC at 1536'. PU 4-1/2" DHS CR and set at 1474'. Pressure test tubing to 1000 PSI, OK. Circulate well. Attempt to pressure test casing, bradenhead started circulating out of 1" x 1/4" valve, no test. RU A-Plus wireline. Ran CBL from 1474' to surface. Wait on orders. Spot plug #2 with calculated TOC at 1281'. PUH to 310'. SI well and SDFD.
- 10/20/16 Travel to location. Held safety meeting. Open up well; no pressures. RU relief lines. TIH and tag TOC at 1265'. Spot plug #3 with calculated TOC at 353'. TOH and LD all tubing. Dig out the bradenhead. Write Hot Work Permit. Install 2" nipple in bradenhead for circulating. WOC. TIH to 462', no tag. Reverse circulate green cement. WOC. TOH and LD all tubing. Perforate 3 HSC squeeze holes at 346'. WOC. Tag TOC at 346'. Establish rate of 2 bpm at 250 PSI. Spot plug #4 with TOC at surface. TOH and LD all tubing. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Riggs Oil & Gas
Martin #1

October 21, 2016
Page 2 of 2

Plugging Work Details (continued):

10/21/16 Travel to location. Held safety meeting. Open up well; no pressures. RU relief lines. Tag cement down 18' in 4-1/2" casing. ND BOP. Dig out wellhead. RU cut off saw. Cut off wellhead. Found cement at surface in 8-5/8" x 4-1/2" annulus and down 9' in 4-1/2" casing below ground level. Spot plug #5 top off casings and install P&A marker with coordinates Lat 36.71448 / Long -107.93811. RD and MOL.

Tom Smith, Riggs Oil & Gas representative, was on location.
Jonathan Kelly, NMOCD representative, was on location.