Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137

Expires. January 51, 2016						
5	5. Lease Serial No. NMNM012202					
6	5. If Indian, Allottee or Tribe Name					

SUNDRY Do not use the		NMNM012202				
abandoned we	6. If Indian, Allotted	6. If Indian, Allottee or Tribe Name				
SUBMIT IN	7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No.				
Type of Well     Oil Well		8. Well Name and No. BOLACK B LS 3				
2. Name of Operator BP AMERICA PRODUCTION	Contact: TO	9. API Well No. 30-045-06946	9. API Well No. 30-045-06946-00-C1			
3a. Address 501 WESTLAKE PARK BLVD HOUSTON, TX 77079		Phone No. (include area code) 1: 281.892.5369	10. Field and Pool of MultipleSee	Field and Pool or Exploratory Area     Multiple—See Attached		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11. County or Paris	h, State		
Sec 33 T28N R8W SESW 079 36.613190 N Lat, 107.687119	W/Lon	mended	SAN JUAN COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, REPORT, OR O	THER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	□ Water Shut-Off		
Subsequent Report     ■     Subsequent Report     Subse	☐ Alter Casing ☐ Casing Repair	<ul><li>☐ Hydraulic Fracturing</li><li>☐ New Construction</li></ul>	☐ Reclamation ☐ Recomplete	☐ Well Integrity ☐ Other		
☐ Final Abandonment Notice	Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	☐ Other		
(2)	Convert to Injection	☑ Plug Back	☐ Water Disposal			
13. Describe Proposed or Completed Op. If the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final Al determined that the site is ready for f  BP plugged the Picture Cliffs t updated plug back summary r	ally or recomplete horizontally, give rk will be performed or provide the E I operations. If the operation results bandonment Notices must be filed on inal inspection.	subsurface locations and measuraged No. on file with BLM/BIA in a multiple completion or recoulty after all requirements, including anuary 2015. Please see to	red and true vertical depths of all per Required subsequent reports must impletion in a new interval, a Form 3 ng reclamation, have been complete the attached	tinent markers and zones. be filed within 30 days 160-4 must be filed once		
			U	EL 10 2011		
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #3791 For BP AMERICA PRODU itted to AFMSS for processing	95 verified by the BLM Well JCTION COMPANY, sent to by WILLIAM TAMBEKOU or	Information System the Farmington 12/13/2017 (18WMT0189SE)			
Name (Printed/Typed) TOYA CO			ATORY ANALYST			
Signature (Electronic S	Submission)	Date 06/19/20	017			
	THIS SPACE FOR F	EDERAL OR STATE (	OFFICE USE			
Approved By ACCEPT	ED	WILLIAM T TitlePETROLE	AMBEKOU JM ENGINEER	Date 12/13/2017		
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to conduct the conductive to conduct the conductive that the applicant to conduct the conductive that	uitable title to those rights in the subj		on			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



## Plug Back Operations for the Bolack B LS 3 - January 2015

## January 2015

01/15/2015- JSEA, SAFETY MEETING, MIRU START UP RIG AND EQUIPMENT, FINISH MOVING IN ON LOC, SPOTTED RIG AND EQUIP, RIG UP WO RIG. NU RIG PUMP AND 3" FLOW LINECHECK WH PRESSURES- PASSED, BLEW WELL PRESSURE DOWN, ND TREE, NU BOP, PRESSURE TEST, POOH WITH 2.375 PROD TBG, SECURE WEI

01/16/2015- JSEA, SAFETY MEETING, START UP RIG AND EQUIPMENT, PERFORM RIG INSPECTIONS, CHECK WH PRESSURES-PASSED, BLEW WELL PRESSURE DOWN, RIH WITH TANDAM CSG SCRAPERS TO 2350', POOH, RIH WITH RBP TO 2355', POOH, RIH WITH PKR @ 2270', FILL AND PRESSURE TEST RBP- 250/1200 PSI, 5 MINUTES-GOOD TEST, SHUT DOWN SECURE WELL

01/19/2015- JSEA, SAFETY MEETING, START UP RIG AND EQUIPMENT, PERFORM RIG INSPECTIONS, CHECK WH PRESSURES- PASSED, SET PKR 2260', FILL AND PRESSURE TEST BACKSIDE-PRESSURE TEST TO 500 PSI-PASSED, NU BAKER HUGHES, PUMP 16BBLS FRESH WATER PUMP ACID 15%HCL PUMP 12 BBLS AT 1.5 BPM WITH 0 PSI, SWITCH TO WATER PUMP 4 BBLS, WAIT 10 MINUTES, PUMP 5 BBLS H2O, WAIT 10 MINUTES, PUMP 7 BBLS H2O, SWITCH TO CEMENT, PUMP 16 BBLS OF H20 SPACER, PUMP 19 BBLS OF CLASS G CEMENT YIELD 1.15 15.6 PPG, SWITCH TO H2O, PUMP 9 BBLS DISPLACEMENT, PRESSURE TEST CEMENT TO 500 PSI HOLD 5 MINS-PASSED, SQUEEZE OFF PC PERFORATIONS BLEED OFF, ND BAKER HUGHES, SHUT DOWN SECURE WELL.

01/20/2015- JSEA, SAFETY MEETING, START UP RIG AND EQUIPMENT, PERFORM RIG INSPECTIONS, CHECK WH PRESSURES- PASSED, RELEASE PKR, POOH, RIH WITH 6-3/4 BLADE BIT, TAG CEMENT TOP, DRILL OUT CEMENT TO 2201', SECURE WELL

01/21/2015- JSEA, SAFETY MEETING, START UP RIG AND EQUIPMENT, PERFORM RIG INSPECTIONS, CHECK WH PRESSURES-PASSED, FINISH DRILL OUT CMT TO 2201', PRESSURE TEST SQUEEZE TO 600 PSI-PASSED POOH LAY DOWN BIT/BIT SUB, PICK UP RETRIEVING TOOL, RIH RELEASE RBP, POOH, SECURE WELL

01/22/2015- JSEA, SAFETY MEETING, START UP RIG AND EQUIPMENT, PERFORM RIG INSPECTIONS, CHECK WH PRESSURES-PASSED, BLEW WELL PRESSURE DOWN, POOH, LAY DOWN RBP, MAKE UP BHA, RIH WITH 2 3/8" J-55 4.7# PROD TBG TO 4431', ND BOP, NU TREE, NU FLOW LINES, RIG DOWN WO RIG AND EQUIPMENT, SECURE WELL, MOVE OFF LOCATION