#### Form 3160-5 (August 2007)

### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

NMSF-078642

abandoned well. Use Form 3160-3 (APD) for such proposals.	SUNDRY NOTICES AND REPORTS ON WELls reau of Lan  Do not use this form for proposals to drill or to re-enter an	Field Office 6. If Indian, Affottee or Tribe Name Management
and it do it is a first of the state of the	abandoned well. Use Form 3160-3 (APD) for such proposals.	

	s.	
tructions on page 2.	7. If Unit of CA/Agreement, N	Jame and/or No.
	8. Well Name and No.  San Jua	an 29-5 Unit 17C
	9. API Well No.	
ny	30-0	039-29465
3b. Phone No. (include area code	e) 10. Field and Pool or Explorate	ory Area
505-599-3400	Gobenador P	C/Blanco Mesaverde
EL, Sec. 5, T29N, R05W	11. Country or Parish, State Rio Arriba	, New Mexico
TO INDICATE NATURE O	F NOTICE, REPORT OR OTH	ER DATA
TYPE O	F ACTION	
Deepen	Production (Start/Resume)	Water Shut-Off
Fracture Treat	Reclamation	Well Integrity
New Construction	X Recomplete	Other
Plug and Abandon	Temporarily Abandon	
Plug Back	Water Disposal	
ils, including estimated starting da	ate of any proposed work and approxim	nate duration thereof.
Sond No. on file with BLM/BIA. I	Required subsequent reports must be fil	led within 30 days
	pletion in a new interval, a Form 3160-	
	ny 3b. Phone No. (include area code 505-599-3400  EL, Sec. 5, T29N, R05W  TO INDICATE NATURE O  TYPE O  Deepen Fracture Treat New Construction Plug and Abandon Plug Back ils, including estimated starting days subsurface locations and measured	PD) for such proposals.  Fructions on page 2.  7. If Unit of CA/Agreement, No. 18. Well Name and No. 19. API Well No. 19. API Well No. 19. API Well No. 19. Field and Pool or Explorate 19. Field and Pool or Explorate 19. Fracture Treat 19. Production (Start/Resume) 19. Plug and Abandon 19. Temporarily Abandon 19. Temp

Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle the existing Mesaverde with the Pictured Cliffs. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved before the work proceeds.

OIL CONS. DIV DIST. 3

Notify NMOCD 24 hrs prior to beginning operations

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

	,			
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Etta Trujillo	Title	Operations/Regulatory	Гесhnician - Sr.	
Signature EAAC Factor	Date	1-24-18		
THIS SPACE FOR FED	ERAL O	R STATE OFFICE USE		
Approved by William Tambekou		Title Tetroleum	Engineer	Date 1/25/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant or	certify	_		
that the applicant holds legal or equitable title to those rights in the subject lease which	would	Office FFO		
entitle the applicant to conduct operations thereon.		.,,		
				0.1 ** 1. 1.0.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**District 1** 

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II** 

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV** 

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.

**Santa Fe, NM 87505** 

Form C-102 August 1, 2011

Permit 247486

### WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-29465	2. Pool Code 77440	3. Pool Name GOBERNADOR PICTURED CLIFFS (GAS)
4. Property Code	5. Property Name San Juan 29-5 Unit	6. Well No. 017C
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6573

#### 10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
1	5	29N	05W		2165	s	1205	E	RIO ARRIBA

#### 11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A	<del>.00</del> E/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

## NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

 The second secon	
Control of the second of the s	
*	

#### **OPERATOR CERTIFICATION**

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations / Regulatory Tech Sr

Date: 1/24/2018

#### **SURVEYOR CERTIFICATION**

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Jason C. Edwards

Date of Survey:

9/18/2004

Certificate Number:

15269



# HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 17C PICTURED CLIFFS RECOMPLETION SUNDRY

#### JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 5,758'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 3,700' to isolate the Dakota. Note: TOC at 2,970' by CBL.
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Pictured Cliffs in a single stage (Top Perforation @ 3,516'; Bottom Perforation @ 3,598').
- 7. Isolate frac stage with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 10. Clean out to Mesa Verde isolation plug and, when water and sand rates are acceptable, flow test the Pictured Cliffs.
- 11. Drill out Mesa Verde isolation plug and cleanout to PBTD of 6,044'. TOOH.
- 12. TIH and land production tubing. Get a commingled Mesa Verde/Pictured Cliffs flow rate.



# HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 17C PICTURED CLIFFS RECOMPLETION SUNDRY

