Form 3160-5 (June 2015)

☐ Final Abandonment Notice

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OMB NO. 1004-0137 Expires: January 31, 2018

FORM APPROVED

#### SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

5. Lease Serial No. NMSF078051

abandoned we	6.	If Indian, Allottee o	r Tribe Name		
SUBMIT IN	7.	If Unit or CA/Agree	ement, Name and/or No.		
Type of Well		Well Name and No. NEIL A 7A			
Name of Operator     BP AMERICA PRODUCTION		API Well No. <mark>30-045-22463-0</mark>	0-C1		
3a. Address 501 WESTLAKE PARK BLVD HOUSTON, TX 77079	,	Field and Pool or I BLANCO MESA BLANCO PICTU	(VERDE		
4. Location of Well (Footage, Sec., T	11.	County or Parish,	State		
Sec 33 T32N R11W NWNW 0 36.946290 N Lat, 107.998170		SAN JUAN COL	JNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	F NOTICE, RE	PORT, OR OTH	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent     □ Subsequent Report	☐ Acidize ☐ Alter Casing ☑ Casing Repair	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction	☐ Production (☐ Reclamation☐ Recomplete	1	☐ Water Shut-Off ☐ Well Integrity ☐ Other
	_ 5 1				

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

☐ Plug Back

☐ Plug and Abandon

Please see the attached procedure to remediate the BH pressure on the subject well.

□ Change Plans

☐ Convert to Injection

OIL COMS. DIV DIST. 3

FEB 01 2018

☐ Temporarily Abandon

■ Water Disposal

Notify NMOCD 24 hrs prior to beginning operations

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #402388 verified by the BLM Well Information System  For BP AMERICA PRODUCTION COMPANY, sent to the Farmington  Committed to AFMSS for processing by WILLIAM TAMBEKOU on 01/29/2018 (18WMT0330SE)					
Name (Printed/Typed)	TOYA COLVIN	Title	REGULATORY ANALYST		
			,	,	
Signature	(Electronic Submission)	Date .	01/26/2018		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By WILLIAM TAMBEKOU		TitleP	ETROLEUM ENGINEER	Date 01/29/2018	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Farmington		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

#### Neil A 007A

API # 30-045-22463-00 Location: D SEC. 33, T32N, R11W San Juan County, New Mexico

## Reason/Background for Job

The Neil A 007A was completed in the Pictured Cliffs and Mesa Verde in 1977. The two formations were downhole commingled in 2002. In 2017, Bradenhead testing revealed potential gas communication between the production casing and Bradenhead (based on gas composition). BP proposes the following procedure to determine the source of the pressure and remediate the issue.

### <u>Procedure</u>

- 1. Test WH seals to ensure no leak between production casing and Bradenhead
- 2. ND WH; NU BOP
- 3. Pull tubina
- 4. Set RBP at 2865' and load casing with 2% KCl water
- 5. Test to 500 psi for 30 minutes
  - 5.1. If test passes, go to Step #6
  - 5.2. If test fails, go to Step #7
- 6. Blow down the Bradenhead until there is no blow (0 psig)
  - 6.1. If successful, contact NMOCD to report results, then proceed to Step #8
    - A. We will monitor BH pressure for 6 months to ensure no active communication
  - 6.2. If Bradenhead will not blow down, proceed to Step #7
- 7. Run CBL from 2865' to surface
  - 7.1. Execute squeeze plan as appropriate (TBD based on injection rates, etc.)
- 8. Retrieve and pull RBP
- 9. Tag for fill and clean out if necessary
- 10. Land tubing
- 11. ND BOP: NU WH
- 12. Return the well to production

## **Current WBD**



Neil A 007A PC/MV API # 3004522463 Unit D - Sec. 33 - T32N - R11W San Juan, NM

Formation Tops	Depth
Pictured Cliffs	2877
Mesa Verde	4408
Point Lookout	5160

# Pictured Cliffs Perforations 2880' - 2900' 16 spz 2908' - 2914' 16 spz 2924' - 2944' 16 spz Frac'd w/ 54k# 20/40 & 54k gal wtr

Mesa Verde Perl	forations
4461' - 4466'	16 spz
4503' - 4510'	16 spz
4546' - 4558'	16 spz
4641' - 4662'	16 spz
4662' - 4682'	16 spz
4725' - 4739'	16 spz
Frac'd w/ 88k# 20	0/40 & 88k gal wtr
4833' - 4843'	16 spz
4853' - 4876'	16 spz
4906' - 4918'	16 spz
4951' - 4959'	16 spz
4969' - 4976'	16 spz
4969' - 4976' 5013' - 5029' 5039' - 5055'	16 spz
5039' - 5055'	16 spz
5065' - 5073'	16 spz
Frac'd w/ 82k# 20	0/40 & 82k gal wtr
5162' - 5185'	16 spz
5195' - 5199'	16 spz
5225' - 5237'	16 spz
5247' - 5259'	16 spz
5273' - 5283'	. 16 spz
5293' - 5311'	16 spz
Frac'd w/ 90k# 20	0/40 & 90k gal wtr
5379' - 5385'	16 spz
5417' - 5425'	16 spz
5435' - 5447'	16 spz
5479' - 5491'	16 spz
5504' - 5511'	16 spz
5521' - 5527'	16 spz
5539' - 5548'	16 spz
5559' - 5571'	16 spz
5590' - 5601'	16 spz
Frac'd w/ 28k# 20	0/40 & 30k gal wtr

12' KB GL: 6192'

