Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137

1-1/20-9	A	00
1- 1-0 1-1	- 5	173
· made		

	Expires:	July	31,	2010	
0 '111					١

				NMS	SF079049B	
SUN	IDRY NOTICES AND REPO	offfdedian, Allottee or Tribe N	ame			
Do not us	e this form for proposals	to drill orto re-enter an	Mana	agement		
	well. Use Form 3160-3 (A		5.			
	IBMIT IN TRIPLICATE - Other ins	tructions on page 2.		7. If Unit of CA/Agreement, Na	ame and/or No.	
1. Type of Well						
Oil Well	X Gas Well Other			8. Well Name and No.	n 28-6 Unit 167	
2. Name of Operator				9. API Well No.	11 20-0 OTHE 107	
	Hilcorp Energy Compa	nny		30-0	39-20483	
3a. Address		3b. Phone No. (include area code	e)	10. Field and Pool or Exploratory Area		
PO Box 4700, Farmingto		505-599-3400		Blanco Mesa	verde/Basin Dakota	
4. Location of Well (Footage, Sec., T.,F				11. Country or Parish, State		
Surface Unit K (N	IESW) 1750'FSL & 1500' F	WL, Sec. 4, T27N, R06W	/	Rio Arriba ,	New Mexico	
12. CHECK T	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOT	ICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE O	F AC	TION		
X Notice of Intent	Acidize	Deepen	Pr	roduction (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	R	eclamation	Well Integrity	
Subsequent Report 0	Casing Repair	New Construction	X R	ecomplete	Other	
_ BY	Change Plans	Plug and Abandon	Te	emporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	o w	ater Disposal		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle with the existing Dakota. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be						
submitted and approved						
	prior to	MOCD 24 hrs o beginning erations		BLM'S APPROVAL OR A ACTION DOES NOT REI OPERATOR FROM OBTA AUTHORIZATION REQU ON FEDERAL AND INDL	JEVE THE LESSEE AND LINING ANY OTHER LIRED FOR OPERATIONS	

prior to begin operation					
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)					
Tammy Jones	Title	Operations/Regulatory Technician - Sr.			
Signature Tammy Inch	Date	2/13/2018			
THIS SPACE FOR FED	ERAL O	R STATE OFFICE USE			
Approved by Lilliam Tambekou		Title Petroleum Engineer Date 2/15/2018			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any false, fictitious or fraudulent statements or representations as to any matter within its just		wingly and willfully to make to any department or agency of the United States any			

(Instruction on page 2)



District 1

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 248404

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-20483	2. Pool Code , 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318710	5. Property Name SAN JUAN 28 6 UNIT	6. Well No. 167
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6465

10. Surface Location

1	UL - Lot	Section	Township	Range	Lot idn	Feet From	N/S Line	Feet From	E/W Line	County
ı	K	4	27N	06W		1750	8	1500	VV	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 321.00 W/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to did this well at this location pursuant to a contract with an owner of such a mineral or working				
	Interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.				
	E-Signed By: Tammy Jones				
	Title: Operations/Regulatory Technician - Sr.				
	Date: 2/13/2018				
2	SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual				
	surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.				
	Surveyed By: DAVID KILVEN				
	Date of Survey: 3/9/1972				
	Certificate Number: 1760				



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 167 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,650'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 5,875' to isolate the Dakota. Note: TOC at 2,920' by CBL.
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Mesa Verde in two or three stages (Top Perforation @ 4,700'; Bottom Perforation @ 6,600').
- 7. Isolate frac stages with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top Isolation plug and Mesa Verde frac plugs.
- 10. Clean out to Dakota isolation plug and, when water and sand rates are acceptable, flow test the Mesa Verde.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 7,663'. TOOH.
- 12. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 167 MESA VERDE RECOMPLETION SUNDRY

