Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

	NMSF079363					
SUNDRY NOTICES AND REPOR		6. If Indian, Allottee or Tribe Na	ame			
Do not use this form for proposals to abandoned well. Use Form 3160-3 (API						
SUBMIT IN TRIPLICATE - Other instruc	7. If Unit of CA/Agreement, Name and/or No.					
1. Type of Well	ctions on page 2.	San Juan 28-6 Unit				
Oil Well X Gas Well Other		8. Well Name and No.				
			28-6 Unit 158E			
Name of Operator Hilcorp Energy Company	V	9. API Well No. 30-039-30020				
	Phone No. (include area code)	10. Field and Pool or Explorator				
PO Box 4700, Farmington, NM 87499	505-599-3400	Blanco Mesaverde/Basin Dakota				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit H (SENE) 1445'FNL & 940' FEL,	Sec. 11, T27N, R06W	11. Country or Parish, State Rio Arriba ,	New Mexico			
12. CHECK THE APPROPRIATE BOX(ES) TO	O INDICATE NATURE OF NO	TICE, REPORT OR OTHER	R DATA			
TYPE OF SUBMISSION	TYPE OF AC	TION				
X Notice of Intent Acidize	Deepen I	Production (Start/Resume)	Water Shut-Off			
Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report Casing Repair		Recomplete	Other			
Change Plans		Cemporarily Abandon				
Final Abandonment Notike Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details		Water Disposal				
Attach the bond under which the work will be performed or provide the Bor following completion of the involved operations. If the operation results in Testing has been completed. Final Abandonment Notices must be filed only determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the se existing Dakota with the Mesaverde. Attached is the application will be submitted and approved before the second secon	a multiple completion or recompletion y after all requirements, including recubject well in the Mesavere MV C102, recomplete pr	n in a new interval, a Form 3160- lamation, have been completed an	4 must be filed once d the operator has			
OIL CONS. DIV DIST. 3			RECEIVED			
FEB 1 2 2018	BLM'S APPROVAL OR ACCEP ACTION DOES NOT RELIEVE OPERATOR FROM OBTAININ AUTHORIZATION REQUIRES ON FEDERAL AND INDIAN L	THE LESSEE AND NG ANY OTHER D FOR OPERATIONS	FEB 0 6 2013			
			rmington Field Office au of Land Management			
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)						
Etta Trujillo	Title Operations/R	Title Operations/Regulatory Technician - Sr.				
Signature Photogram Signature	Date	1/31/2018				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by **Conditions of approval, if any, are attached. Approval of this notice does not war.	Title Fert	roleum Engineer	Date 2/9/2018			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equitable title to those rights in the subject lease which would

Office

Form C-102 August 1, 2011

Permit 246329

<u>District I</u>

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

<u>District II</u>

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-30020	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318710	5. Property Name SAN JUAN 28 6 UNIT	6. Well No. 158E
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6588

10. Surface Location

										_
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	1
н	11	27N	06W		1445	N	. 940	E	RIO ARRIBA	Ì

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 13. Joint of 320.00 E/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

0.7.1.07.1.0 0.111.					
	OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working Interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Etta Trujillo Title: Operations / Regulatory Technician Date: 1/31/2018				
	SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. Surveyed By: David R. Russell				
	Date of Survey: 6/15/2006				
	Certificate Number: 10201				



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 158E MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,687'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 6,000' to isolate the Dakota. Note: TOC at 2,590' by CBL.
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Mesa Verde in two or three stages (Top Perforation @ 4,750'; Bottom Perforation @ 5,650').
- 7. Isolate frac stages with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TiH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 10. Clean out to Dakota isolation plug and, when water and sand rates are acceptable, flow test the Mesa Verde.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 7,798*. TOOH.
- 12. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 158E MESA VERDE RECOMPLETION SUNDRY

