Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No. NO-G-1403-1908

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use Form 3160-3 (APD) for such proposals.	

CUMPRY NOTICES AND DEPORTS ON WELLS

6. If Indian, Allottee or Tribe Name

abandoned well	l. Use Form 3160	0-3 (APD) for such p	roposals.	0. 11 11111111, 121	Total or Tribe Traine		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well				W LYBROO	K UNIT / NMNM135216A		
Oil Well Gas Well Other					8. Well Name and No. W Lybrook Unit 711H		
2. Name of Operator APR 1 0 2017				9. API Well No.			
WPX Energy Production, LLC					09		
3a. Address	3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area				
PO Box 640 Aztec, N	IM 87410	505-333-1808		LYBROOK N	MANCOS W		
4. Location of Well (Footage, Sec., T.,R,M., or Survey Description) SHL: 1205' FSL & 1327' FWL, Sec 8, T23N, R8W BHL: 1004' FSL & 803' FWL, Sec 6 T23N, R8W				11. Country or Parish, State SAN JUAN COUNTY, NEW MEXICO			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION			TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Sta	art/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete		Other Equipment Placement		
	Change Plans	Plug and Abandon	Temporarily A	bandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	ı	į		
Describe Proposed or Comp							
duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths							
of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required							

subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)


WPX Energy Production, LLC is requesting to set permanent facilities on the W Lybrook Unit 703H, 704H, 711H, 713H, 743H, and 744H well pad. Permanent facilities on location would consist of two gas lift skids and cathodic protection equipment. A site visit was conducted on March 27, 2017 with Randy McKee to discuss facility layout and placement. Facilities on location would consist of two gas lift skids and cathodic protection equipment. Concurrently, WPX and BLM decided these facilities would be located on the south side of the access road. Please see the attached well pad diagram.

Farmington Field Office Bureau of Land Management 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Marie Jaramillo Permit Technician III Signature Date 03/31/2017 SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject Office lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



WPX Energy Production, LLC W Lybrook Unit 703H, 704H, 711H, 713H, 743H & 744H Well Pad Diagram Section 8, T23N, R8W, NMPM San Juan County, New Mexico



where the parties and the

o maria

W Lybrook UT 703H 1,212' FSL & 1,366' FWL API # 30-045-35727

W Lybrook UT 704H 1,199' FSL & 1,287' FWL API # 30-045-35728 W Lybrook UT 711H 1,205' FSL & 1,327' FWL API # 30-045-35809

W Lybrook UT 713H 1,215' FSL & 1,386' FWL API # 30-045-35808

- 1) Long Term Disturbance = 0.31 Acres
 - a. Facilities = 0.00* Acres
 - b. Access Road (AR) = 0.31 Acres
- 2) Reseed Area Only= 0.96 Acres
 - a. Working Area (WA) = .96 Acres (excluding Access Road)
 - b. Teardrop Area (contained within WA) = 0.00 Acres
- 3) Reseed & Recontoure Area = 4.26 Acres

Total Disturbance Area = 5.53 Acres

*Production facilities for the W Lybrook UT 703H, 704H, 711H, 713H, 743H & 744H are remotely located on WLU Remote #1.



NORTH

90'-0"

1" = 90'

W Lybrook Unit NMNM-135216X

W Lybrook UT 743H 1,209' FSL & 1,346' FWL API # 30-045-35729

W Lybrook UT 744H 1,202' FSL & 1,307' FWL API # 30-045-35730