6	~ <u>*</u>							
	Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.		
					NMSF079073			
	abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
	SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. 892000929C		
	1. Type of Well ☐ Oil Well					8. Well Name and No. NEBU 12M		
	2. Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION COMPA® Mail: Toya.Colvin@bp.com				9. API Well No. 30-045-31290-00-C1			
	3a. Address 501 WESTLAKE PARK BLVD. THREE ELDRIGE PLACE: 281.892.5369 HOUSTON, TX 77079					10. Field and Pool or Exploratory Area BASIN DAKOTA BLANCO MESAVERDE		
	4. Location of Well <i>(Footage, Sec., T.</i>		11. County or Parish, State					
	Sec 18 T30N R7W NESW 263 36.812583 N Lat, 107.613064	SAN JUAN COUNTY, NM						
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT,						IER DATA	
	TYPE OF SUBMISSION	JBMISSION TYPE OF ACTION						
24	🛛 Notice of Intent	□ Acidize	the product of the second s	Deepen		ion (Start/Resume)	□ Water Shut-Off	
1	Subsequent Report	 Alter Casing Casing Repair 		Hydraulic Fracturing New Construction		lete	 Well Integrity Other 	
	Final Abandonment Notice				Temporarily Abandon Sub		Subsurface Comming	
	Convert to Injection		Plug Back		□ Water Disposal		ng	
	13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.							
8	BP requests to downhole commingle the existing Basin Dakota and Blanco Mesaverde formations in the subject well, under previously approved NMOCD Order DHC 1551.							
	Please see the attached procedure including wellbore diagrams and C-102 plats.							
	NMOCD							
						FEB 2 6 2018		
	DISTRICT III							
	14. I hereby certify that the foregoing is true and correct. Electronic Submission #403361 verified by the BLM Well Information System For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by WILLIAM TAMBEKOU on 02/21/2018 (18WMT0541SE) Name (Printed/Typed) TOYA COLVIN Title REGULATORY ANALYST							
	Circuture (Electoric C	(Electronic Submission)						
	Signature (Electronic Submission) Date 02/05/2018 THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
	_Approved_By_WILLIAM_TAMBEKOU					ER	Date 02/21/2018	
	Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	Office Farmington						
	Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
	(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED *	* BLM RF	VISED ** BI M	REVISED	** BLM REVISE	D **	

NMOCDA

Northeast Blanco Unit 12M

API # 30-045-31290

-

Location: Unit K - Sec 18 - T30N - R07W

San Juan, New Mexico

Reason/Background for Job

The NEBU 12M was drilled and competed on 2003 in the Dakota and the Mesa Verde. In order to optimize production in the well, it is proposed to unset the packer, pull tubing, cleanout to PBTD if needed and run tubing allowing the DK and MV to be bottom hole commingled. We know this will allow us to increase the production of the MV formation through the use of artificial lift technique of plunger lifting.

.

Basic Job Procedure:


- 1. Unset Packer
- 2. Pull Tubing
- 3. Clean Out to PBTD (if needed)

٠

- 4. Run Tubing without packer
- 5. Install bottom hole bumper spring and plunger
- 6. Return Well to production

Proposed


1 4



History 12/22/2003 Spudded well.

Current:

* * * ==



History 12/22/2003 Spudded well.