Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR VED BUREAU OF LAND MANAGEMENT

FORM A	PPRO	VED
OMB No.	1004	-0137
Evnires: In	ly 31	2010

5. Lease Serial No.

B. 1	B # /	\sim \sim	07	04	-	~

			14	10101013132			
Do not us	NDRY NOTICES AND REF se this form for proposals d well. Use Form 3160-3 (to drill or to re-enter an		Name			
	UBMIT IN TRIPLICATE - Other in	vad or Land wanagemen	7. If Unit of CA/Agreement,	Name and/or No.			
1. Type of Well				San Juan 28-6 Unit			
	X Gas Well Other		8. Well Name and No.	8. Well Name and No.			
			San Ju	San Juan 28-6 Unit 126			
2. Name of Operator			9. API Well No.				
	Hilcorp Energy Comp			039-20065			
3a. Address		3b. Phone No. (include area cod	,				
PO Box 4700, Farming	ton, NM 87499	505-599-3400	Blanco Mes	averde/Basin Dakota			
4. Location of Well (Footage, Sec., T., Surface Unit N (R.,M., or Survey Description) SESW) 800'FSL & 1770'FV	VL, Sec. 16, T28N, R06W	11. Country or Parish, State Rio Arriba	, New Mexico			
12. CHECK	THE APPROPRIATE BOX(ES) TO INDICATE NATURE O	F NOTICE, REPORT OR OTH	IER DATA			
TYPE OF SUBMISSION		TYPE O	F ACTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off			
_	Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	X Recomplete	Other			
_	Change Plans	Plug and Abandon	Temporarily Abandon				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal				
13. Describe Proposed or Completed C	peration: Clearly state all pertinent de	etails, including estimated starting of	late of any proposed work and approx	imate duration thereof.			
1 1	ionally or recomplete horizontally, giv						
	work will be performed or provide the			And the second s			
0 1	ved operations. If the operation result al Abandonment Notices must be filed		•				
determined that the site is ready for		omy and an requirements, includ	ing reciamation, have been completed	and the operator has			
Hilaam Enames Campa	my plane to recomplete th	a aubicat wall in the Ma	avorda formation and da	umbala aamminala tha			

Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle the existing Dakota with the Mesaverde. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved before the work proceeds.



BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)		
Etta Trujillo	Title	Operations/Regulatory Technician - Sr.
Signature She Tay	Date	2-16-18
THIS SPACE FOR FEDE	ERAL O	DR STATE OFFICE USE
Approved by Lilliam Tambekon		Title Terroleum Engineer Date 2/21/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant or	certify	
that the applicant holds legal or equitable title to those rights in the subject lease which	would	Office FFD
entitle the applicant to conduct operations thereon.		110
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any	person kno	owingly and willfully to make to any department or agency of the United States any

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410

Phone: (505) 334-6178 Fax: (505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 248663

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-20065	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318710	5. Property Name SAN JUAN 28 6 UNIT	6. Well No. 126
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6554


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
N	16	28N	06W	İ	800	S	1770	w	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot idn	Feet From	N/S Line	Feet From	E/W Line	County
	12. Dedicated Acres 320.00 W/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working Interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations/Regulatory Tech Sr

Date: 02/16/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

David Kilven

Date of Survey:

4/3/1967

Certificate Number:

1760



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 126 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,624'.
- 3. RU Wireline. Run CBL. Record Top of Cement. (Note: TOC at 3,260' by Temperature Log).
- 4. Set a 4-1/2" cast iron bridge plug at +/- 5,850' to isolate the Dakota.
- 5. Load the hole and pressure test the casing to frac pressure.
- 6. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 7. Perforate and frac the Mesa Verde in two or three stages (Top Perforation @ 4,900'; Bottom Perforation @ 5,710').
- 8. Isolate frac stages with a composite bridge plug.
- 9. Nipple down frac stack, nipple up BOP and test.
- 10. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 11. Clean out to Dakota isolation plug and, when water and sand rates are acceptable, flow test the Mesa Verde.
- 12. Drill out Dakota isolation plug and cleanout to PBTD of 7,889'. TOOH.
- 13. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 126 MESA VERDE RECOMPLETION SUNDRY

