	NMOCD
Submit One Copy To Appropriate District State of New Mexico	Form C-103
District I Energy, Winerars and Natural Resources	R 0 5 2018 Revised August 1, 2011 WELL API NO. August 1, 2011 August 1, 2011 August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Grand Ave., Artesia, NM OIL CONSERVATION DIVISION	RICT 111 30-045-12005
811 S. First St., Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE X FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Mangum B Com
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 1
2. Name of Operator DAVID H. ARRINGTON OIL AND GAS,	9. OGRID Number 5898
3. Address of Operator P.O. BOX 2071 MIDLAND, TX 79702	10. Pool name or Wildcat
	Basin Dakota
4. Well Location Unit Letter P : 890 feet from the S line and 990 feet from the E	line
Section 32 Township 29N Range 11W NMPM County Sa	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
5425	ata
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da	ata
NOTICE OF INTENTION TO: SUBS PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	LING OPNS. P AND A
OTHER:	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Oper	ator's pit permit and closure plan.
	ator's pit permit and closure plan. properly abandoned.
All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the <u>ARTER/OUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u>
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has bother production equipment. 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR IN HAS BEEN WELDED OR
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pixed A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has bother production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR IN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pixed A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has bother production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production is produced by the operator's pit permit and closure plan. 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR IN HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has b other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has b other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has b other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR we cleared of all junk, trash, flow lines and have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has b other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR we cleared of all junk, trash, flow lines and have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has b other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed red. (Poured onsite concrete bases do not have All fluids have been removed from non-
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has be other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed red. (Poured onsite concrete bases do not have All fluids have been removed from non-
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has be other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produ- from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. When all work bas been completed, return this form to the appropriate District office to sche SIGNATURE TYPE OR PRINT NAME DEBBIE WHITING E-MAIL: DEBBIE.WHITING 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have All fluids have been removed from non- edule an inspection.
 All pits have been remediated in compliance with OCD rules and the terms of the Oper Rat hole and cellar have been filled and leveled. Cathodic protection holes have been filed A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has be other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below groun If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sche SIGNATURE Additional production of the DEBBIE WHITING E-MAIL: DEBBIE.WHITING 	ator's pit permit and closure plan. properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR IN HAS BEEN WELDED OR where the end of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have All fluids have been removed from non- edule an inspection. DATE 04/02/2018