RECEIVED

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR MAY 0 8 2011

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT Expires: July 31, 2010 5. Lease Serial No. NMSF-078281 SUNDRY NOTICES AND REPORTS ON WELLS and Manag 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well 8. Well Name and No. Other San Juan 29-5 Unit 25B 2. Name of Operator 9. API Well No. 30-039-29450 Hilcorp Energy Company 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 505-599-3400 Gobenador PC/Blanco Mesaverde 11. Country or Parish, State 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit H (SENE) 2100'FNL & 100' FEL, Sec. 18, T29N, R05W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity X Subsequent Report New Construction X Recomplete Other Casing Repair Change Plans Plug and Abandon Temporarily Abandon Water Disposal Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) See attached. ACCEPTED FOR RECORD MMOCD MAY 1 4 2018 DISTRICT III 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Etta Trujillo Operations/Regulatory Technician - Sr. Title 5-8-18 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Title

Office

Date

4/06/2018 – MIRU. ND WH. NU BOP & PT, test good. Pull tbg hanger. TOOH w/2-3/8" tbg. TIH w/3-7/8" casing scraper. TIH to 3800'. LD 58jts TOOH & LD csg scraper. SDFW.

4/07/2018 – TTL. CK press. Blow well down. INT csg continued blowing. TIH w/4 -1/2" CIBP, set @ 3650'. Load csg w/water & press test csg to 2000#, 30min. Test good. TOOH & LD setting tool. ND BOPE, NU Frac stack w/BOP on top. Attempt to load INT csg w/pkr fluid. Press up to 500#, bled to 0 psi in 2 secs. Attempt 10x w/same results. Attempt to pump pkr fluid down BH. BH has cmt to surface. SIW. SDFWE.

4/09/2018 – TTL. CK press. Get gas sample & blow well down. INT csg continued blowing. RU WL & Run CBL from 3650' to surf. TOC @ 3000' w/stringer @2990'. Notified William Tambekou (BLM) and Charlie Perrin (OCD) – Request permission to sqz holes in 4-1/2" csg. Verbal approval received. RU WL w/11/16" tbg gun to perf only 4-1/2" csg. RIH & perf 2 holes @ 2880'. RU pump & establish circ. Circ hole clean. RD WL. SIW. SDFN.

4/10/2018 – TTL. CK press. PU 4-1/2" cmt ret, TIH & set @ 2828'. Circ clean. Load 4-1/2" csg & press up to 500#. Pump cmt sqz f/2880' to surf, leaving 52' below cmt ret. Sting out & leave 50' on top. Pumped 406sx Class G cmt @ 15.8 ppg. TOOH & LD setting tool. SIW. SDFN.

4/11/2018 – TTL. CK press. TIH & tag TOC @ 2641'. DO cmt & cmt ret, fell through @ 2890'. Circ csg clean & PT to 530# 15min, test good. RD pwr swivel. RU tbg equip. SIW. SDFN.

4/12/2018 – TTL. CK press. TIH & tag CIBP. TOOH. RU well check w/1000# chart recorder. Run MIT @ 580# 30min. passed. Witnessed by John Durham w/NMOCD. Press up to 2000# 10min. held. 3000# 10min. held. 5000# 30min, held. RD test unit. RU WL. RIH & perf 68 holes @ f/3466' – 3499', .34 dia, 2 SPF. RD WL. SIW. SDFN.

4/13/2018 - TTL. CK press. TIH & tag CIBP @ 3650'. RU air package & blow well dry. RD air package. LD all tbg. ND BOP. NU Frac Y. RD. Rig release.

4/25/2018 – Foam frac Pictured Cliffs w/149,940# 20/40 & 28,703gal 20# linear gel & 1.03 million SCF N2 70Q. RD. RU flowback crew.

4/26/2018 – RU. ND Frac Y, NU BOP on frac valve. Chart test BOP good. BD well to 100#. Kill w/20bbls & monitor. Well came around 28mins. Kill well w/40bbls. TIH w/3-3/4" bit to 2800'. Tally. Open well to flowback. SDFN.

4/27/2018 – TTL. TIH & tag fill @ 3575'. 75' of fill. CIBP @ 3650'. CO. DO CIBP. TIH & tag MV @ 5994'. CO to PBTD & 6001' til clean. TOOH w/bit. Open well to flowback. SDFN.

4/28/2018 – TTL. TIH w/pro BHA/Drift. Tag PBTD @ 6001'. No fill. Test tbg to 500#. Good test. Pump off check @ 1000#. PU & land 2-3/8" tbg @ 5752', 181jts. SN @ 5750', 4.70#, J-55. RD. ND BOP stack/frac valve. NU B-2. RD. Rig release.

Well is now producing as Pictured Cliffs/Mesaverde commingle under DHC 3982AZ

