Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

AV 2 2 2005. Lease Serial No.

SUNDRY NOT	TICES AND	REPORTS	ON WELLS

NM-03188

	DRY NOTICES AND REPO		o. If Indian, Afforce of Tribe Name			
Do not use	this form for proposals	to drill or to re-enter an	ald Office			
abandoned	well. Use Form 3160-3 (A	(PD) for such proposals	fanagament			
	IBMIT IN TRIPLICATE - Other ins	Duittud of Lufter it	7. If Unit of CA/Agreement, Na	ame and/or No.		
1. Type of Well	Dim in in in zioniz	radione on page 2.	- I om or or or grounding the			
Oil Well	Gas Well Other		8. Well Name and No.			
				n 29-5 Unit 22C		
2. Name of Operator			9. API Well No.			
	Hilcorp Energy Compa	any	30-0	39-29464		
3a. Address		3b. Phone No. (include area code)	Field and Pool or Explorato	ry Area		
382 Road 3100, Aztec, N	NM 87410	505-599-3400	Gobenador Po	C/Blanco Mesaverde		
4. Location of Well (Footage, Sec., T.,R	.,M., or Survey Description)		11. Country or Parish, State			
Surface Unit M (SWSW) 305'FSL & 220' FV	VL, Sec. 8, T29N, R05W	Rio Arriba	New Mexico		
	,					
12. CHECK T	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION		TYPE OF	ACTION			
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off		
_	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
Subsequent Report	Casing Repair	New Construction	X Recomplete	Other		
	Change Plans	Plug and Abandon	Temporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent deta	ails, including estimated starting dat	e of any proposed work and approxima	ate duration thereof.		
If the proposal is to deepen direction	nally or recomplete horizontally, give	subsurface locations and measured	and true vertical depths of all pertinen	t markers and zones.		
Attach the bond under which the w	ork will be performed or provide the	Bond No. on file with BLM/BIA. R	equired subsequent reports must be file	ed within 30 days		
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once						
-		only after all requirements, including	g reclamation, have been completed an	d the operator has		
determined that the site is ready for	final inspection.)					

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle the existing Mesaverde with the Pictured Cliffs. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved before the work proceeds. A closed loop system will be utilized.

NMOCD

MAY 3 0 2018

DISTRICT 111

SEE ATTACHED FOR CONDITIONS OF APPROVAL

(Instruction on page 2)

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	T				
Etta Trujillo	Title	Operations/Regulatory	Гесhnician - Sr.		
Signature THIS SPACE FOR FED	Date	5-22-18 DR STATE OFFICE USE		,	
Approved by William Tambekou		Title Petroleum	Engineer	Date	5/24/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant or that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	Office FFO				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any false, fictitious or fraudulent statements or representations as to any matter within its jur		wingly and willfully to make to any	department or agency	of the U	Inited States any

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210

Phone: (575) 748-1283 Fax: (575) 748-9720 **District III**1000 Rio Brazos Rd., Aztec, NM 87410

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 252310

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-29464	2. Pool Code 77440	3. Pool Name GOBERNADOR PICTURED CLIFFS (GAS)
4. Property Code	5. Property Name	6. Well No.
318837	SAN JUAN 29 5 UNIT	022C
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6516


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
M	8	29N	05W		305	S	220	w	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	12. Dedicated Acres 320.00 W/2		13. Joint or Infill		14. Consolidation Code			15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations/Regulatory Tech

Date: 5/11/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Jason C. Edwards

Date of Survey:

8/11/2004

Certificate Number:

15269




HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 22C PICTURED CLIFFS RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 5,647'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 4,050' to isolate the Mesa Verde.
- 4. RU Wireline. Run CBL. Record Top of Cement. Note; Current TOC at 3,950' by CBL.
- 5. Load the hole and pressure test the casing to frac pressure.
- 6. Perforate squeeze holes in the 4-1/2" production casing @ 3,784'.
- 7. Pump and circulate cement to surface.
- 8. Clean out any excess cement to cast iron bridge plug @ 4,050'.
- 9. RU Wireline. Run CBL. Record Top of Cement.
- 10. Load the hole and MIT the casing to 660 psi.
- 11. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 12. Perforate and frac the Pictured Cliffs in a single stage (Top Perforation @ 3,461'; Bottom Perforation @ 3,531').
- 13. Isolate frac stage with a composite bridge plug.
- 14. Nipple down frac stack, nipple up BOP and test.
- 15. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 16. Clean out to Mesa Verde isolation plug and, when water and sand rates are acceptable, flow test the Pictured Cliffs.
- 17. Drill out Mesa Verde isolation plug and cleanout to PBTD of 6,008'. TOOH.
- 18. TIH and land production tubing. Get a commingled Mesa Verde/Pictured Cliffs flow rate.



HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 22C PICTURED CLIFFS RECOMPLETION SUNDRY





United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



CASING REPAIR, WORKOVER, AND RECOMPLETION CONDITION OF APPROVAL

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. If a CBL or other logs are run, provide this office with a copy.
- 3. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minutes test period. Provide test chart with your subsequent report of operations
- 4. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 5. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.