Submit 1 Copy To Appropriate District	State of New Mexico Form					
Office District I – (575) 393-6161 Energ	gy, Minerals and Natural Resources	Revised July 18, 2013				
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.				
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	CONSERVATION DIVISION	30-045-33814 5. Indicate Type of Lease				
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	STATE FEE				
* 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM		FEE				
87505 SUNDRY NOTICES AND	REPORTS ON WELLS	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DR		7. Dease Name of Cliff Agreement Name				
DIFFERENT RESERVOIR. USE "APPLICATION FOR	PERMIT" (FORM C-101) FOR SUCH	CULPEPPER MARTIN				
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	Other	8. Well Number				
		14E				
2. Name of Operator		9. OGRID Number				
HILCORP ENERGY COMPANY 3. Address of Operator		372171 10. Pool name or Wildcat				
382 Road 3100, Aztec, NM 87410		Basin Dakota/BmGP				
4. Well Location		Bushi Bukota 10.1 City				
	from the South line and 1035	feet from the East line				
1	32N Range 12W tion (Show whether DR, RKB, RT, GR, etc.	NMPM San Juan County				
11. Eleva	5937'					
	5757					
12 Check Appropria	te Box to Indicate Nature of Notice,	Report or Other Data				
12. Спеск Арргорпа	te Box to indicate Nature of Notice,	Report of Other Data				
NOTICE OF INTENTIO	N TO: SUB	SEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AN	ND ABANDON REMEDIAL WOR					
TEMPORARILY ABANDON CHANGE						
	E COMPL CASING/CEMEN	T JOB				
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	TESTING OTHER:	П				
		d give pertinent dates, including estimated date				
	RULE 19.15.7.14 NMAC. For Multiple Con					
proposed completion or recompletion.						
		e Mancos and downhole commingle with the				
	be produced, it will be temporarily monitor	commingling. A closed loop system will be				
used.	pheation will be fried and approved prior to	comminging. A closed loop system will be				
Kth. OHC must be in	place prior to the CIBP bei	NMOCD				
A INE NIIC IIII						
removed above the Nako	Notify NMOCD 24 hrs	MAY 2 4 2018				
	prior to beginning					
	operations	DISTRICT III				
		-				
Spud Date:	Rig Release Date:					
		,				
I hereby certify that the information above is tru	e and complete to the best of my knowledg	e and belief.				
1/ 5						
Stua Ma Shot						
SIGNATURE TUSHING SIGNATURE	TITLE Operations / Regulatory To	echnician DATE 05/24/2018				
Type or print name Priscilla Shorty	E-mail address:pshorty@hilcor	p.com PHONE: 505-324-5188				
For State Use Only	L-man addresspsnorty(w,micor	7.00H 1110NE. 505-324-3100				
0////						
		1 :0				
APPROVED BY: 7560	TITLE_	DATE 5-31-18				
APPROVED BY: 75000000000000000000000000000000000000	TITLE	DATE 5-31-18				

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 252724

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-045-33814	2. Pool Code 97232	3. Pool Name BASIN MANCOS					
4. Property Code 318880	5. Property Name CULPEPPER MARTIN	6. Well No. 014E					
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 5937					

10. Surface Location

UL - Lot	Section		Township	Range		Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
F	0	32	32	V	12W		1155	S	1035	E		SAN JUAN

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 320.00			13. Joint or Infill 14. Consolidation Code 15.				15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OTANDARD ONT IN	AS BEEN AFFROVED BY THE DIVISION
	OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and contained and belief, and that this organization either owns a work mineral interest in the land including the proposed bottom hole lost this well at this location pursuant to a contract with an owner of suinterest, or to a voluntary pooling agreement or a compulsory pool by the division. E-Signed By: Title: Operations Regulatory Technician Date: 05/22/2018
	SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotte surveys made by me or under my supervision, and that the same of my belief. Surveyed By: Glen Russell Date of Survey: 6/1/2006

true and complete to the best of my owns a working interest or unleased tom hole location(s) or has a right to drill owner of such a mineral or working pulsory pooling order heretofore entered

FICATION

t was plotted from field notes of actual at the same is true and correct to the best

Certificate Number:

15703



HILCORP ENERGY COMPANY CULPEPPER MARTIN 14E MANCOS DFIT PROCEDURE

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 6,945'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 6,368' to isolate the Dakota.
- 4. Load the hole with KCL fluid and pressure test to DFIT pressure. Note: TOC at 3,680' by CBL.
- 5. RU EL & RIH & perforate the Mancos (5,606'-6,303')
- 6. RIH w/ RBP and pressure gauge & hold in unset position above Mancos Perforation
- 7. RU pump truck and perform DFIT on Mancos (pump into Mancos with KCI fluid at approximately 4-6 bpm up to approximately 40 bbls)
- 8. Shut down pump truck
- 9. Set RBP and pressure gauge above Mancos Perforation.
- 10. Leave well SI and monitor pressure. RDMO Pump truck & EL
- 11. Monitor pressures for extended period of time.
- 12. Return to well to retrieve RBPs, gauges and return well to DK production.



HILCORP ENERGY COMPANY CULPEPPER MARTIN 14E MANCOS DFIT PROCEDURE

