Form	3160-5
(Inne	2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM APPROVED
	OMB NO. 1004-0137
•	Expires: January 31, 20

i	5.	Lease Serial	ľ
	l	NMSF080	7

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals.	

abandoned well. Use form 3160-3 (APD) for such proposals.				EASTERN NAVAJO				
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. 892000844L				
Type of Well Gas Well					8. Well Name and No. GALLEGOS CANYON UNIT 381			
2. Name of Operator	Contact: TO	YA COLVI	N		9. API Well No.			
BP AMERICA PRODUCTION				· · · · · ·	30-045-27588-00-S1			
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401 3b. Phone No Ph: 281.36					10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State			
Sec 20 T29N R12W SENE 1650FNL 0985FEL 36.714750 N Lat, 108.116060 W Lon					SAN JUAN COUNTY, NM			
12. CHECK THE AF	PROPRIATE BOX(ES) TO	INDICAT	TE NATURE OF	NOTICE,	REPORT, OR OTH	ER DA	TA	
TYPE OF SUBMISSION	·		TYPE OF	ACTION				
Notice of Intent	☐ Acidize	☐ Deep	en	☐ Product	ion (Start/Resume)	□ Wa	ter Shut-Off	
_	☐ Alter Casing	☐ Hydi	aulic Fracturing	□ Reclam	ation	□ We	ll Integrity	
☐ Subsequent Report	Casing Repair	□ New	Construction	□ Recomp	olete	☐ Oth	ner	
☐ Final Abandonment Notice	☐ Change Plans	🔀 Plug	and Abandon	□ Tempor	arily Abandon			
<i>BP</i>	Convert to Injection	☐ Plug	Back	☐ Water I	Disposal			
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BP requests to P&A the subject well. Please see the attached P&A procedure and wellbore documents. In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during operations. *Please note this well is private surface and does not require reclamation plans. Notify NMOCD 24 hrs prior to beginning operations. Notify NMOCD 24 hrs prior to beginning operations.								
	Electronic Submission #4130 For BP AMERICA PR mmitted to AFMSS for process	RODUCTIQI	N CO, sent to the	Farmingtor	1			
Name (Printed/Typed) TOYA COLVIN Titl			Title REGULA	ATORY AN	ALYST			
Signature (Electronic S	ubmission)		Date 05/04/20)18	·			
	THIS SPACE FOR	FEDERA	L OR STATE (OFFICE U	SE			
Approved By JACK SAVAGE Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the second of the seco	itable title to those rights in the sub ct operations thereon.	ject lease	Office Farmingt	on			ate 06/04/2018	
States any false, fictitious or fraudulent s				winiuny w mi	and to any department of a	igency di	uic Office	

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

PLUG AND ABANDONMENT PROCEDURE

December 29, 2017

Gallegos Canyon Unit #381

Basin Fruitland Coal 1650' FNL and 985' FEL, Section 29, T29N, R12W San Juan County, New Mexico / API 30-045-27588

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. NE wellhead and NU BOP. Function test BOP.			
2.	Rods: Yes_X_, No, Unknown Tubing: Yes_X_, No, Unknown, Size2-3/8"_, Length1545'			

3.	Plug #1 (Pictured Cliffs top, Fruitland Coal perfs and Fruitland top, 1461' - 1110'): RIH and
	set 4.5" CR at 1461' (same ownership). Pressure test tubing to 1000#. Circulate well clean.
•	Pressure test casing to 800#. If casing does not test then spot or tag subsequent plugs as
	appropriate Mix 31 sys Class B cement inside casing from 1461' to cover the PC top through

Packer: Yes____, No _X__, Unknown____, Type _____

the Fruitland top. PUH.

- 4. Plug #2 (Kirtland, Ojo Alamo tops and 8.625" casing shoe, 366' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 30 sxs cement and spot a balanced plug from 366' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A
 marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.
 Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM
 stipulations

Gallegos Canyon Unit #381

Proposed P&A

Basin Fruitland Coal 1650' FNL, 985' FEL, Section 20, T-29-N, R-12-W San Juan County, NM, API #30-045-27588

Today's Date: 12/29/17 Spud: 4/9/90

Completed: 6/4/90 Elevation: 5614' GI

5622' KB

8.75" hole


Ojo Alamo @ 217'

Kirtland @ 316'

Fruitland @ 1160'

Pictured Cliffs @ 1540'

6.25" hole



Circulated cement to surface

7" 20# Casing set @ 134' Cement with 150 sxs, circulated

> Plug #2: 366' - 0' Class B cement, 30 sxs

> Plug #1: 1461' - 1110' Class B cement, 31 sxs

Set CR @ 1461'

Fruitland Coal Perforations: 1511' - 1534'

4.5",10.5#, Casing set @ 1675' Cement with 385 sxs, circulated to surface

TD 1700' PBTD 1637'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Gallegos Canyon Unit 381

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.