Form 3160-5 (June 2015)

UNITED STATES								
DEPARTMENT OF THE INTERIOR								
BUREAU OF LAND MANAGEMENT								

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 20

DI	UREAU OF LAND MANA	GEMENT		1	Expires: J	anuary .	31, 2018	
	5. Lease Serial No. NMNM24661							
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN T	TRIPLICATE - Other ins	tructions on	page 2		7. If Unit or CA/Agree	ement,	Name and/or No.	
1. Type of Well	8. Well Name and No. JULY JUBILEE 2							
		9. API Well No.						
DUGAN PRODUCTION COR			30-045-25123-00-S1					
3a. Address 709 E MURRAY DRIVE FARMINGTON, NM 87499	. (include area code) 5.1821	code) 10. Field and Pool or Exploratory Area UNDESIGNATED						
4. Location of Well (Footage, Sec., T	)		11. County or Parish, State					
Sec 29 T24N R9W NWNW 07 36.290054 N Lat, 107.818115				SAN JUAN COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTI	HER D	DATA	
TYPE OF SUBMISSION	TYPE OF	TYPE OF ACTION						
■ Notice of Intent	☐ Acidize	☐ Dee	oen	☐ Producti	on (Start/Resume)		Water Shut-Off	
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	tion		Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Construction		☐ Recomplete		☐ Other		
☐ Final Abandonment Notice	☐ Change Plans		and Abandon	☐ Tempora	Temporarily Abandon			
66	☐ Convert to Injection	Back	■ Water D	ter Disposal				
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for final Dugan Production Corp. plans  1) Tag CIBP @ 5052'. Load has 2) Spot Plug I above BP from 4760'-5052'  3) Spot Plug II inside 4-1/2" can Mancos, Plug II: 4213'-4313'. 4) Spot inside Plug III from 24 Plug III: 1960'-2440'.  5) Spot inside Plug IV from 17 Fruitland-PC 1350'-1708'.  6) Spot Plug V from 777' to 49	rk will be performed or provide operations. If the operation rebandonment Notices must be fill inal inspection.  Is to plug and abandon the sole. Pressure test casing 5052' to 4760' w/26 sks (asing from 4313'-4213' w/40' to 1960' w/42 sks (49.08' to 1350' w/28 sks (33.00' w/26 sks (31 cu ft) Cla	the Bond No. or sults in a multiple donly after all the well as per the growth of the following to 600 psi. If 31 cu ft) Class 12 sks (14.2 cu ft) Class cu ft) Class Euft) Class Euft) Class Euft) Class E	a file with BLM/BIA completion or recorrequirements, including processing a Bibliogram of the following processing processing a Bibliogram of the following processing processing a Bibliogram of the following processing	Required submpletion in a ning reclamation edure:  lup Plug I: ment - averde-Char	sequent reports must be ew interval, a Form 316, , have been completed: Notify NMOCD 2. prior to beginn operations.  Al	filed w for 4 must and the 4 hrs ing	of thin 30 days st be filed once	
14. I hereby certify that the foregoing is  Con Name (Printed/Typed) ALIPH RE	# Electronic Submission For DUGAN PRODU mmitted to AFMSS for prod	CTION CORP	RÁTION, sent to CK SAVAGE on 0	the Farming 8/14/2018 (18	ton	D.		
Maine (17 mew 19 peu) MLIPTI NE	LIVA		THE AGENT,	LINGINEER	MING SUPERVISOR	`		
Signature (Electronic S	Date 05/18/20	)18						
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	BE			
_Approved_By_JACK_SAVAGE			TitlePETROLE	UM ENGINE	ER		Date 08/14/2018	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Farmington					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



## Additional data for EC transaction #420534 that would not fit on the form


#### 32. Additional remarks, continued

490'-777'.
7) Spot inside Plug VI from 252' to surface w/23 sks (27 cu ft) Class B cement - Plug VI: Surface - 0'.

8) Cut wellhead. Tag TOC at surface. Fill cement in case needed.
9) Tag TOC behind 4-1/2" casing w/1" tubing. Fill up cement as needed.
10) Install dryhole marker. Clean location.

# Planned P & A Schematic

July Jubilee # 2 30-045-25123 S29 T24N R9W 790' FNL 790' FWL San Juan County, NM



85/8" J-55 24# casing @ 202'. Cemented with 135 sks Class B w/ 2% CaCl2. Circulated cement to surface.

Spot plug from 252' to surface w/23 sks Class B @ 0-252' (27 cu.ft) [Plug VI: Surface]

Inside plug w/ 26 sks Class B (31 cu.ft) @ 490'-777' [Plug V: Ojo Alamo-Kirtland]

Inside plug w/ 28 sks Class B @ 1350'-1708' (33 cu.ft) [Plug IV: PC-Fruitland]

Inside plug w/ 42 sks Class B @ 1960'-2440' (49.5 cu.ft) [Plug III: Chacra-Mesaverde]

Inside plug w/ 12 sks Class B @ 4213'-4313' (14.2 cu.ft)[ Plug II: Mancos]

Cemented w / 250 sks Class B w/ 4% gel followed by 150 sks Class B (557 Cu.ft). DV tool @ 4296'. 475 sks 65-35-12 followed by 100 sks Class B w/ 4% gel. (1396 cu.ft). Total slurry 1953 cu.ft.

Set CIBP @ 5052'. Inside plug w/ 26 sks Class B @ 4760'-5052' (31 cu.ft)[ Plug I: Gallup].


Gallup Perforated @ 5112'-5328', 38 holes

4 ½" 10.5, 116. # casing @ 6403'. PBTD @ 6002'

BP set @ 6052' to plug Dakota perforations. Dakota perfs @ 6102'-6108', 6260'-6270', 6287'-6297'. 26 holes.

# **Current Wellbore Schematic**

July Jubilee # 2 30-045-25123 S29 T24N R9W 790' FNL 790' FWL San Juan County, NM



 $8\,5/8"$  J-55 24# casing @ 202'. Cemented with 135 sks Class B w/ 2% CaCl2. Circulated cement to surface.

Cemented w / 250 sks Class B w/ 4% gel followed by 150 sks Class B (557 Cu.ft). DV tool @ 4296'. 475 sks 65-35-12 followed by 100 sks Class B w/ 4% gel. (1396 cu.ft). Total slurry 1953 cu.ft.

2-3/8" J-55 Tubing set @ 4982'

CIBP @ 5052'

Gallup Perforated @ 5112'-5328', 38 holes

4 1/2" 10.5, 116. # casing @ 6403'. PBTD @ 6002'

BP set @ 6052' to plug Dakota perforations. Dakota perfs @ 6102'-6108', 6260'-6270', 6287'-6297'. 26 holes.

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Jay Jubilee 2

## CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
  - a) Set Plug 5 (810 539) ft. to cover the Kirtland and Ojo Alamo tops. BLM picks top of Kirtland at 760 ft. BLM picks top of Ojo Alamo at 589 ft.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.