			AI XA	000	 * Second and a second se		
Form 3160-5	FS .	LA TAI	OCD	EODMA	PPPOVED		
(August 2007)				n 2	FORM APPROVED OMB No. 1004-0137		
	BUREAU OF LAND MAN	NAGEM	ENT			uly 31, 2010	
			DISTRI	CT	5. Lease Serial No.	NM03188	
SU	NDRY NOTICES AND REPO	ORTS O	N WELLS		6. If Indian, Allottee or Tribe N		
Do not use this form for proposals to drill o					0.0050		
	well. Use Form 3160-3 (A			Isij U	6 2013		
1. Type of Well	UBMIT IN TRIPLICATE - Other ins	tructions c	n page 2.		7. If Unit of CA/Agreement, Na	ame and/or No.	
Oil Well	X Gas Well Other				8. Well Name and No.		
			Bureau of Lar		San Juar	n 29-5 Unit 65F	
2. Name of Operator Hilcorp Energy Company					9. API Well No.	39-29554	
			No. (include area code) 10. Field and Po		10. Field and Pool or Explorato		
382 Road 3100, Aztec,	NM 87410		505-599-3400			/Blanco MV/Basin DK	
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			.,	11. Country or Parish, State	N	
Surface Unit D	(NWNW) 480'FNL & 15' FW	L, Sec.	28, T29N, R05W		Rio Arriba ,	New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDI	CATE NATURE (DF NO	TICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION			TYPE				
Notice of Intent	Acidize	Deen	Deepen Production (Start/Resume) Water Shut-Off				
	Alter Casing		ure Treat		Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New	Construction	XI	Recomplete	Other	
ent	Change Plans	Plug	and Abandon]	Femporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug			Water Disposal		
-	Operation: Clearly state all pertinent de tionally or recomplete horizontally, give						
	work will be performed or provide the						
	lved operations. If the operation results al Abandonment Notices must be filed						
determined that the site is ready t		only after a	n requirements, inclu	ung rec	namation, nave been completed a	nd the operator has	
6/20/18 MIRU. ND WH	. NU 5K frac valve & BOP. F	PT to 150	00#, test good. I	Pull tb	og hanger. TOOH w/2-3/	8" tbg. SDON.	
6/21/18 TIH w/3-3/4" bi	t & 4.5" csg scraper to 4000	'. ТООН	w/bit & csq scr	aper.	Kill well w/wtr & biocide.	. RU W/L. TIH w/4.5"	
CIBP set @ 3920'. RD \	N/L. TIH w/2-3/8" tbg, tag pl	ug @ 39	12' (WLD @ 39				
4.5" csg & CIBP to 2000)#/20 mins, test good. TOOF			0			
6/22/18 ND BOP NU t	est flange. PT 4.5" csg & CIE		OR RECOR		o BH or INT communic	ation. Kill well w/40 bbls	
	D test flange. NU BOP. Kill						
TOOH w/bit. TIH w/RBF	^o & pkr, set RBP @ 3880'. L	oad & ci	hole w/54 bbl	s wtr.	Set pkr @ 3870'. PT R	BP @ 3880' to 2000#/15	
mins, good test. Rls pkr release, TOOH, SDON,	& test 4.5" csg to 2025#/20	mins, te	st good, no BH	or IN	T communication. Latch	onto & equalize RBP &	
Telease, TOOTI, ODON.	By:	TIP	1		CONTINUED or	Page 2	
		4					
14. I hereby certify that the foregoing	is true and correct. Name (Printed Ty)	pea)					
Tammy Jones		V	Title Operat	tions/F	Regulatory Technician - S	Sr.	
Signature TAMMY	Janos		Date 😵 /	61	2018		
<i>[0\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	THIS SPACE FC		U/	FOF	FICE LISE		
Approved by							
Approved by							
			Tit	le		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or that the applicant holds legal or equitable title to those rights in the subject lease which w				fice			
entitle the applicant to conduct operat							
	e 43 U.S.C. Section 1212, make it a cri			l willful	ly to make to any department or a	agency of the United States any	
false, fictitious or fraudulent statemen (Instruction on page 2)	ts or representations as to any matter w	ithin its jur		-			
(monucion on page 2)			NMOCO	A.			



Page 2 CONTINUED....

San Juan 29-5 Unit 65F	30-039-29554	NMNM03188	

6/23/18 TIH w/retrieving tool, tag & latch onto RBP. TOOH w/RBP & retrieving tool. TIH w/3-7/8" mill to 3900'. Est circ w/air, tag solid @ 3912'. DO failed CIBP @ 3912'. Circ hole clean. TIH w/3-7/8" mill to 6035'. TOOH w/mill. TIH w/RBP & pkr, set RBP @ 5480' & pkr @ 5460'. PT RBP to 600#/15 mins, test good. RIs pkr & circ hole. PT 4.5" csg to 650#/15 mins, test good. Latch onto & rls RBP @ 5480'. TOOH w/RBP & pkr. SDON.

6/24/18 Kill well w/30 bbls wtr. TIH & set 4.5" CIBP @ 3850'. Circ hole w/75 bbls wtr treated w/biocide. PT CIBP & 4.5" csg to 2025#/20 mins, test good. TOOH. ND BOP. NU test flange. PT CIBP & 4.5" csg to 4000#/30 mins, test good. ND test flange. NU frac valve. SDON.

7/6/18 Load hole & PT csg & frac valve to 4000#/30 mins.

7/7/18 RU W/L. Perf Pictured Cliffs @ 3668-3732' (2 SPF) for a total of 130, 0.44" dia holes. RD W/L.

7/17/18 MIRU. ND frac valve. NU BOP & PT, test good. TIH w/tbg to 3740'. Pump 500 gals 15% HCL & displace w/11.5 bbls fresh wtr. TOOH w/tbg. NU pump truck, broke dwn formation @ 2640#, pumped 4.5 BPM @ 600#. RD pump truck. ND BOP. NU frac stack. RD. Rig released.

7/23/18 RU Frac crew. Broke down well with water & 500 gal 15% HCL. Foam FRAC'D Pictured Cliffs w/150,080# 20/40 sand & 35,198 gal slk wtr & 1.14 million SCF N2 70 quality. avg rate = 40 BPM, avg PSI = 2007. RD frac crew.

7/25/18 Flow back well.

7/26/18 MIRU. Pump 40 bbls wtr treated w/biocide dwn 4.5" csg. RU W/L. TIH & set isolation plug @ 3550'. Load csg & PT CBP @ 3550' to 1500#/15 mins, test good. RD W/L. ND frac stack. NU BOP & PT, test good. TIH w/3-7/8" junk mill to 3411'. SDON. SI well.

7/27/18 Tag CBP @ 3550'. Swivel up & est circ. D/O isolation plug @ 3550'. CO fill to 3842', PU to 3595'. Flow back well.

7/28/18 Est. circ. TIH tag fill & CO to CIBP @ 3850'. D/O CIBP @ 3850'. CO to 8026'. SDON.

7/29/18 CO to 8026'. TOOH w/3-7/8" junk mill. Kill well. TIH w/3-7/8" junk mill to 4894'. SDON.

7/30/18 Est. circ & tag fill @ 8007'. CO to 8078'. PUH to 6802'. SDON.

7/31/18 Tag fill @ 8068'. CO fill to 8096'. TOOH w/3-7/8" junk mill. SDON.

8/1/18 TIH w/BHA & tag @ 8074'. CO fill to 8116' w/air & mist. Circ well clean. Land 259 jts 2-3/8" 4.7# J-55 EUE T&C upset tubing @ 8019', SN @ 8017'. ND BOP. NU WH. RD. Rig released.

Well is now producing as Gobernador Pictured Cliffs/Blanco Mesaverde/Basin Dakota tri-mingle under DHC4836.